
ADDRESS . : 56 WEATHERBY CT
 CONTRACTOR : STEPHENSON RANDY T
 OWNER . . : STEPHENSON RANDY #13
 PARCEL . . : 07-0691- - -0023- -12-
 APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 E TO 27 TO COATS LEFT ON 55 GO APPRO
 X 3 MILES RIGHT ON SILAS HAYES HUNTERS P
 OINT ON RIGHT LOT 13 JB
 XXX
 PERMIT INCLUDES BLDG,ELEC,MECH,PLUMB
 INSULATION AND LAND USE.
 XXX
 Work must conform and comply with the
 STATE BUILDING CODE and all other State
 and local laws, ordinances & regulations

STRUCTURE: 000 000 75X42 3BDR
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/14/07 <u>5-14-07</u>	TI <u>APBS</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001408327

----- COMMENTS AND NOTES -----

ADDRESS : 56 WEATHERBY CT
CONTRACTOR : STEPHENSON RANDY T
OWNER : STEPHENSON RANDY #13
PARCEL : 07-0691- - -0023- -12-
APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)

SUBDIV: HUNTERS POINT 45 LOTS
PHONE : (919) 894-4436
PHONE : (919) 894-4436

DIRECTIONS : 421 E TO 27 TO COATS LEFT ON 55 GO APPRO
X 3 MILES RIGHT ON SILAS HAYES HUNTERS P
OINT ON RIGHT LOT 13 JB
XX
PERMIT INCLUDES BLDG,ELEC,MECH,PLUMB
INSULATION AND LAND USE.
XX
Work must conform and comply with the
STATE BUILDING CODE and all other State
and local laws, ordinances & regulations

STRUCTURE: 000 000 75X42 3BDR
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/14/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001408327
	5/14/07	AP	t poles must have seperate ground rods
B103 01	5/15/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001409580
	5/15/07	CA	SERVICE POLE INSPECTION.ELECTRICIAN HAD SEPARATE RODS BUT HAD THEM BONDED TOGETHER.HAS BEEN CHANGED. We do not do temp poles as a separate inspection. It will be done at the foundation inspection.
B103 03	<u>5/31/07</u> <u>5-31</u>	<u>TI</u> <u>RP</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418722 PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
B103 02	5/31/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418714
	5/30/07	CA	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763

COMMENTS AND NOTES

*Called Randy &
told him that
we don't schedule
the notes that he
does.*

ADDRESS : 56 WEATHERBY CT SUBDIV: HUNTERS POINT 45 LOTS
 CONTRACTOR : STEPHENSON RANDY T PHONE : (919) 894-4436
 OWNER : STEPHENSON RANDY #13 PHONE : (919) 894-4436
 PARCEL : 07-0691- - -0023- -12-
 APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 E TO 27 TO COATS LEFT ON 55 GO APPRO
 X 3 MILES RIGHT ON SILAS HAYES HUNTERS P
 OINT ON RIGHT LOT 13 JB
 XX
 PERMIT INCLUDES BLDG,ELEC,MECH,PLUMB
 INSULATION AND LAND USE.
 XX
 Work must conform and comply with the
 STATE BUILDING CODE and all other State
 and local laws, ordinances & regulations

STRUCTURE: 000 000 75X42 3BDR
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/14/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001408327
	5/14/07	AP	t poles must have seperate ground rods
B103 01	5/15/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001409580
	5/15/07	CA	SERVICE POLE INSPECTION.ELECTRICIAN HAD SEPARATE RODS BUT HAD THEM BONDED TOGETHER.HAS BEEN CHANGED. We do not do temp poles as a separate inspection. It will be done at the foundation inspection.
B103 03	5/31/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418722
	5/31/07	AP	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
B103 02	5/31/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418714
	5/30/07	CA	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
A814 01	6/05/07	TI	ADDRESS CONFIRMATION VRU #: 001422930
B105 01	<u>6/7/07</u>	<u>TI AP</u>	R*OPEN FLOOR VRU #: 001423011

COMMENTS AND NOTES

ADDRESS : 56 WEATHERBY CT SUBDIV: HUNTERS POINT 45 LOTS
 CONTRACTOR : STEPHENSON RANDY T PHONE : (919) 894-4436
 OWNER : STEPHENSON RANDY #13 PHONE : (919) 894-4436
 PARCEL : 07-0691- - -0023- -12-
 APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 E TO 27 TO COATS LEFT ON 55 GO APPRO
 X 3 MILES RIGHT ON SILAS HAYES HUNTERS P
 OINT ON RIGHT LOT 13 JB
 XXX
 PERMIT INCLUDES BLDG,ELEC,MECH,PLUMB
 INSULATION AND LAND USE.
 XXX
 Work must conform and comply with the
 STATE BUILDING CODE and all other State
 and local laws, ordinances & regulations

STRUCTURE: 000 000 75X42 3BDR
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/14/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001408327
	5/14/07	AP	t poles must have seperate ground rods
B103 01	5/15/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001409580
	5/15/07	CA	SERVICE POLE INSPECTION.ELECTRICIAN HAD SEPARATE RODS BUT HAD THEM BONDED TOGETHER.HAS BEEN CHANGED. We do not do temp poles as a separate inspection. It will be done at the foundation inspection.
B103 03	5/31/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418722
	5/31/07	AP	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
B103 02	5/31/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418714
	5/30/07	CA	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
A814 01	6/05/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001422930
	7/03/07	AP	55 WEATHERBY CT LOT 13 NOT 56
B105 01	6/07/07	KS	R*OPEN FLOOR VRU #: 001423011
	6/07/07	AP	
R425 01	7/12/07	TI	FOUR TRADE ROUGH IN VRU #: 001444710

PA-MR

COMMENTS AND NOTES

ADDRESS : 56 WEATHERBY CT
 CONTRACTOR : STEPHENSON RANDY T
 OWNER : STEPHENSON RANDY #13
 PARCEL : 07-0691- - -0023- -12-
 APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 E TO 27 TO COATS LEFT ON 55 GO APPRO
 X 3 MILES RIGHT ON SILAS HAYES HUNTERS P
 OINT ON RIGHT LOT 13 JB
 XXX
 PERMIT INCLUDES BLDG,ELEC,MECH,PLUMB
 INSULATION AND LAND USE.
 XXX
 Work must conform and comply with the
 STATE BUILDING CODE and all other State
 and local laws, ordinances & regulations

STRUCTURE: 000 000 75X42 3BDR
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/14/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001408327
	5/14/07	AP	t poles must have seperate ground rods
B103 01	5/15/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001409580
	5/15/07	CA	SERVICE POLE INSPECTION.ELECTRICIAN HAD SEPARATE RODS BUT HAD THEM BONDED TOGETHER.HAS BEEN CHANGED. We do not do temp poles as a separate inspection. It will be done at the foundation inspection.
B103 03	5/31/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418722
	5/31/07	AP	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
B103 02	5/31/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418714
	5/30/07	CA	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
A814 01	6/05/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001422930
	7/03/07	AP	55 WEATHERBY CT LOT 13 NOT 56
B105 01	6/07/07	KS	R*OPEN FLOOR VRU #: 001423011
	6/07/07	AP	
R425 01	7/12/07	MR	FOUR TRADE ROUGH IN VRU #: 001444710
	7/12/07	DA	1. toilet gflanges must be installed, screwed down and pressure tested 2. Will check on insul. inspect.
I129 01	7/16/07	MR	R*INSULATION INSPECTION VRU #: 001447002
	7/16/07	AP	
R425 02	7/16/07	MR	FOUR TRADE ROUGH IN VRU #: 001447028
	7/16/07	AP	
M405 01	7/17/07	TI	R*MECHANICAL UNDERGROUND VRU #: 001446992

2-17 CA)
 KS

ADDRESS . : 56 WEATHERBY CT
 CONTRACTOR : STEPHENSON RANDY T
 OWNER . . : STEPHENSON RANDY #13
 PARCEL . . : 07-0691- - -0023- -12-
 APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 E TO 27 TO COATS LEFT ON 55 GO APPRO
 X 3 MILES RIGHT ON SILAS HAYES HUNTERS P
 OINT ON RIGHT LOT 13 JB
 XXX
 PERMIT INCLUDES BLDG,ELEC,MECH,PLUMB
 INSULATION AND LAND USE.
 XXX
 Work must conform and comply with the
 STATE BUILDING CODE and all other State
 and local laws, ordinances & regulations

STRUCTURE: 000 000 75X42 3BDR
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/14/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001408327
	5/14/07	AP	t poles must have seperate ground rods
B103 01	5/15/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001409580
	5/15/07	CA	SERVICE POLE INSPECTION.ELECTRICIAN HAD SEPARATE RODS BUT HAD THEM BONDED TOGETHER.HAS BEEN CHANGED. We do not do temp poles as a separate inspection. It will be done at the foundation inspection.
B103 03	5/31/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418722
	5/31/07	AP	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
B103 02	5/31/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418714
	5/30/07	CA	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
A814 01	6/05/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001422930
	7/03/07	AP	55 WEATHERBY CT LOT 13 NOT 56
B105 01	6/07/07	KS	R*OPEN FLOOR VRU #: 001423011
	6/07/07	AP	
R425 01	7/12/07	MR	FOUR TRADE ROUGH IN VRU #: 001444710
	7/12/07	DA	1. toilet gflanges must be installed, screwed down and pressure tested 2. Will check on insul. inspect.
I129 01	7/16/07	TI	R*INSULATION INSPECTION VRU #: 001447002
		AP-MR	
R425 02	7/16/07	TI	FOUR TRADE ROUGH IN VRU #: 001447028
		AP-MR	

COMMENTS AND NOTES

HTE# 07-5-17001

Harnett County Department of Public Health 19503

PERMIT # 23770

Operation Permit

New Installation Septic Tank Repair Nitrification Line Expansion

PROPERTY LOCATION: SR 1565 Subdiv 14000 RD

Name: (owner) Randy Stephens

SUBDIVISION Hunters Point

LOT # 13

System Installer: John Thompson

Registration # _____

Basement with plumbing: Garage Number of Bedrooms 3


Type of Water Supply: Community Public Well Distance from well _____ feet

System Type: 25% REDUCED SYSTEM TYPE VI Types V and VI Systems expire in 5 years.

(In accordance with Table V a)

Owner must contact Health Department 6 months prior to expiration for permit renewal.

This system has been installed in compliance with applicable North Carolina General Statutes, Rules for Sewage Treatment and Disposal, and all conditions of the Improvement Permit and Construction Authorization.



PERMIT CONDITIONS:

- I. Performance: System shall perform in accordance with Rule .1961.
- II. Monitoring: As required by Rule .1961.
- III. Maintenance: As required by Rule .1961. Other: _____
Subsurface system operator required? Yes No
If yes, see attached sheet for additional operation conditions, maintenance and reporting.
- IV. Operation: _____
- V. Other: _____

Following are the specifications for the sewage disposal system on the above captioned property.

Type of system: Conventional Other 25% REDUCED SYSTEM Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons
 Subsurface Drainage Field: No. of ditches 2 exact length of each ditch 150 feet width of ditches 3 feet depth of ditches 28 inches
 French Drain Required: _____ Linear feet

Authorized State Agent James C. Martin for SR

Date 8-27-67

ADDRESS : 56 WEATHERBY CT
CONTRACTOR : STEPHENSON RANDY T
OWNER : STEPHENSON RANDY #13
PARCEL : 07-0691- - 0023- -12-
APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 421 E TO 27 TO COATS LEFT ON 55 GO APPRO
X 3 MILES RIGHT ON SILAS HAYES HUNTERS P
OINT ON RIGHT LOT 13 JB
XX
PERMIT INCLUDES BLDG, ELEC, MECH, PLUMB
INSULATION AND LAND USE.
XX
Work must conform and comply with the
STATE BUILDING CODE and all other State
and local laws, ordinances & regulations

SUBDIV: HUNTERS POINT 45 LOTS
PHONE : (919) 894-4436
PHONE : (919) 894-4436

28 335085

Dml

STRUCTURE: 000 000 75X42 3BDR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/14/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001408327
	5/14/07	AP	t poles must have seperate ground rods
B103 01	5/15/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001409580
	5/15/07	CA	SERVICE POLE INSPECTION.ELECTRICIAN HAD SEPARATE RODS BUT HAD THEM BONDED TOGETHER.HAS BEEN CHANGED. We do not do temp poles as a separate inspection. It will be done at the foundation inspection.
B103 03	5/31/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418722
	5/31/07	AP	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
B103 02	5/31/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418714
	5/30/07	CA	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
A814 01	6/05/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001422930
	7/03/07	AP	55 WEATHERBY CT LOT 13 NOT 56
B105 01	6/07/07	KS	R*OPEN FLOOR VRU #: 001423011
	6/07/07	AP	
R425 01	7/12/07	MR	FOUR TRADE ROUGH IN VRU #: 001444710
	7/12/07	DA	1. toilet gflanges must be installed, screwed down and pressure tested 2. Will check on insul. inspect.
I129 01	7/16/07	MR	R*INSULATION INSPECTION VRU #: 001447002
	7/16/07	AP	
R425 02	7/16/07	MR	FOUR TRADE ROUGH IN VRU #: 001447028
	7/16/07	AP	
M405 01	7/17/07	KS	R*MECHANICAL UNDERGROUND VRU #: 001446992
	7/17/07	CA	1. o not know what this inspection is. Went to job site but could not determine what was asked for.
R429 02	11/21/07	TI	FOUR TRADE FINAL VRU #: 001523653
	11/20/07	CA	CANCELLED. NO OPERATIONS PERMIT.
R429 01	11/21/07	TI	FOUR TRADE FINAL VRU #: 001523646
	11/20/07	CA	CANCELLED. NO OPERATIONS PERMIT

ADDRESS . . : 56 WEATHERBY CT
CONTRACTOR : STEPHENSON RANDY T
OWNER . . . : STEPHENSON RANDY #13
PARCEL . . . : 07-0691- - -0023- -12-
APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)

SUBDIV: HUNTERS POINT 45 LOTS
PHONE : (919) 894-4436
PHONE : (919) 894-4436

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 03	11/27/07 11/26/07	TI CA	FOUR TRADE FINAL VRU #: 001524982 CANCELLED 11/26/07. NO OPERATIONS PERMIT. NJT
H824 01	11/27/07 11/27/07	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001526250
R429 04	11/30/07 <u>11.30</u>	TI <u>DP</u>	FOUR TRADE FINAL VRU #: 001527993

----- COMMENTS AND NOTES -----

ADDRESS : 56 WEATHERBY CT
 CONTRACTOR : STEPHENSON RANDY T
 OWNER : STEPHENSON RANDY #13
 PARCEL : 07-0691- - -0023- -12-
 APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 E TO 27 TO COATS LEFT ON 55 GO APPRO
 X 3 MILES RIGHT ON SILAS HAYES HUNTERS P
 OINT ON RIGHT LOT 13 JB
 XXX
 PERMIT INCLUDES BLDG,ELEC,MECH,PLUMB
 INSULATION AND LAND USE.
 XXX
 Work must conform and comply with the
 STATE BUILDING CODE and all other State
 and local laws, ordinances & regulations

STRUCTURE: 000 000 75X42 3BDR
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/14/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001408327
	5/14/07	AP	t poles must have seperate ground rods
B103 01	5/15/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001409580
	5/15/07	CA	SERVICE POLE INSPECTION.ELECTRICIAN HAD SEPARATE RODS BUT HAD THEM BONDED TOGETHER.HAS BEEN CHANGED. We do not do temp poles as a separate inspection. It will be done at the foundation inspection.
B103 03	5/31/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418722
	5/31/07	AP	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
B103 02	5/31/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418714
	5/30/07	CA	PLEASE ALSO CHECK SERVICE POLE & SCHEDULE METER. THANKS, RANDY STEPHENSON 919-524-8763
A814 01	6/05/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001422930
	7/03/07	AP	55 WEATHERBY CT LOT 13 NOT 56
B105 01	6/07/07	KS	R*OPEN FLOOR VRU #: 001423011
	6/07/07	AP	
R425 01	7/12/07	MR	FOUR TRADE ROUGH IN VRU #: 001444710
	7/12/07	DA	1. toilet gflanges must be installed, screwed down and pressure tested 2. Will check on insul. inspect.
I129 01	7/16/07	MR	R*INSULATION INSPECTION VRU #: 001447002
	7/16/07	AP	
R425 02	7/16/07	MR	FOUR TRADE ROUGH IN VRU #: 001447028
	7/16/07	AP	
M405 01	7/17/07	KS	R*MECHANICAL UNDERGROUND VRU #: 001446992
	7/17/07	CA	1. o not know what this inspection is. Went to job site but could not determine what was asked for.
R429 02	11/21/07	TI	FOUR TRADE FINAL VRU #: 001523653
	11/20/07	CA	CANCELLED. NO OPERATIONS PERMIT.
R429 01	11/21/07	TI	FOUR TRADE FINAL VRU #: 001523646
	11/20/07	CA	CANCELLED. NO OPERATIONS PERMIT
R429 03	11/27/07	TI	FOUR TRADE FINAL VRU #: 001524982
	11/26/07	CA	CANCELLED 11/26/07. NO OPERATIONS PERMIT. NJT

ADDRESS . : 56 WEATHERBY CT
CONTRACTOR : STEPHENSON RANDY T
OWNER . . : STEPHENSON RANDY #13
PARCEL . . : 07-0691- - -0023- -12-
APPL NUMBER: 07-50017001 CP NEW RESIDENTIAL (SFD)

SUBDIV: HUNTERS POINT 45 LOTS
PHONE : (919) 894-4436
PHONE : (919) 894-4436

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	11/27/07 11/27/07	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001526250
R429 04	11/30/07 11/30/07	KS DP	FOUR TRADE FINAL VRU #: 001527993 1. No ground rod driven and no ground for service 2. Need covers on bath vents 3. Insulation missing from floor where deck bolts attach Premise number 28335085
R429 05	12/03/07 <u>12-3-07</u>	TI <u>AP</u>	FOUR TRADE FINAL VRU #: 001528694

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential Conditional Use Permit No.: _____
Type of Construction: V Building Permit No.: _____
Owner of Building: Randy Stephens Electrical Permit No.: _____
Building Address: 56 Weatherly CT Insulation Permit No.: _____
Zoning District: _____ Plumbing Permit No.: 075017001
Zoning Permit No.: _____ Mech. Permit No.: _____
Date: 10-3-07 Envir. C.O. No.: _____
K. Stath _____

Building Official

Zoning Official