
ADDRESS : 19151 *UNASSIGNED SUBDIV:
CONTRACTOR : PHONE :
OWNER : AUSDENMOORE MARTIN & APRIL #1 PHONE : (919) 207-1983
PARCEL : 02-1538- - -9000- -05-
APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : FOUNDATIONS BIBLE #1
421E TO 201 RT ON HODGES CHAPEL RD AT
NORDIC WHSE PROPERTY AT END OF 2ND
CURVE ON LEFT AT GRAVEL RD PILGRIMS
VIEW LN ON CORNER OF OTHER GRAVEL RD.JD

STRUCTURE: 000 000 42X48 4BR W/OUTSIDE STORAGE
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/11/07 <u>5-11-07</u>	TI <u>APBS</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001407345 I will not have the t-pole set up until foundation inspection. thanks.

----- COMMENTS AND NOTES -----

ADDRESS . . : 19151 *UNASSIGNED SUBDIV:
CONTRACTOR : PHONE :
OWNER . . : AUSDENMOORE MARTIN & APRIL #1 PHONE : (919) 207-1983
PARCEL . . : 02-1538- - -9000- -05-
APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : FOUNDATIONS BIBLE #1
421E TO 201 RT ON HODGES CHAPEL RD AT
NORDIC WHSE PROPERTY AT END OF 2ND
CURVE ON LEFT AT GRAVEL RD PILGRIMS
VIEW LN ON CORNER OF OTHER GRAVEL RD.JD

STRUCTURE: 000 000 42X48 4BR W/OUTSIDE STORAGE
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/11/07 5/11/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001407345 I will not have the t-pole set up until foundation inspection. thanks.
B103 01	6/01/07 <i>6-1</i>	TI <i>AP</i>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420314 This inspection is for building foundation and temp service electrical pole. Thanks.

----- COMMENTS AND NOTES -----

ADDRESS . . : 10 PILGRIMS VIEW LN SUBDIV:
CONTRACTOR : PHONE :
OWNER . . : AUSDENMOORE MARTIN & APRIL #1 PHONE : (919) 207-1983
PARCEL . . : 02-1538- - -9000- -05-
APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : FOUNDATIONS BIBLE #1
421E TO 201 RT ON HODGES CHAPEL RD AT
NORDIC WHSE PROPERTY AT END OF 2ND
CURVE ON LEFT AT GRAVEL RD PILGRIMS
VIEW LN ON CORNER OF OTHER GRAVEL RD.JD

STRUCTURE: 000 000 42X48 4BR W/OUTSIDE STORAGE
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/11/07 5/11/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001407345 I will not have the t-pole set up until foundation inspection. thanks.
B103 01	6/01/07 6/01/07	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420314 This inspection is for building foundation and temp service electrical pole. Thanks. Need portable toilet or no more inspections until one is on site
A814 01	6/06/07 6/07/07	TI AP	ADDRESS CONFIRMATION VRU #: 001423607 10 PILGRIMS VIEW LN
B105 01	6/08/07 <u>6-8</u>	TI <u>AP</u>	R*OPEN FLOOR VRU #: 001424290 Thanks! <u>KJ</u>

COMMENTS AND NOTES

ADDRESS . : 10 PILGRIMS VIEW LN SUBDIV:
CONTRACTOR : PHONE :
OWNER . . : AUSDENMOORE MARTIN & APRIL #1 PHONE : (919) 207-1983
PARCEL . . : 02-1538- - -9000- -05-
APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : FOUNDATIONS BIBLE #1
421E TO 201 RT ON HODGES CHAPEL RD AT
NORDIC WHSE PROPERTY AT END OF 2ND
CURVE ON LEFT AT GRAVEL RD PILGRIMS
VIEW LN ON CORNER OF OTHER GRAVEL RD.JD

STRUCTURE: 000 000 42X48 4BR W/OUTSIDE STORAGE
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/11/07 5/11/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001407345 I will not have the t-pole set up until foundation inspection. thanks.
B103 01	6/01/07 6/01/07	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420314 This inspection is for building foundation and temp service electrical pole. Thanks. Need portable toilet or no more inspections until one is on site
A814 01	6/06/07 6/07/07	TI AP	ADDRESS CONFIRMATION VRU #: 001423607 10 PILGRIMS VIEW LN
B105 01	6/08/07 6/10/07	KS AP	R*OPEN FLOOR VRU #: 001424290 Thanks!
R425 01	11/05/07 <u>11-5</u>	TI <u>DA</u>	FOUR TRADE ROUGH IN VRU #: 001514819 Front door will be unlocked. If you don't mind calling me when you are there, I have a few questions. 919-820-1308. Thanks.

----- COMMENTS AND NOTES -----

ADDRESS . . : 10 PILGRIMS VIEW LN
 CONTRACTOR :
 OWNER . . . : AUSDENMOORE MARTIN & APRIL #1
 PARCEL . . . : 02-1538- - -9000- -05-
 APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : FOUNDATIONS BIBLE #1
 421E TO 201 RT ON HODGES CHAPEL RD AT
 NORDIC WHSE PROPERTY AT END OF 2ND
 CURVE ON LEFT AT GRAVEL RD PILGRIMS
 VIEW LN ON CORNER OF OTHER GRAVEL RD.JD

STRUCTURE: 000 000 42X48 4BR W/OUTSIDE STORAGE
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/11/07 5/11/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001407345 I will not have the t-pole set up until foundation inspection. thanks.
B103 01	6/01/07 6/01/07	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420314 This inspection is for building foundation and temp service electrical pole. Thanks. Need portable toilet or no more inspections until one is on site
A814 01	6/06/07 6/07/07	TI AP	ADDRESS CONFIRMATION VRU #: 001423607 10 PILGRIMS VIEW LN
B105 01	6/08/07 6/10/07	KS AP	R*OPEN FLOOR VRU #: 001424290 Thanks!
R425 01	11/05/07 11/05/07	KS DA	FOUR TRADE ROUGH IN VRU #: 001514819 Front door will be unlocked. If you don't mind calling me when you are there, I have a few questions. 919-820-1308. Thanks. 1. Need return air duct installed upstairs. Shall be on both floors. 2. Riser from platform cannot exceed 8 1/4 inches when finished. 3. need receptacles accessible from grade on front and rear of house and within 25 feet of a/c unit. 4. cannot feed receptacle on rear porch from kitchen circuit. 5. Receptacles in dining area shall be 20 amp circuit ergo 12-2 shall feed that receptacle. OK to side--do not insulate.
R425 02	11/06/07	TI	FOUR TRADE ROUGH IN VRU #: 001516111

AP KS
NGJ

----- COMMENTS AND NOTES -----

ADDRESS : 10 PILGRIMS VIEW LN
 CONTRACTOR :
 OWNER : AUSDENMOORE MARTIN & APRIL #1
 PARCEL : 02-1538- - -9000- -05-
 APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)

SUBDIV:
 PHONE :
 PHONE : (919) 207-1983

DIRECTIONS : FOUNDATIONS BIBLE #1
 421E TO 201 RT ON HODGES CHAPEL RD AT
 NORDIC WHSE PROPERTY AT END OF 2ND
 CURVE ON LEFT AT GRAVEL RD PILGRIMS
 VIEW LN ON CORNER OF OTHER GRAVEL RD.JD

STRUCTURE: 000 000 42X48 4BR W/OUTSIDE STORAGE
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/11/07 5/11/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001407345 I will not have the t-pole set up until foundation inspection. thanks.
B103 01	6/01/07 6/01/07	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420314 This inspection is for building foundation and temp service electrical pole. Thanks. Need portable toilet or no more inspections until one is on site
A814 01	6/06/07 6/07/07	TI AP	ADDRESS CONFIRMATION VRU #: 001423607 10 PILGRIMS VIEW LN
B105 01	6/08/07 6/10/07	KS AP	R*OPEN FLOOR VRU #: 001424290 Thanks!
R425 01	11/05/07 11/05/07	KS DA	FOUR TRADE ROUGH IN VRU #: 001514819 Front door will be unlocked. If you don't mind calling me when you are there, I have a few questions. 919-820-1308. Thanks. 1. Need return air duct installed upstairs. Shall be on both floors. 2. Riser from platform cannot exceed 8 1/4 inches when finished. 3. need receptacles accessible from grade on front and rear of house and within 25 feet of a/c unit. 4. cannot feed receptacle on rear porch from kitchen circuit. 5. Receptacles in dining area shall be 20 amp circuit ergo 12-2 shall feed that receptacle. OK to side--do not insulate.
R425 02	11/06/07 11/06/07	KS AP	FOUR TRADE ROUGH IN VRU #: 001516111
I129 02	12/12/07 <u>12-12</u>	TI <u>AP</u>	R*INSULATION INSPECTION VRU #: 001533496 Just a reminder about the insulation--Kenny gave me permission to put 3+ layers of R-13 for all attic ceilings in place of "R-30" insulation. Only the layer next to the heated space has the kraft face attached. This was a verbal permission given during a telephone conversation with Kenny on or about 10/21/2007. Thank you again for this consideration/permission. (The R-19 crawl space insulation will be completed for the final (CO) inspection.)
I129 01	12/12/07 12/11/07	TI CA	R*INSULATION INSPECTION VRU #: 001533488 Just a reminder about the insulation--Kenny gave me permission to put 3+ layers of R-13 for all attic ceilings

ADDRESS . : 10 PILGRIMS VIEW LN
CONTRACTOR :
OWNER . . : AUSDENMOORE MARTIN & APRIL #1
PARCEL . . : 02-1538- - -9000- -05-
APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)

SUBDIV:
PHONE :
PHONE : (919) 207-1983

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			heated space has the kraft face attached. This was a verbal permission given during a telephone conversation with Kenny on or about 10/21/2007. Thank you again for this consideration/permission. (The R-19 crawl space insulation will be completed for the final (CO) inspection.)
H824 01	12/18/07	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001538164
	12/18/07	AP	
M305 01	2/28/08	TI	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 001569425
	<u>11</u>	<u>AP-MR</u>	customer requests septic connection inspected so he can cover it. customer ok'd with ken.

----- COMMENTS AND NOTES -----

ADDRESS : 10 PILGRIMS VIEW LN
CONTRACTOR :
OWNER : AUSDENMOORE MARTIN & APRIL #1
PARCEL : 02-1538- - -9000- -05-
APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)

SUBDIV:
PHONE :
PHONE : (919) 207-1983

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 01	12/12/07 12/11/07	TI CA	this consideration/permission. (The R-19 crawl space insulation will be completed for the final (CO) inspection.) R*INSULATION INSPECTION VRU #: 001533488 Just a reminder about the insulation--Kenny gave me permission to put 3+ layers of R-13 for all attic ceilings in place of "R-30" insulation. Only the layer next to the heated space has the kraft face attached. This was a verbal permission given during a telephone conversation with Kenny on or about 10/21/2007. Thank you again for this consideration/permission. (The R-19 crawl space insulation will be completed for the final (CO) inspection.)
H824 01	12/18/07 12/18/07	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001538164
M305 01	2/28/08 2/28/08	MR AP	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 001569425 customer requests septic connection inspected so he can cover it. customer ok'd with ken.
P307 01	2/02/09 <u>2-2</u>	TI <u>AP</u>	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 001730720

KS

----- COMMENTS AND NOTES -----

ADDRESS : 10 PILGRIMS VIEW LN
CONTRACTOR :
OWNER : AUSDENMOORE MARTIN & APRIL #1
PARCEL : 02-1538- - -9000- -05-
APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)

SUBDIV:
PHONE :
PHONE : (919) 207-1983

DIRECTIONS : FOUNDATIONS BIBLE #1
421E TO 201 RT ON HODGES CHAPEL RD AT
NORDIC WHSE PROPERTY AT END OF 2ND
CURVE ON LEFT AT GRAVEL RD PILGRIMS
VIEW LN ON CORNER OF OTHER GRAVEL RD.JD

07831998
called-1339

STRUCTURE: 000 000 42X48 4BR W/OUTSIDE STORAGE
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/11/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001407345
	5/11/07	AP	I will not have the t-pole set up until foundation inspection. thanks.
B103 01	6/01/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420314
	6/01/07	AP	This inspection is for building foundation and temp service electrical pole. Thanks. Need portable toilet or no more inspections until one is on site
A814 01	6/06/07	TI	ADDRESS CONFIRMATION VRU #: 001423607
	6/07/07	AP	10 PILGRIMS VIEW LN
B105 01	6/08/07	KS	R*OPEN FLOOR VRU #: 001424290
	6/10/07	AP	Thanks!
R425 01	11/05/07	KS	FOUR TRADE ROUGH IN VRU #: 001514819
	11/05/07	DA	Front door will be unlocked. If you don't mind calling me when you are there, I have a few questions. 919-820-1308. Thanks. 1. Need return air duct installed upstairs. Shall be on both floors. 2. Riser from platform cannot exceed 8 1/4 inches when finished. 3. need receptacles accessible from grade on front and rear of house and within 25 feet of a/c unit. 4. cannot feed receptacle on rear porch from kitchen circuit. 5. Receptacles in dining area shall be 20 amp circuit ergo 12-2 shall feed that receptacle. OK to side--do not insulate.
R425 02	11/06/07	KS	FOUR TRADE ROUGH IN VRU #: 001516111
	11/06/07	AP	
I129 02	12/12/07	KS	R*INSULATION INSPECTION VRU #: 001533496
	12/12/07	AP	Just a reminder about the insulation--Kenny gave me permission to put 3+ layers of R-13 for all attic ceilings in place of "R-30" insulation. Only the layer next to the heated space has the kraft face attached. This was a verbal permission given during a telephone conversation

ADDRESS : 10 PILGRIMS VIEW LN
CONTRACTOR :
OWNER : AUSDENMOORE MARTIN & APRIL #1
PARCEL : 02-1538- - -9000- -05-
APPL NUMBER: 07-50017328 CP NEW RESIDENTIAL (SFD)

SUBDIV:
PHONE :
PHONE : (919) 207-1983

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			with Kenny on or about 10/21/2007. Thank you again for this consideration/permission. (The R-19 crawl space insulation will be completed for the final (CO) inspection.)
I129 01	12/12/07 12/11/07	TI CA	R*INSULATION INSPECTION VRU #: 001533488 Just a reminder about the insulation--Kenny gave me permission to put 3+ layers of R-13 for all attic ceilings in place of "R-30" insulation. Only the layer next to the heated space has the kraft face attached. This was a verbal permission given during a telephone conversation with Kenny on or about 10/21/2007. Thank you again for this consideration/permission. (The R-19 crawl space insulation will be completed for the final (CO) inspection.)
H824 01	12/18/07 12/18/07	JM AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001538164
M305 01	2/28/08 2/28/08	MR AP	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 001569425 customer requests septic connection inspected so he can cover it. customer ok'd with ken.
P307 01	2/02/09 2/02/09	KS AP	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 001730720
R429 01	2/09/09 2/09/09	TI CA	FOUR TRADE FINAL VRU #: 001732700 When on the way, please call 919-820-1308 so that I can have the house unlocked. Thanks.
R429 02	2/10/09 <u>2-10-09</u>	TI <u>AP</u>	FOUR TRADE FINAL VRU #: 001733054 Please call 919-820-1308 when on the way to get the door unlocked. Thanks. <i>Washer on 20 Amp - Keyed</i>

COMMENTS AND NOTES

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential

Owner: Martin Anderson

911 Address: 10 Pilgrims View Ln
Dulm

State: _____ Zip Code: _____

Date: 2-10-09

Ke Stalt
Building Official

PERMIT NUMBERS

Building Permit No.: _____

Electrical Permit No.: _____

Insulation Permit No.: _____

Plumbing Permit No.: _____

Mech. Permit No.: _____

MFG. Home: _____

02-50017328