

ADDRESS . . : 164 BUIE FARM LN
CONTRACTOR : LANGSTON, ERNEST LEE
OWNER . . . : TURI GEORGE & ALISON #5
PARCEL . . . : 07-0692- - -0165- - -
APPL NUMBER: 07-50017687 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 421 SOUTH TURN LEFT ON HEY 27 EAST
RIGHT ONTO BUIE FARMS LANE 1ST LOT ON
RIGHT LOT 5 JB

SUBDIV:
PHONE : (910) 395-0443
PHONE : (919) 775-2049

STRUCTURE: 000 000 70X72 4BDR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
--------	------------------------	----------------	---------------------------------

B101 01	8/01/07 <u>8/1</u>	TI <u>AR</u>	R*BLDG FOOTING / TEMP SVC POLE VOICE MESSAGE LEFT
---------	-----------------------	-----------------	--

VRU #: 001457462

COMMENTS AND NOTES

919 - 868 - 4191

ADDRESS . . : 164 BUIE FARM LN
CONTRACTOR : LANGSTON, ERNEST LEE
OWNER . . . : TURI GEORGE & ALISON #5
PARCEL . . . : 07-0692- - -0165- - -
APPL NUMBER: 07-50017687 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 421 SOUTH TURN LEFT ON HEY 27 EAST
RIGHT ONTO BUIE FARMS LANE 1ST LOT ON
RIGHT LOT 5 JB

SUBDIV:
PHONE : (910) 395-0443
PHONE : (919) 775-2049

STRUCTURE: 000 000 70X72 4BDR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/01/07	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001457462
	8/01/07	AP	VOICE MESSAGE LEFT
B103 01	8/14/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001466556
	8/14/07	AP	
A814 01	8/14/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001466598
	8/15/07	AP	164 BUIE FARM LN LOT5
B105 01	9/11/07	TI	R*OPEN FLOOR VRU #: 001482918

9-11 70

KS

COMMENTS AND NOTES

Quinz's

PREPARED 10/12/07, 14:08:29
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

ADDRESS : 164 BUIE FARM LN
CONTRACTOR : LANGSTON, ERNEST LEE
OWNER : TURI GEORGE & ALISON #5
PARCEL : 07-0692- - -0165- - -
APPL NUMBER: 07-50017687 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 421 SOUTH TURN LEFT ON HEY 27 EAST
RIGHT ONTO BUIE FARMS LANE 1ST LOT ON
RIGHT LOT 5 JB

SUBDIV:
PHONE : (910) 395-0443
PHONE : (919) 775-2049

STRUCTURE: 000 000 70X72 4BDR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/01/07	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001457462
	8/01/07	AP	VOICE MESSAGE LEFT
B103 01	8/14/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001466556
	8/14/07	AP	
A814 01	8/14/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001466598
	8/15/07	AP	164 BUIE FARM LN LOT5
B105 01	9/11/07	KS	R*OPEN FLOOR VRU #: 001482918
	9/11/07	AP	
R427 01	10/15/07	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001504067

10-15-07 IVR

COMMENTS AND NOTES

ADDRESS . : 164 BUIE FARM LN
 CONTRACTOR : LANGSTON, ERNEST LEE
 OWNER . . : TURI GEORGE & ALISON #5
 PARCEL . . : 07-0692- - -0165- - -
 APPL NUMBER: 07-50017687 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 SOUTH TURN LEFT ON HEY 27 EAST
 RIGHT ONTO BUIE FARMS LANE 1ST LOT ON
 RIGHT LOT 5 JB

SUBDIV:
 PHONE : (910) 395-0443
 PHONE : (919) 775-2049

STRUCTURE: 000 000 70X72 4BDR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/01/07	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001457462
	8/01/07	AP	VOICE MESSAGE LEFT
B103 01	8/14/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001466556
	8/14/07	AP	
A814 01	8/14/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001466598
	8/15/07	AP	164 BUIE FARM LN LOT5
B105 01	9/11/07	KS	R*OPEN FLOOR VRU #: 001482918
	9/11/07	AP	
R427 01	10/15/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001504067
	10/15/07	DA	1. Need tempered glass at master tub top and bottom sashes. 2. Washing machine box must be 34 inches above FINISHED FLOOR. (tile floor) 3. Support double 2x10 valley to load wall below 4. Sheet inside garage walls w/ osb. 5. Rodent proof all holes in floor at tub and shower traps with sheet metal and firecaulk. 6. Header above front window not supported on jacks. Install hangers to triples from trey ceiling. ok to side/insulate
I129 01	10/19/07	TI	R*INSULATION INSPECTION VRU #: 001507334
	<u>10-19</u>	<u>AP</u>	
R427 02	10/19/07	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001507342
	<u>10-19</u>	<u>AP</u>	1 C S

COMMENTS AND NOTES

ADDRESS . : 164 BUIE FARM LN
 CONTRACTOR : LANGSTON ERNEST LEE
 OWNER . . : TURI GEORGE & ALISON #5
 PARCEL . . : 07-0692- - -0165- - -
 APPL NUMBER: 07-50017687 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 SOUTH TURN LEFT ON HEY 27 EAST
 RIGHT ONTO BUIE FARMS LANE 1ST LOT ON
 RIGHT LOT 5 JB

SUBDIV:
 PHONE : (910) 395-0443
 PHONE : (919) 775-2049

STRUCTURE: 000 000 70X72 4BDR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/01/07	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001457462
	8/01/07	AP	VOICE MESSAGE LEFT
B103 01	8/14/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001466556
	8/14/07	AP	
A814 01	8/14/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001466598
	8/15/07	AP	✓164 BUIE FARM LN LOT5
B105 01	9/11/07	KS	R*OPEN FLOOR VRU #: 001482918
	9/11/07	AP	
R427 01	10/15/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001504067
	10/15/07	DA	1. Need tempered glass at master tub top and bottom sashes. 2. Washing machine box must be 34 inches above FINISHED FLOOR. (tile floor) 3. Support double 2x10 valley to load wall below 4. Sheet inside garage walls w/ osb. 5. Rodent proof all holes in floor at tub and shower traps with sheet metal and firecaulk. 6. Header above front window not supported on jacks. Install hangers to triples from trey ceiling. ok to side/insulate
I129 01	10/19/07	KS	R*INSULATION INSPECTION VRU #: 001507334
	10/19/07	AP	1. Cantilever ingarage is open. Needs 1/2 inch sheetrock. 2. Remove 2x4's on piers
R427 02	10/19/07	KS	FOUR TRADE ROUGH IN >2500 VRU #: 001507342
	10/19/07	AP	1. Cantilever ingarage is open. Needs 1/2 inch sheetrock. 2. Remove 2x4's on piers
H824 01	12/10/07	JM	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533751
	12/10/07	AP	
R431 01	1/08/08	TI	FOUR TRADE FINAL >2500 VRU #: 001543909

1-8 DA

COMMENTS AND NOTES

ADDRESS : 164 BUIE FARM LN
 CONTRACTOR : LANGSTON ERNEST LEE
 OWNER : TURI GEORGE & ALISON #5
 PARCEL : 07-0692- - -0165- - -
 APPL NUMBER: 07-50017687 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 421 SOUTH TURN LEFT ON HEY 27 EAST
 RIGHT ONTO BUIE FARMS LANE 1ST LOT ON
 RIGHT LOT 5 JB

SUBDIV:
 PHONE : (910) 395-0443
 PHONE : (919) 775-2049

48973258

STRUCTURE: 000 000 70X72 4BDR SFD
 FLOOD ZONE : FLOOD ZONE X

called PE - 10.51

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/01/07	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001457462
	8/01/07	AP	VOICE MESSAGE LEFT
B103 01	8/14/07	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001466556
	8/14/07	AP	
A814 01	8/14/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001466598
	8/15/07	AP	✓ 164 BUIE FARM LN LOT5
B105 01	9/11/07	KS	R*OPEN FLOOR VRU #: 001482918
	9/11/07	AP	
R427 01	10/15/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001504067
	10/15/07	DA	1. Need tempered glass at master tub top and bottom sashes. 2. Washing machine box must be 34 inches above FINISHED FLOOR. (tile floor) 3. Support double 2x10 valley to load wall below 4. Sheet inside garage walls w/ osb. 5. Rodent proof all holes in floor at tub and shower traps with sheet metal and firecaulk. 6. Header above front window not supported on jacks. Install hangers to triples from trey ceiling. ok to side/insulate
I129 01	10/19/07	KS	R*INSULATION INSPECTION VRU #: 001507334
	10/19/07	AP	1. Cantilever ingarage is open. Needs 1/2 inch sheetrock. 2. Remove 2x4's on piers
R427 02	10/19/07	KS	FOUR TRADE ROUGH IN >2500 VRU #: 001507342
	10/19/07	AP	1. Cantilever ingarage is open. Needs 1/2 inch sheetrock. 2. Remove 2x4's on piers
H824 01	12/10/07	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533751
	12/10/07	AP	
R431 01	1/08/08	KS	FOUR TRADE FINAL >2500 VRU #: 001543909
	1/08/08	DA	✓ 1. Need 911 address at road due to home being greater than 100 feet from road. ✓ 2. Need wind rating label on garage doors. ✓ 3. Need receptacle for microwave. ✓ 4. Insulate plumbing lines in garage for water heater and sink with R 6.5 insulation. 5. Need lintels installed where bloock was broken out for vents. ✓ 6. There shall be a vent within 3 feet of corners of house. 7. Vent missing behind a/c units. 8. House bibs shall be secured to brick. ✓ 9. Reinstall insulation that has fallen in attic.
R431 02	1/14/08	TI	FOUR TRADE FINAL >2500 VRU #: 001546886

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential Conditional Use Permit No.: _____
Type of Construction: V Building Permit No.: _____
Owner of Building: George Turi Electrical Permit No.: _____
Building Address: 1164 Blue Fern Ln Insulation Permit No.: _____
Zoning District: _____ Plumbing Permit No.: _____
Zoning Permit No.: _____ Mech. Permit No.: _____
Date: 1-14-08 Envir. C.O. No.: _____
K. Slatt Building Official _____ Zoning Official