

ADDRESS : GREEN LEVEL DR
CONTRACTOR : RAYNOR BUILDERS INC
OWNER : KINSEY PAUL JR & LISA #46
PARCEL : 04-0663- - -0029- - -
APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)

SUBDIV: NEILLS CREEK FARMS PHASE 1
PHONE : (919) 639-3012
PHONE : 3

DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
NORRIS RT WHEELER DR RT GREEN LEVEL LOT
ON RT.JD

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	<u>2/11/08</u> <u>2-11</u>	<u>TI</u> <u>AP</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	<u>2/11/08</u> <u>2-11</u>	<u>TI</u> <u>AP</u>	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018

Handwritten note: 227-5467

----- COMMENTS AND NOTES -----

ADDRESS : GREEN LEVEL DR SUBDIV: NEILLS CREEK FARMS PHASE 1
CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
OWNER : KINSEY PAUL JR & LISA #46 PHONE : 3
PARCEL : 04-0663- - -0029- - -
APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
NORRIS RT WHEELER DR RT GREEN LEVEL LOT
ON RT.JD

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08 2/11/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08 2/11/08	KS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
A814 01	2/18/08	TI	ADDRESS CONFIRMATION VRU #: 001564640
B103 01	2/18/08 2/18/08	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl 2. Wall not built to support floor truss at top of stairs. 3. Need change stating 16 inch lsl to replace 2 9 1/4's Jacks studs missing. 4 Plan calls for 3 16 inch lvl's--only 2 inplace.
B105 01	2/18/08 <u>2-18-08</u>	TI <u>DA</u>	R*OPEN FLOOR TIME: 17:00 VRU #: 001565282

----- COMMENTS AND NOTES -----

ADDRESS : GREEN LEVEL DR SUBDIV: NEILLS CREEK FARMS PHASE 1
CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
OWNER : KINSEY PAUL JR & LISA #46 PHONE : 3
PARCEL : 04-0663- - -0029- - -
APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
NORRIS RT WHEELER DR RT GREEN LEVEL LOT
ON RT.JD

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 5.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150
	2/11/08	AP	This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08	KS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
	2/11/08	AP	
A814 01	2/18/08	TI	ADDRESS CONFIRMATION VRU #: 001564640
B103 01	2/18/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657

2-18 AT

COMMENTS AND NOTES

Application number, type 07 50018545 CP NEW RESIDENTIAL (SFD)
Property address GREEN LEVEL DR

- 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl
- 2. Wall not built to support floor truss at top of stairs.
- 3. Need change stating 16 inch lvl to replace 2 9 1/4's Jacks studs missing.
- 4 Plan calls for 3 16 inch lvl's--only 2 in place.



OK Exit Cancel Copy Insert Delete Time stamp User defaults

ADDRESS : GREEN LEVEL DR
CONTRACTOR : RAYNOR BUILDERS INC
OWNER : KINSEY PAUL JR & LISA #46
PARCEL : 04-0663- - -0029- - -
APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
NORRIS RT WHEELER DR RT GREEN LEVEL LOT
ON RT.JD

SUBDIV: NEILLS CREEK FARMS PHASE 1
PHONE : (919) 639-3012
PHONE : 3

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08 2/11/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08 2/11/08	KS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
A814 01	2/18/08	TI	ADDRESS CONFIRMATION VRU #: 001564640
B103 01	2/18/08 2/18/08	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl 2. Wall not built to support floor truss at top of stairs. 3. Need change stating 16 inch lsl to replace 2 9 1/4's Jacks studs missing. 4 Plan calls for 3 16 inch lvl's--only 2 in place.
B105 01	2/18/08 2/18/08	KS DA	R*OPEN FLOOR TIME: 17:00 VRU #: 001565282
B105 02	2/20/08 <i>2/20/08</i>	TI <i>DABS</i>	R*OPEN FLOOR VRU #: 001565464

COMMENTS AND NOTES

ADDRESS : GREEN LEVEL DR
CONTRACTOR : RAYNOR BUILDERS INC
OWNER : KINSEY PAUL JR & LISA #46
PARCEL : 04-0663- - -0029- - -
APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
NORRIS RT WHEELER DR RT GREEN LEVEL LOT
ON RT.JD

SUBDIV: NEILLS CREEK FARMS PHASE 1
PHONE : (919) 639-3012
PHONE : 3

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08 2/11/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08 2/11/08	KS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
B103 01	2/18/08 2/18/08	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl 2. Wall not built to support floor truss at top of stairs. 3. Need change stating 16 inch lsl to replace 2 9 1/4's Jacks studs missing. 4 Plan calls for 3 16 inch lvl's--only 2 in place.
A814 01	2/18/08 2/20/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001564640 190 GREEN LEVEL DR LOT 46
B105 01	2/18/08 2/18/08	KS DA	R*OPEN FLOOR TIME: 17:00 VRU #: 001565282
B105 02	2/20/08 2/20/08	BS DA	R*OPEN FLOOR VRU #: 001565464 1. Frame wall adjacent to plumbing test 12 inches on center (this is a load wall, truss above is straight framed, not webbed) 2. Wall point in truss at front has no wall underneath, there is a wall framed and laying on the floor, but it is not installed. RECHECK AT ROUGH IN
B101 02	3/05/08 <u>3-5-08</u>	TI <u>AP</u>	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001572114 WILL BE FOR PIER FOOTINGS.

COMMENTS AND NOTES

72472073

ADDRESS : GREEN LEVEL DR SUBDIV: NEILLS CREEK FARMS PHASE 1
CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
OWNER : KINSEY PAUL JR & LISA #46 PHONE : 3
PARCEL : 04-0663- - -0029- - -
APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
NORRIS RT WHEELER DR RT GREEN LEVEL LOT
ON RT.JD

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 5.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08 2/11/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08 2/11/08	KS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
B103 01	2/18/08 2/18/08	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl 2. Wall not built to support floor truss at top of stairs. 3. Need change stating 16 inch lsl to replace 2 9 1/4's Jacks studs missing. 4. Plan calls for 3 16 inch lvl's--only 2 in place.
A814 01	2/18/08 2/20/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001564640 190 GREEN LEVEL DR LOT 46
B105 01	2/18/08 2/18/08	KS DA	R*OPEN FLOOR TIME: 17:00 VRU #: 001565282
B105 02	2/20/08 2/20/08	BS DA	R*OPEN FLOOR VRU #: 001565464 1. Frame wall adjacent to plumbing test 12 inches on center (this is a load wall, truss above is straight framed, not webbed) 2. Wall point in truss at front has no wall underneath, there is a wall framed and laying on the floor, but it is not installed. RECHECK AT ROUGH IN
B101 02	3/05/08 3/05/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001572114 WILL BE FOR PIER FOOTINGS. 200 amp service with nothing attached to it. Need final use of this service in place for inspection.
R425 01	3/25/08	TI	FOUR TRADE ROUGH IN VRU #: 001581853

DA-MR

COMMENTS AND NOTES

Some h.d. pts missed under walls
Rough Pl+Elect OK
garage anchors
OK to insulate + side

ADDRESS : GREEN LEVEL DR SUBDIV: NEILLS CREEK FARMS PHASE 1
 CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
 OWNER : KINSEY PAUL JR & LISA #46 PHONE : 3
 PARCEL : 04-0663- - -0029- - -
 APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
 NORRIS RT WHEELER DR RT GREEN LEVEL LOT
 ON RT.JD

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08 2/11/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08 2/11/08	KS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
B103 01	2/18/08 2/18/08	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl 2. Wall not built to support floor truss at top of stairs. 3. Need change stating 16 inch lsl to replace 2 9 1/4's Jacks studs missing. 4 Plan calls for 3 16 inch lvl's--only 2 in place.
A814 01	2/18/08 2/20/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001564640 190 GREEN LEVEL DR LOT 46
B105 01	2/18/08 2/18/08	KS DA	R*OPEN FLOOR TIME: 17:00 VRU #: 001565282
B105 02	2/20/08 2/20/08	BS DA	R*OPEN FLOOR VRU #: 001565464 1. Frame wall adjacent to plumbing test 12 inches on center (this is a load wall, truss above is straight framed, not webbed) 2. Wall point in truss at front has no wall underneath, there is a wall framed and laying on the floor, but it is not installed. RECHECK AT ROUGH IN
B101 02	3/05/08 3/05/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001572114 WILL BE FOR PIER FOOTINGS. 200 amp service with nothing attached to it. Need final use of this service in place for inspection.
R425 01	3/25/08 3/25/08	MR DA	FOUR TRADE ROUGH IN VRU #: 001581853 1. load pt missed under wall along stairway 2. rough pl and elect ok 3. garage anchors missing 4.ok to side and insul.
I129 02	4/08/08 <u>4-8</u>	TI <u>AP</u>	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001589670
R427 01	4/08/08 <u>4-8</u>	TI <u>AP</u>	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001589662

COMMENTS AND NOTES

ADDRESS : GREEN LEVEL DR
 CONTRACTOR : RAYNOR BUILDERS INC
 OWNER : KINSEY PAUL JR & LISA #46
 PARCEL : 04-0663- - -0029- - -
 APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
 NORRIS RT WHEELER DR RT GREEN LEVEL LOT
 ON RT.JD

SUBDIV: NEILLS CREEK FARMS PHASE 1
 PHONE : (919) 639-3012
 PHONE : 3

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08 2/11/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08 2/11/08	KS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
B103 01	2/18/08 2/18/08	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl 2. Wall not built to support floor truss at top of stairs. 3. Need change stating 16 inch lsl to replace 2 9 1/4's Jacks studs missing. 4 Plan calls for 3 16 inch lvl's--only 2 in place.
A814 01	2/18/08 2/20/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001564640 190 GREEN LEVEL DR LOT 46
B105 01	2/18/08 2/18/08	KS DA	R*OPEN FLOOR TIME: 17:00 VRU #: 001565282
B105 02	2/20/08 2/20/08	BS DA	R*OPEN FLOOR VRU #: 001565464 1. Frame wall adjacent to plumbing test 12 inches on center (this is a load wall, truss above is straight framed, not webbed) 2. Wall point in truss at front has no wall underneath, there is a wall framed and laying on the floor, but it is not installed. RECHECK AT ROUGH IN
B101 02	3/05/08 3/05/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001572114 WILL BE FOR PIER FOOTINGS. 200 amp service with nothing attached to it. Need final use of this service in place for inspection.
R425 01	3/25/08 3/25/08	MR DA	FOUR TRADE ROUGH IN VRU #: 001581853 1. load pt missed under wall along stairway 2. rough pl and elect ok 3. garage anchors missing 4.ok to side and insul.
I129 02	4/08/08 4/08/08	KS AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001589670
R427 01	4/08/08 4/08/08	KS AP	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001589662
I129 01	4/09/08	TI	R*INSULATION INSPECTION VRU #: 001589654

4-9- AP

ADDRESS : 190 GREEN LEVEL DR SUBDIV: NEILLS CREEK FARMS PHASE 1
 CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
 OWNER : KINSEY PAUL JR & LISA #46 PHONE : 3
 PARCEL : 04-0663- - -0029- - -
 APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
 NORRIS RT WHEELER DR RT GREEN LEVEL LOT
 ON RT.JD

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 5.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08 2/11/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08 2/11/08	KS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
B103 01	2/18/08 2/18/08	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl 2. Wall not built to support floor truss at top of stairs. 3. Need change stating 16 inch lsl to replace 2 9 1/4's Jacks studs missing. 4 Plan calls for 3 16 inch lvl's--only 2 in place.
A814 01	2/18/08 2/20/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001564640 190 GREEN LEVEL DR LOT 46
B105 01	2/18/08 2/18/08	KS DA	R*OPEN FLOOR TIME: 17:00 VRU #: 001565282
B105 02	2/20/08 2/20/08	BS DA	R*OPEN FLOOR VRU #: 001565464 1. Frame wall adjacent to plumbing test 12 inches on center (this is a load wall, truss above is straight framed, not webbed) 2. Wall point in truss at front has no wall underneath, there is a wall framed and laying on the floor, but it is not installed. RECHECK AT ROUGH IN
B101 02	3/05/08 3/05/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001572114 WILL BE FOR PIER FOOTINGS. 200 amp service with nothing attached to it. Need final use of this service in place for inspection.
R425 01	3/25/08 3/25/08	MR DA	FOUR TRADE ROUGH IN VRU #: 001581853 1. load pt missed under wall along stairway 2. rough pl and elect ok 3. garage anchors missing 4.ok to side and insul.
I129 02	4/08/08 4/08/08	KS AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001589670
R427 01	4/08/08 4/08/08	KS AP	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001589662

PREPARED 5/23/08, 14:23:54
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 10
DATE 5/27/08

ADDRESS : 190 GREEN LEVEL DR
CONTRACTOR : RAYNOR BUILDERS INC
OWNER : KINSEY PAUL JR & LISA #46
PARCEL : 04-0663- - -0029- - -
APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)

SUBDIV: NEILLS CREEK FARMS PHASE 1
PHONE : (919) 639-3012
PHONE : 3

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 01	4/09/08	KS	R*INSULATION INSPECTION VRU #: 001589654
	4/09/08	CA	done yesterday
H824 01	4/16/08	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001595511
	4/16/08	AP	
R431 01	5/27/08	TI	FOUR TRADE FINAL >2500 VRU #: 001614775
	<u>5-27-08</u>	<u>DAB</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 190 GREEN LEVEL DR
 CONTRACTOR : RAYNOR BUILDERS INC
 OWNER : KINSEY PAUL JR & LISA #46
 PARCEL : 04-0663- - -0029- - -
 APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : NEILLS CREEK FARMS #46-210 RT JAMES
 NORRIS RT WHEELER DR RT GREEN LEVEL LOT
 ON RT.JD

SUBDIV: NEILLS CREEK FARMS PHASE 1
 PHONE : (919) 639-3012
 PHONE : 3

STRUCTURE: 000 000 64X64 5BR FULL BASEMENT W/GARAGE
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/11/08 2/11/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001560150 This is a superior wall basement system.No footing required. I have walls & under slab plumbing as well as lug footings ready for inspection. Thanks
P309 01	2/11/08 2/11/08	KS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001561018
B103 01	2/18/08 2/18/08	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001564657 1. Lvl at door for stairs calls for 3 jack studs supporting the lvl 2. Wall not built to support floor truss at top of stairs. 3. Need change stating 16 inch lsl to replace 2 9 1/4's Jacks studs missing. 4 Plan calls for 3 16 inch lvl's--only 2 inplace.
A814 01	2/18/08 2/20/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001564640 ✓190 GREEN LEVEL DR LOT 46
B105 01	2/18/08 2/18/08	KS DA	R*OPEN FLOOR TIME: 17:00 VRU #: 001565282
B105 02	2/20/08 2/20/08	BS DA	R*OPEN FLOOR VRU #: 001565464 1. Frame wall adjacent to plumbing test 12 inches on center (this is a load wall, truss above is straight framed, not webbed) 2. Wall point in truss at front has no wall underneath, there is a wall framed and laying on the floor, but it is not installed. RECHECK AT ROUGH IN
B101 02	3/05/08 3/05/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001572114 WILL BE FOR PIER FOOTINGS. 200 amp service with nothing attached to it. Need final use of this service in place for inspection.
R425 01	3/25/08 3/25/08	MR DA	FOUR TRADE ROUGH IN VRU #: 001581853 1. load pt missed under wall along stairway 2. rough pl and elect ok 3. garage anchors missing 4.ok to side and insul.
I129 02	4/08/08 4/08/08	KS AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001589670
R427 01	4/08/08 4/08/08	KS AP	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001589662
I129 01	4/09/08 4/09/08	KS CA	R*INSULATION INSPECTION VRU #: 001589654 done yesterday

ADDRESS : 190 GREEN LEVEL DR
CONTRACTOR : RAYNOR BUILDERS INC
OWNER : KINSEY PAUL JR & LISA #46
PARCEL : 04-0663- - -0029- - -
APPL NUMBER: 07-50018545 CP NEW RESIDENTIAL (SFD)

SUBDIV: NEILLS CREEK FARMS PHASE 1
PHONE : (919) 639-3012
PHONE : 3

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	4/16/08 4/16/08	BM AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001595511
R431 01	5/27/08 5/27/08	BS DA	FOUR TRADE FINAL >2500 VRU #: 001614775 1. Wiring to unit in basement is undersized. 2. Need a splash guard at basement floordrain. 3. Need a set of plans at job for final. Want to check beam support in attic.
R431 02	5/28/08 <u>5-28-08</u>	TI <u>ARBS</u>	FOUR TRADE FINAL >2500 VRU #: 001615772

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Type of Construction: II

Owner of Building: Paul & Melissa Kinsey

Building Address: 190 Green Level Dr.

Zoning District: _____

Zoning Permit No.: N/A

Date: 5-28-08

Bud Smith

Building Official

Conditional Use Permit No.: _____

Building Permit No.: _____

Electrical Permit No.: _____

Insulation Permit No.: _____

Plumbing Permit No.: 1.5

Mech. Permit No.: 0

Envir. C.O. No.: _____

Zoning Official