Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: 67.500 - 18897

Applicant:

Address:

Date Evaluated: 11-27-07

Proposed Facility: SFD

Design Flow (.1949): 360

Property Size: .611 ac

Location of Site: 1125

Property Recorded:

Water Supply: [X] Public [ ] Individual [ ] Well [ ] Spring [ ] Other

Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut

Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
	S	0-28	GR SL	VFR SE					
		28-38	SBK SCL	FR SE					.5
	4%								
		0-28	GR SL	VFR SE					
		28-38	SBK SCL	FR SE					.5
		0-28	GR SL	VFR SE					
		28-38	SBK SCL	FR SE					.5
		0-24	GR SL	VFR SE					
		24-30	SBK SCL	FR SE					
		30-38	SBK SC	FI SE					.4
		0-30	GR SL	VFR SE					.6

Description	Initial System	Repair System
Available Space (.1945)	/	/
System Type(s)	25%	25%
Site LTAR	.4	.4

Other Factors (.1946):

Site Classification (.1948): PI

Evaluated By: [illegible]

Others Present: