Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:
Address:
Proposed Facility: 3 BEDROOM HOUSE
Location of Site:

Applicant:
Date Evaluated: 2/4/08
Design Flow (.1949): 360 gpd
Property Size:
Property Recorded:

Water Supply: [X] Public [ ] Individual [ ] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	OTHER PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapric Class	.1944 Restr Horiz	Profile Class & LTAR
1	L 2-5%	0-15	GSL	VFR NS/NP					PS .4
		15-34"	SBK SCL	FR SS/SP	10YR 7/2 @ 34"				
2		0-21	G SL	VFR NS/NP					PS .4
		21-40"	SBK SCL	FR SS/SP	10YR 7/2 @ 36"				

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	ACC.	LPP
Site LTAR	.4	.2

Other Factors (.1946):
Site Classification (.1948): PS
Evaluated By: OT
Others Present:

4 x 70' @ 18-28"