

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: _____ Occupancy: ✓

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: Lance & Allison DeLong

Address: 3730 McLean Chapel Church Rd

Date: 10-25-11

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

Building Official: James T. Hill

08-50019283

ADDRESS . : 3730 MCLEAN CHAPEL CHURCH RD SUBDIV:
 CONTRACTOR : TOM SPILLER & SON BUILDERS INC PHONE : (910) 484-2789
 OWNER . . : DELONG LANCE & ALLISON PHONE : (910) 237-4613
 PARCEL . . : 12-0546- - -0060- -14-
 APPL NUMBER: 08-50019283 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : HWY 401 S THUR BUNNLEVEL TURN RIGHT ON
 MCLEAN CHAPEL CHURCH RD FOR 5 MILES
 PROPERTY IS ON RIGHT MARKED W/ SURVEYOR
 TAPES & HARNETT COUNTY BUILDING
 INSPECTIONS CENTRAL PERMITTING PROPERTY
 LINE FLAGS ACROSS THE ST FROM
 UNOCCUPIED WHITE FARM HOUSE JB

STRUCTURE: 000 000 65X85 CRAWL 4BD/3.5BA W/GAR,DECK, FIN BN

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/05/11 5/05/11	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002076167
B103 01	5/19/11 5/19/11	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 002082677 Need to remove all dirt from footing inside & outside of foundation wall & around piers for projection inspection.
B103 02	5/20/11 5/20/11	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 002083186 12" foundation walls @ porches do not have 2" projection on the inside of foundation wall. 2 piers center are not in the center 1/3 of the footings.
B103 03	6/01/11 6/01/11	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002087229 PER ENGINEER LETTER
B105 01	6/03/11 6/03/11	JH AP	R*OPEN FLOOR VRU #: 002088715 T/S: 06/03/2011 01:19 PM NTART
A814 01	6/08/11 6/20/11	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002088724 3730 mclean chapel church rd bunnlevel 28323 **note # on home and by driveway T/S: 06/20/2011 03:24 PM TWARD
E207 01	6/10/11 6/10/11	JH AP	R*ELEC TEMP SERVICE POLE VRU #: 002092195 ***T-Pole only***
R427 01	7/25/11 7/25/11	JH DA	FOUR TRADE ROUGH IN >2500 VRU #: 002113304 1)Missing roof boots for plumbing. 2)Master bed closet light wires sheathing is not in the box. 3)Fire caulk 1 1/2"pipe in spare bathroom @ top plate. 4)3' head of wateron drain line test. 5)Nail all 2ply roof truss per drawings. 5)Leak on 3" drain line under family room, chip in pipe, white strap laying on pipe @ chip.
R427 02	7/28/11 7/28/11	JH DP	FOUR TRADE ROUGH IN >2500 VRU #: 002115133 Items #4 & #5 were not corrected from previous violations. PAY \$50 RE FEE
I129 01	8/01/11 8/01/11	JH AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002116606 T/S: 07/29/2011 12:43 PM VBROWN
R427 03	8/01/11	JH	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002116598

----- CONTINUED ONTO NEXT PAGE -----

