

Sheet:  
 Property ID:  
 Lot #:  
 File #:  
 Code:

**SOIL/SITE EVALUATION  
 for ON-SITE WASTEWATER SYSTEM**

Owner: 08-500-19293

Applicant:

Address:

Chgo 7.76

Date Evaluated: 2.2.08

Proposed Facility: SFD

Design Flow (.1948): ~~430~~

Property Size:

Location of Site: 1125

Property Recorded:

- Water Supply:  Public     Individual     Well     Spring     Other  
 Evaluation Method:  Auger Boring     Pit     Cut  
 Type of Wastewater:  Sewage     Industrial Process     Mixed

P R O F I L E #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapru Class	.1944 Restr Horiz	
S S/L		0-30	GML	Vh SE					.5  .5  .5  .5  J
		30-38	SM SCL	FR SE					
		0-30	GML	Vh SE					
		30-38	SM SCL	FR SE					
		0-30	GML	Vh SE					
		30-38	SM SCL	FR SE					
		0-30	GML	Vh SE					
		30-38	SM SCL	FR SE					
		0-30	GML	Vh SE					
		30-38	SM SCL	FR SE					
		0-30	GML	Vh SE					
		30-38	SM SCL	FR SE					

Description	Initial System	Repair System
Available Space (.1945)	—	—
System Type(s)	25%	LT 25%
Site LTAR	.5	.5

Other Factors (.1946): \_\_\_\_\_  
 Site Classification (.1948): P1  
 Evaluated By: g.w.l.  
 Others Present: . . . . .