

Sheet:
 Property ID:
 Lot #:
 File #:
 Code:

**SOIL/SITE EVALUATION
 for ON-SITE WASTEWATER SYSTEM**

Owner: 08500-19294

Applicant:

Address:

Proposed Facility: SFD

Design Flow (.1949): 480

Date Evaluated: 2-25-08

Location of Site: 1125

Property Size: 34ac

Water Supply: Public Individual

Property Recorded:

Evaluation Method: Auger Boring Well

Spring Other

Type of Wastewater: Sewage Pit Industrial Process

Cut Mixed

P R O F I L E #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR	
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapra Class	.1944 Restr Horiz		
S 42/10		020	GR SL	VFA	SE					
		3-38	SDM SCL	FR	SE					5
		023	GR SL	VFA	SE					
		3-38	SDM SCL	FR	SE					5
		020	GR SL	VFA	SE					
		3-28	SDM SCL	FR	SE					5
		024	GR SL	VFA	SE					
		2-38	SDM SCL	FR	SE					5
		024	GR SL	VFA	SE					
		2-38	SDM SCL	FR	SE					5
		024	GR SL	VFA	SE					
		2-38	SDM SCL	FR	SE					5

Description	Initial System	Repair System
Available Space (.1945)	—	—
System Type(s)	25%	25%
LTAR	5	-5

Other Factors (.1946): _____
 Site Classification (.1948): B5
 Evaluated By: SW
 Others Present: Holes by Tomu