Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Site
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:
Address:
Applicant:
Date Evaluated: 2/13/08
Proposed Facility: 3 BEDROOM HOME Design Flow (.1949): 360 gpd
Property Size:
Location of Site:
Property Recorded:
Water Supply: [X] Public [ ] Individual [ ] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1	L 2-5%	0-30"	G LS	VFR NS/NP	5Y 5/1 @ 4"				US
2		0-15"	G LS	VFR NS/NP					
		15-48"	SBK SCL	FR S/SP					PS .4
3		0-15"	G LS	VFR NS/NP					
		15-48"	SBK SCL	FR SS/SP					PS .4

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	PUMP TO PANEL BLOCK	PUMP TO PANEL BLOCK
Site LTAR	.4	.4

Other Factors (.1946):
Site Classification (.1948): PS
Evaluated By: OT
Others Present: —

3x50' @ = REPAIR MANATEE