
ADDRESS . . : 166 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER . . . : STANCIL BUILDERS INC
PARCEL . . . : 03-9597- - -0225- - -
APPL NUMBER: 08-50019876 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : PATTONS POINT II #119
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/17/2008 02:46 PM VBROWN -----

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE : (919) 639-2073

STRUCTURE: 000 000 40X60 3BDR 2BATH SFD
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/16/09 <u>4-16-9</u>	TI <u>AP-MR</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001755791

----- COMMENTS AND NOTES -----

ADDRESS . . : 166 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER . . . : STANCIL BUILDERS INC
PARCEL . . . : 03-9597- - -0225- - -
APPL NUMBER: 08-50019876 CP NEW RESIDENTIAL (SFD)

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE : (919) 639-2073

DIRECTIONS : PATTONS POINT II #119
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/17/2008 02:46 PM VBROWN ----

STRUCTURE: 000 000 40X60 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW SEPTIC

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/16/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001755791
	4/16/09	AP	
B103 01	5/06/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001764335
	<u>5-6-9</u>	<u>AP MR</u>	

COMMENTS AND NOTES

ADDRESS : 166 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- - -
APPL NUMBER: 08-50019876 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : PATTONS POINT II #119
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/17/2008 02:46 PM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE : (919) 639-2073

STRUCTURE: 000 000 40X60 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW SEPTIC

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/16/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001755791
	4/16/09	AP	
B103 01	5/06/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001764335
	5/06/09	AP	
B105 01	5/26/09	TI	R*OPEN FLOOR VRU #: 001771746
	<u>5-26-09</u>	<u>AP-MR</u>	

----- COMMENTS AND NOTES -----

919-353-0370

ADDRESS : 166 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- - -
APPL NUMBER: 08-50019876 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : PATTONS POINT II #119
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/17/2008 02:46 PM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE : (919) 639-2073

STRUCTURE: 000 000 40X60 3BDR 2BATH SFD
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/16/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001755791
	4/16/09	AP	
B103 01	5/06/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001764335
	5/06/09	AP	
B105 01	5/26/09	MR	R*OPEN FLOOR VRU #: 001771746
	5/26/09	AP	
A814 01	6/05/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001777390
R425 01	6/05/09	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001777382
	<u>6-5-9</u>	<u>DA-MR</u>	

----- COMMENTS AND NOTES -----

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DO NOT REMOVE

DATE: 06-05-09

PERMIT# 08-50019877

ADDRESS: 150 true blue

VIOLATIONS:

1. Install flashing at front door for porch and under front door
2. Remove low volt wire from fireplace switch box.. no low and high allowed in same box
3. Tempered window required by back door
4. All grounds in a box must be tied together
5. Buchannan connector missing on ground in kitchen
6. No mixing voltages at fireplace

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

ADDRESS : 166 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- - -
APPL NUMBER: 08-50019876 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : PATTONS POINT II #119
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/17/2008 02:46 PM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE : (919) 639-2073

STRUCTURE: 000 000 40X60 3BDR 2BATH SFD
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/16/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001755791
	4/16/09	AP	
B103 01	5/06/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001764335
	5/06/09	AP	
B105 01	5/26/09	MR	R*OPEN FLOOR VRU #: 001771746
	5/26/09	AP	
A814 01	6/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001777390
	6/08/09	AP	166 true blue dr lot 119 broadway 27505
R425 01	6/05/09	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001777382
	6/05/09	DA	install flashing at front door and porch remove low volt wire from hi volt box at fireplace tempered window needed next to back door all grounds must be tied together crimp connector missing at kitchen sw.
R425 02	6/10/09	TI	FOUR TRADE ROUGH IN VRU #: 001779310
	6/10-9	AP-MR	VOICE MESSAGE LEFT

COMMENTS AND NOTES

ADDRESS : 166 TRUE BLUE DR
 CONTRACTOR : STANCIL BUILDERS INC.
 OWNER : STANCIL BUILDERS INC
 PARCEL : 03-9597- - -0225- - -
 APPL NUMBER: 08-50019876 CP NEW RESIDENTIAL (SFD)

SUBDIV: PATTONS POINT PH 2 73LOTS
 PHONE : (919) 639-2073
 PHONE : (919) 639-2073

DIRECTIONS : PATTONS POINT II #119
 27W, LEFT ON DOCS RD, RIGHT ON MICRO
 TOWER RD, SUB DIV ON RIGHT.
 T/S: 04/17/2008 02:46 PM VBROWN ----

STRUCTURE: 000 000 40X60 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/16/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001755791
	4/16/09	AP	
B103 01	5/06/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001764335
	5/06/09	AP	
B105 01	5/26/09	MR	R*OPEN FLOOR VRU #: 001771746
	5/26/09	AP	
A814 01	6/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001777390
	6/08/09	AP	166 true blue dr lot 119 broadway 27505
R425 01	6/05/09	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001777382
	6/05/09	DA	1. install flashing at front door and porch 2. remove low volt wire from hi volt box at fireplace 3. tempered window needed next to back door 4. all grounds must be tied together 5. crimp connector missing at kitchen sw.
R425 02	6/10/09	MR	FOUR TRADE ROUGH IN VRU #: 001779310
	6/10/09	AP	VOICE MESSAGE LEFT
I129 01	6/11/09	TI	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001780501

6-11-09 AP-MR

COMMENTS AND NOTES

ADDRESS : 166 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- - -
APPL NUMBER: 08-50019876 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : PATTONS POINT II #119
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/17/2008 02:46 PM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE : (919) 639-2073

STRUCTURE: 000 000 40X60 3BDR 2BATH SFD
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/16/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001755791
	4/16/09	AP	
B103 01	5/06/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001764335
	5/06/09	AP	
B105 01	5/26/09	MR	R*OPEN FLOOR VRU #: 001771746
	5/26/09	AP	
A814 01	6/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001777390
	6/08/09	AP	✓ 166 true blue dr lot 119 broadway 27505
R425 01	6/05/09	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001777382
	6/05/09	DA	1. install flashing at front door and porch 2. remove low volt wire from hi volt box at fireplace 3. tempered window needed next to back door 4. all grounds must be tied together 5. crimp connector missing at kitchen sw.
R425 02	6/10/09	MR	FOUR TRADE ROUGH IN VRU #: 001779310
	6/10/09	AP	VOICE MESSAGE LEFT
I129 02	6/11/09	TI	R*INSULATION INSPECTION VRU #: 001780086
	<u>7-31-9</u>	<u>CA-MR</u>	
I129 01	6/11/09	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001780501
	6/11/09	AP	
H824 01	7/06/09	JW	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001791144
	7/06/09	AP	T/S: 07/07/2009 11:04 AM SSTEWARD ----- T/S: 07/07/2009 11:04 AM SSTEWARD -----
R429 01	7/31/09	TI	FOUR TRADE FINAL VRU #: 001801973
	<u>7-31-9</u>	<u>DP-MR</u>	

----- COMMENTS AND NOTES -----

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DO NOT REMOVE

DATE: 07-31-09

PERMIT # 08-50019876

ADDRESS: 166 true blue

VIOLATIONS:

1. Receptacles required on both porches
2. # 8 al is not permitted for a 40 amp range outlet
3. Install a intersystem bonding termination at panel
4. Install a blank plate at panel to seal up at breakers

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

ADDRESS : 166 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- - -
APPL NUMBER: 08-50019876 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : PATTONS POINT II #119
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/17/2008 02:46 PM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE : (919) 639-2073

STRUCTURE: 000 000 40X60 3BDR 2BATH SFD
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/16/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001755791
	4/16/09	AP	
B103 01	5/06/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001764335
	5/06/09	AP	
B105 01	5/26/09	MR	R*OPEN FLOOR VRU #: 001771746
	5/26/09	AP	
A814 01	6/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001777390
	6/08/09	AP	✓ 166 true blue dr lot 119 broadway 27505
R425 01	6/05/09	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001777382
	6/05/09	DA	1. install flashing at front door and porch 2. remove low volt wire from hi volt box at fireplace 3. tempered window needed next to back door 4. all grounds must be tied together 5. crimp connector missing at kitchen sw.
R425 02	6/10/09	MR	FOUR TRADE ROUGH IN VRU #: 001779310
	6/10/09	AP	VOICE MESSAGE LEFT
I129 02	6/11/09	MR	R*INSULATION INSPECTION VRU #: 001780086
	7/31/09	CA	T/S: 07/31/2009 10:40 AM MREARIC ----- ok
I129 01	6/11/09	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001780501
	6/11/09	AP	
H824 01	7/06/09	JW	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001791144
	7/06/09	AP	T/S: 07/07/2009 11:04 AM S STEWART ----- T/S: 07/07/2009 11:04 AM S STEWART -----
R429 01	7/31/09	MR	FOUR TRADE FINAL VRU #: 001801973
	7/31/09	DP	T/S: 07/31/2009 10:42 AM MREARIC ----- 1. receipt req,d on both porches 2. #8 al no permitted for range 3. install an intersystem bonding terminal 4. install blank plates in panel
R429 02	8/05/09	TI	FOUR TRADE FINAL VRU #: 001804798

8-5-9 AP MR

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: R-3

Type of Construction: #

Owner of Building: Stancil Bldgs

Building Address: 166 True Blue

Zoning District: _____

Zoning Permit No.: _____

Conditional Use Permit No.: _____

Building Permit No.: 08-SC-19876

Electrical Permit No.: 11

Insulation Permit No.: 11

Plumbing Permit No.: 11

Mech. Permit No.: _____

Envir. C.O. No.: _____

Date: 8-5-9
G. Michael Rearin

Building Official

Zoning Official