

ADDRESS : 16 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- -73-
APPL NUMBER: 08-50019885 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : PATTONS POINT II #194 SUB DIV.
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/18/2008 10:04 AM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE :

STRUCTURE: 000 000 40X40 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC
PROPOSED USE : SFD
WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/15/09 <i>[Signature]</i>	TI <i>[Signature]</i>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001794017

COMMENTS AND NOTES

[Large handwritten signature]

ADDRESS : 16 TRUE BLUE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- -73-
APPL NUMBER: 08-50019885 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : PATTONS POINT II #194 SUB DIV.
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/18/2008 10:04 AM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE :

STRUCTURE: 000 000 40X40 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC
PROPOSED USE : SFD
WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/15/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001794017
	7/15/09	AP	T/S: 07/15/2009 03:41 PM FSPIVEY -----
B103 01	7/31/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001802927
	<u>2319</u>	<u>AP-MR</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 16 JUMPMaster DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- -73-
APPL NUMBER: 08-50019885 CP NEW RESIDENTIAL (SFD)

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE :

DIRECTIONS : PATTONS POINT II #194 SUB DIV.
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/18/2008 10:04 AM VBROWN ----

STRUCTURE: 000 000 40X40 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD

WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/15/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001794017
	7/15/09	AP	T/S: 07/15/2009 03:41 PM FSPIVEY -----
B103 01	7/31/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001802927
	7/31/09	AP	T/S: 07/31/2009 10:44 AM MREARIC -----
A814 01	8/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001802936
	8/12/09	AP	16 jumpmaster dr ----- broadway 27505 T/S: 08/12/2009 12:48 PM TWARD -----
B105 01	8/19/09	TI	R*OPEN FLOOR VRU #: 001810641

8-19-09 AP-MR

----- COMMENTS AND NOTES -----

Harnett County

INSPECTOR: IVR

DATE 9/01/09

ADDRESS : 16 JUMPMASER DR
 CONTRACTOR : STANCIL BUILDERS INC.
 OWNER : STANCIL BUILDERS INC
 PARCEL : 03-9597- - -0225- -73-
 APPL NUMBER: 08-50019885 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : PATTONS POINT II #194 SUB DIV.
 27W, LEFT ON DOCS RD, RIGHT ON MICRO
 TOWER RD, SUB DIV ON RIGHT.
 T/S: 04/18/2008 10:04 AM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
 PHONE : (919) 639-2073
 PHONE :

STRUCTURE: 000 000 40X40 3BDR 2BATH SFD
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD
 WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/15/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001794017
	7/15/09	AP	T/S: 07/15/2009 03:41 PM FSPIVEY -----
B103 01	7/31/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001802927
	7/31/09	AP	T/S: 07/31/2009 10:44 AM MREARIC -----
A814 01	8/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001802936
	8/12/09	AP	16 jumpmaster dr ----- broadway 27505 T/S: 08/12/2009 12:48 PM TWARD -----
B105 01	8/19/09	MR	R*OPEN FLOOR VRU #: 001810641
	8/19/09	AP	T/S: 08/19/2009 10:36 AM MREARIC -----
R425 01	9/01/09	TI	FOUR TRADE ROUGH IN VRU #: 001815511

9-1-9 DA-MR

----- COMMENTS AND NOTES -----

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DO NOT REMOVE

DATE: 09-01-09

PERMIT # 08-50019885

ADDRESS: 16 jumpmaster

VIOLATIONS:

1. Nuts missing in garage
2. Boot missing on roof
3. Ok to side and insul.

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

ADDRESS : 16 JUMPMASER DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 03-9597- - -0225- -73-
APPL NUMBER: 08-50019885 CP NEW RESIDENTIAL (SFD)

SUBDIV: PATTONS POINT PH 2 73LOTS
PHONE : (919) 639-2073
PHONE :

DIRECTIONS : PATTONS POINT II #194 SUB DIV.
27W, LEFT ON DOCS RD, RIGHT ON MICRO
TOWER RD, SUB DIV ON RIGHT.
T/S: 04/18/2008 10:04 AM VBROWN ----

STRUCTURE: 000 000 40X40 3BDR 2BATH SFD
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD
WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/15/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001794017
	7/15/09	AP	T/S: 07/15/2009 03:41 PM FSPIVEY -----
B103 01	7/31/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001802927
	7/31/09	AP	T/S: 07/31/2009 10:44 AM MREARIC -----
A814 01	8/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001802936
	8/12/09	AP	16 jumpmaster dr ----- broadway 27505 T/S: 08/12/2009 12:48 PM TWARD -----
B105 01	8/19/09	MR	R*OPEN FLOOR VRU #: 001810641
	8/19/09	AP	T/S: 08/19/2009 10:36 AM MREARIC -----
R425 01	9/01/09	MR	FOUR TRADE ROUGH IN VRU #: 001815511
	9/01/09	DA	T/S: 09/01/2009 09:17 AM MREARIC ----- garage bolts are not complete boot missing on roof ok to side and insulate
I129 01	9/03/09	TI	R*INSULATION INSPECTION VRU #: 001816645
	<u>9-3-9</u>	<u>AP-MR</u>	
R425 02	9/03/09	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001816982
	<u>9-3-9</u>	<u>AP-MR</u>	T/S: 09/02/2009 02:30 PM NTART -----

----- COMMENTS AND NOTES -----

Harnett County

INSPECTOR: IVR

DATE 10/08/09

ADDRESS : 16 JUMPMaster DR
 CONTRACTOR : STANCIL BUILDERS INC.
 OWNER : STANCIL BUILDERS INC
 PARCEL : 03-9597- - -0225- -73-
 APPL NUMBER: 08-50019885 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : PATTONS POINT II #194 SUB DIV.
 27W, LEFT ON DOCS RD, RIGHT ON MICRO
 TOWER RD, SUB DIV ON RIGHT.
 T/S: 04/18/2008 10:04 AM VBROWN -----

SUBDIV: PATTONS POINT PH 2 73LOTS
 PHONE : (919) 639-2073
 PHONE :

STRUCTURE: 000 000 40X40 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD
 WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/15/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001794017
	7/15/09	AP	T/S: 07/15/2009 03:41 PM FSPIVEY -----
B103 01	7/31/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001802927
	7/31/09	AP	T/S: 07/31/2009 10:44 AM MREARIC -----
A814 01	8/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001802936
	8/12/09	AP	✓ 16 jumpmaster dr ----- roadway 27505 T/S: 08/12/2009 12:48 PM TWARD -----
B105 01	8/19/09	MR	R*OPEN FLOOR VRU #: 001810641
	8/19/09	AP	T/S: 08/19/2009 10:36 AM MREARIC -----
R425 01	9/01/09	MR	FOUR TRADE ROUGH IN VRU #: 001815511
	9/01/09	DA	T/S: 09/01/2009 09:17 AM MREARIC ----- garage bolts are not complete boot missing on roof ok to side and insulate
I129 01	9/03/09	MR	R*INSULATION INSPECTION VRU #: 001816645
	9/03/09	AP	T/S: 09/03/2009 11:05 AM MREARIC -----
R425 02	9/03/09	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001816982
	9/03/09	AP	T/S: 09/02/2009 02:30 PM NTART ----- T/S: 09/03/2009 11:05 AM MREARIC -----
H824 01	9/22/09	JW	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001826486
	9/22/09	AP	T/S: 09/23/2009 09:53 AM SSTEWARD ----- T/S: 09/23/2009 09:53 AM SSTEWARD -----
R429 01	10/08/09	TI	FOUR TRADE FINAL VRU #: 001832743

IG-B-9 DP-MR

----- COMMENTS AND NOTES -----

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DO NOT REMOVE

DATE: 10-08-09

PERMIT # 08-50019885

ADDRESS: 16 jumpmaster

VIOLATIONS:

1. Openings in panel must be closed
2. Outlet needed accessible from grade at rear of house
3. Install intersystem bonding terminal
4. The dryer vent duct must be smooth duct ... no corrugated duct

Bonus Room is unfinished

Harnett County Building Department

Mike Rearic cell# (910) 984-4772

ADDRESS : 16 JUMPMASER DR
 CONTRACTOR : STANCIL BUILDERS INC.
 OWNER : STANCIL BUILDERS INC
 PARCEL : 03-9597- - -0225- -73-
 APPL NUMBER: 08-50019885 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : PATTONS POINT II #194 SUB DIV.
 27W, LEFT ON DOCS RD, RIGHT ON MICRO
 TOWER RD, SUB DIV ON RIGHT.
 T/S: 04/18/2008 10:04 AM VBROWN ----

SUBDIV: PATTONS POINT PH 2 73LOTS
 PHONE : (919) 639-2073
 PHONE :

STRUCTURE: 000 000 40X40 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD
 WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/15/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001794017
	7/15/09	AP	T/S: 07/15/2009 03:41 PM FSPIVEY -----
B103 01	7/31/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001802927
	7/31/09	AP	T/S: 07/31/2009 10:44 AM MREARIC -----
A814 01	8/05/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001802936
	8/12/09	AP	✓ 16 jumpmaster dr ----- roadway 27505 T/S: 08/12/2009 12:48 PM TWARD -----
B105 01	8/19/09	MR	R*OPEN FLOOR VRU #: 001810641
	8/19/09	AP	T/S: 08/19/2009 10:36 AM MREARIC -----
R425 01	9/01/09	MR	FOUR TRADE ROUGH IN VRU #: 001815511
	9/01/09	DA	T/S: 09/01/2009 09:17 AM MREARIC ----- garage bolts are not complete boot missing on roof ok to side and insulate
I129 01	9/03/09	MR	R*INSULATION INSPECTION VRU #: 001816645
	9/03/09	AP	T/S: 09/03/2009 11:05 AM MREARIC -----
R425 02	9/03/09	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001816982
	9/03/09	AP	T/S: 09/02/2009 02:30 PM NTART ----- T/S: 09/03/2009 11:05 AM MREARIC -----
H824 01	9/22/09	JW	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001826486
	9/22/09	AP	T/S: 09/23/2009 09:53 AM SSTEWARD ----- T/S: 09/23/2009 09:53 AM SSTEWARD -----
R429 01	10/08/09	MR	FOUR TRADE FINAL VRU #: 001832743
	10/08/09	DP	T/S: 10/08/2009 09:11 AM MREARIC ----- 1. openings in panel must be closed 2. outlet accessible from grade needed at rear 3. install intersystem bonding terminal 4. the dryer vent duct must be smooth, not corrugated 5. NOTE...bonus room is not finished at this time
R429 02	10/09/09	TI	FOUR TRADE FINAL VRU #: 001833672

10-99 AP-MR

COMMENTS AND NOTES

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: R-3

Conditional Use Permit No.: _____

Type of Construction: F

Building Permit No.: 08-50019885

Owner of Building: Stancil

Electrical Permit No.: "

Building Address: 16 Jumpmaster

Insulation Permit No.: "

Zoning District: _____

Plumbing Permit No.: _____

Zoning Permit No.: _____

Mech. Permit No.: _____

Date: 10-9-9

Envir. C.O. No.: _____

T. Michael Rearn

Building Official

Zoning Official