Department of Environment, Fleatin, and Hattiral Nessearces

Division of Environmental Health

On-site Wastewater Section

Property ID:

Lot #:

File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:

Applicant:

15939

Address:

Design Flow (.1949): 360

Date Evaluated: 5-13-08

Property Size:

Proposed Facility: Location of Site:

Property Recorded:

Water Supply:

[] Individual

[] Well

[] Spring

[] Other

Evaluation Method:

[| Auger Boring

[] Pit

[] Cut

Type of Wastewater:

[| Sewage

[] Industrial Process

[] Mixed

P R O F	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS			
1 1 1 1 #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Wetness/	1943 1956 Soil Sapro Depth (IN.) Class	Restr	Profile Class
1	L 6%	36-48	5L SCL	FR GRNSNP Fren / FBIESTSP	46"7.586			.5
2,	Lee	0-24	SL SCL	FRE GRASSIC	42 tr 7.5 gas.			. 45
	1.00	de escrete mas a		å .				

Description	Initial System	Repair System		
Available Space (.1945)				
System Type(s)	25%	2623		
Site LTAR	.5	. 48		

Other Factors (.1946):

Site Classification (.1948):

Evaluated By

Others Present:

Department of Environment, Fleatin, and Hattiral Nessearces

Division of Environmental Health

On-site Wastewater Section

Property ID:

Lot #:

File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:

Applicant:

15939

Address:

Design Flow (.1949): 360

Date Evaluated: 5-13-08

Property Size:

Proposed Facility: Location of Site:

Property Recorded:

Water Supply:

[] Individual

[] Well

[] Spring

[] Other

Evaluation Method:

[| Auger Boring

[] Pit

[] Cut

Type of Wastewater:

[| Sewage

[] Industrial Process

[] Mixed

P R O F	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS			
1 1 1 1 #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Wetness/	1943 1956 Soil Sapro Depth (IN.) Class	Restr	Profile Class
1	L 6%	36-48	5L SCL	FR GRNSNP Fren / FBIESTSP	46"7.586			.5
2,	Lee	0-24	SL SCL	FRE GRASSIC	42 tr 7.5 gas.			. 45
	1.00	de escrete mas a		å .				

Description	Initial System	Repair System		
Available Space (.1945)				
System Type(s)	25%	2623		
Site LTAR	.5	. 48		

Other Factors (.1946):

Site Classification (.1948):

Evaluated By

Others Present:



PLOT PLAN FOR COMFORT HOMES BLACK RIVER TOWNSHIP HARNETT COUNTY NORTH CAROLINA

SITE PLAN APPROVAL DISTRICT RASO USE S #BEDROOMS

> PLAN 1930 "COURTNE OVERALL 55.67 X 32.6

LOT 20 OF STETSON SUBDIVISION. P NUMBER 2008 PGS. 193-196.

DHPUTED BY COORDINATE METHOD.

S CONTROL MONUMENT WITHIN 2000'.

D BE SERVED BY HARNETT COUNTY VIDUAL SEPTIC SYSTEMS.

RFACE COVERAGE DUSE & GARAGE LK & STEPS VAVAVIS FT. - PROPOSED COVERAGE LLOWABLE COVERAGE AVAILABLE COVERAGE

'ERTY IS SUBJECT TO RESTRICTIONS OF RECORD.

T- NOT FOR RECORDATION. R SALES.

PEARCE & ASSOC., P.A.

892 1. C.

3-9605

