

Property ID:  
 Lot #:  
 File #:  
 Code:

**SOIL/SITE EVALUATION  
 for ON-SITE WASTEWATER SYSTEM**

Owner: 08-500-25776

Applicant:

Address:

Date Evaluated: 8-26-04

Proposed Facility: SFD

Design Flow (.1949): 480

Property Size: 8.61a

Location of Site: 1272

Property Recorded: W

Water Supply:  Public  Individual  Well

Spring  Other

Evaluation Method:  Auger Boring  Pit

Cut

Type of Wastewater:  Sewage  Industrial Process

Mixed

P R O F I L E #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr. Horiz.	
304 S		D34	GR SL	VFA SF					.6
		O70	GR SL	VFA SF					.6
		D30	GR SL	VFA SF					.6
		O20	GR SL	VFA SF					.5
		30-30	SM SL	VFA SF					.5
		O20	GR SL	VFA SF					.5
		30-30	SM SL	VFA SF					.5
		O20	GR SL	VFA SF					.6

Description	Initial System	Repair System
Available Space (.1945)		
System Type(s)	20"	45"
Site LTAR	.5	.5

Other Factors (.1946): \_\_\_\_\_

Site Classification (.1948): D

Evaluated By: G

Others Present: S