

Property ID:  
 Lot #:  
 File #:  
 Code:

**SOIL/SITE EVALUATION  
 for ON-SITE WASTEWATER SYSTEM**

Owner: 08500 20871

Applicant:

Address:

Date Evaluated:

Proposed Facility: SFD  
 Location of Site: Tigrum

Design Flow (.1949): 760

Property Size: .275

Property Recorded:

Water Supply:  Public  Individual  Well  Spring  Other  
 Evaluation Method:  Auger Boring  Pit  Cut  
 Type of Wastewater:  Sewage  Industrial Process  Mixed

P R O F I L E #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
S 27		0-38 GR JL	VFA	SE					C
		0-30 GR JL	VFA	SE					C
		0-30 GR JL	VFA	SE					C
		0-28 SDK SCL	VFA	SE					
		28-38 SDK SCL	FR	SE					5
		0-28 GR JL	VFA	SE					
		28-38 SDK SCL	FR	SE					5

Description	Initial System	Repair System
Available Space (.1945)		
System Type(s)	257	267
Site LTAR	15	5

Other Factors (.1946): \_\_\_\_\_  
 Site Classification (.1948): P1  
 Evaluated By: GW  
 Others Present: