
ADDRESS . . : 55 JAYLIN BLVD
CONTRACTOR : FAMILY HOME CONSTRUCTION
OWNER . . . : JS PROPERTIES #10
PARCEL . . . : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --

DATE
SUBDIV: JAYLIN OAKS
PHONE : (910) 321-1002
PHONE : (910) 551-4736

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 <i>9-7-10</i>	TI <i>AP JK</i>	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE <i>No Free</i> ----- COMMENTS AND NOTES -----

ADDRESS . : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
OWNER . . : JS PROPERTIES #10 PHONE : (910) 551-4736
PARCEL . . : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE ----- no t-pole -----
B103 01	9/13/10 9/13/10	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible -----
B105 01	9/16/10 9/16/10	JH AP	R*OPEN FLOOR VRU #: 001982826 READY FOR OPEN FLOOR INSPECTION, A.M. IF POSSIBLE. -----
B104 01	9/24/10 9/23/10	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001986736 Inspection on lug footing in the garage T/S: 09/23/2010 02:23 PM NTART -----
B101 02	9/24/10 <i>9-24-10</i>	TI <i>DA JH</i>	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001986801 T/S: 09/23/2010 02:23 PM NTART ----- WILL BE AN INSPECTION FOR THE LUG FOOTING IN THE GARAGE.

*No Engineer letter for laundry room
footing in garage*

PREPARED 9/10/10, 14:02:02
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 1
DATE 9/13/10

ADDRESS . . : 55 JAYLIN BLVD
CONTRACTOR : FAMILY HOME CONSTRUCTION
OWNER . . . : JS PROPERTIES #10
PARCEL . . . : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --

SUBDIV: JAYLIN OAKS
PHONE : (910) 321-1002
PHONE : (910) 551-4736

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE ----- no t-pole -----
B103 01	9/13/10 <u>9-13-10</u>	TI <u>APJH</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible

----- COMMENTS AND NOTES -----

ADDRESS . . : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
 CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
 OWNER . . : JS PROPERTIES #10 PHONE : (910) 551-4736
 PARCEL . . : 01-0513- - -0217- -10-
 APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE ----- no t-pole -----
B103 01	9/13/10 9/13/10	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible
B105 01	9/16/10 <i>9-16-10</i>	TI <i>APJH</i>	R*OPEN FLOOR VRU #: 001982826 READY FOR OPEN FLOOR INSPECTION, A.M. IF POSSIBLE.

----- COMMENTS AND NOTES -----


ADDRESS . . : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
OWNER . . : JS PROPERTIES #10 PHONE : (910) 551-4736
PARCEL . . : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE ----- no t-pole -----
B103 01	9/13/10 9/13/10	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible -----
B105 01	9/16/10 9/16/10	JH AP	R*OPEN FLOOR VRU #: 001982826 READY FOR OPEN FLOOR INSPECTION, A.M. IF POSSIBLE. -----
B104 01	9/24/10 9/23/10	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001986736 Inspection on lug footing in the garage T/S: 09/23/2010 02:23 PM NTART -----
B101 02	9/24/10 9/24/10	JH DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001986801 T/S: 09/23/2010 02:23 PM NTART ----- WILL BE AN INSPECTION FOR THE LUG FOOTING IN THE GARAGE. Need engineer letter for added footing for laundry room in garage & need 6 mil poly on garage slab.
B101 03	9/30/10 <i>9-30-10</i>	TI <i>AP JH</i>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001988252 ready for inspection on garage slab. a.m. if possible.

----- COMMENTS AND NOTES -----



- NOTES:
1. SECURE SOLE PLATE TO EXISTING SLAB AS PER CODE.
 2. RUN FLOOR FROM HOUSE OVER KNEE WALL FLOOR SYSTEM.
 3. PROVIDE ACCESS TO W/D CRAWL SPACE FROM GARAGE PER CODE.

ADDRESS . . : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
 CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
 OWNER . . : JS PROPERTIES #10 PHONE : (910) 551-4736
 PARCEL . . : 01-0513- - -0217- -10-
 APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE ----- no t-pole -----
B103 01	9/13/10 9/13/10	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible -----
B105 01	9/16/10 9/16/10	JH AP	R*OPEN FLOOR VRU #: 001982826 READY FOR OPEN FLOOR INSPECTION, A.M. IF POSSIBLE. -----
B104 01	9/24/10 9/23/10	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001986736 Inspection on lug footing in the garage T/S: 09/23/2010 02:23 PM NTART -----
B101 02	9/24/10 9/24/10	JH DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001986801 T/S: 09/23/2010 02:23 PM NTART ----- WILL BE AN INSPECTION FOR THE LUG FOOTING IN THE GARAGE. Need engineer letter for added footing for laundry room in garage & need 6 mil poly on garage slab.
B101 03	9/30/10 9/30/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001988252 ready for inspection on garage slab. a.m. if possible.
R427 01	10/07/10 <u>10/7/10</u>	TI <u>DADT</u>	FOUR TRADE ROUGH IN >2500 VRU #: 001990712 a.m. if possible, Thanks.

COMMENTS AND NOTES

ADDRESS . : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
OWNER . . : JS PROPERTIES #10 PHONE : (910) 551-4736
PARCEL . . : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE ----- no t-pole -----
B103 01	9/13/10 9/13/10	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible
B105 01	9/16/10 9/16/10	JH AP	R*OPEN FLOOR VRU #: 001982826 READY FOR OPEN FLOOR INSPECTION, A.M. IF POSSIBLE.
B104 01	9/24/10 9/23/10	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001986736 Inspection on lug footing in the garage T/S: 09/23/2010 02:23 PM NTART -----
B101 02	9/24/10 9/24/10	JH DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001986801 T/S: 09/23/2010 02:23 PM NTART ----- WILL BE AN INSPECTION FOR THE LUG FOOTING IN THE GARAGE. Need engineer letter for added footing for laundry room in garage & need 6 mil poly on garage slab.
B101 03	9/30/10 9/30/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001988252 ready for inspection on garage slab. a.m. if possible.
R427 01	10/07/10 10/07/10	DT DA	FOUR TRADE ROUGH IN >2500 VRU #: 001990712 a.m. if possible, Thanks. X. Need 100 psi on water line. X. Need 10 psi on gas line. 3. Need engineer repair for B gdr truss in garage. 4. B gdr not strapped for enough uplift. Okay to side and insulate. T/S: 10/07/2010 10:27 AM DETAYLOR -----
R427 02	10/12/10 10-12-10	TI Op JH	FOUR TRADE ROUGH IN >2500 VRU #: 001992460 ready for reinspect and insulation. Thanks <i>Items # 324 not corrected</i>

COMMENTS AND NOTES

ADDRESS : 55 JAYLIN BLVD
CONTRACTOR : FAMILY HOME CONSTRUCTION
OWNER : JS PROPERTIES #10
PARCEL : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --

SUBDIV: JAYLIN OAKS
PHONE : (910) 321-1002
PHONE : (910) 551-4736

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE no t-pole
B103 01	9/13/10 9/13/10	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible
B105 01	9/16/10 9/16/10	JH AP	R*OPEN FLOOR VRU #: 001982826 READY FOR OPEN FLOOR INSPECTION, A.M. IF POSSIBLE.
B104 01	9/24/10 9/23/10	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001986736 Inspection on lug footing in the garage T/S: 09/23/2010 02:23 PM NTART
B101 02	9/24/10 9/24/10	JH DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001986801 T/S: 09/23/2010 02:23 PM NTART WILL BE AN INSPECTION FOR THE LUG FOOTING IN THE GARAGE. Need engineer letter for added footing for laundry room in garage & need 6 mil poly on garage slab.
B101 03	9/30/10 9/30/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001988252 ready for inspection on garage slab. a.m. if possible.
R427 01	10/07/10 10/07/10	DT DA	FOUR TRADE ROUGH IN >2500 VRU #: 001990712 a.m. if possible, Thanks. 1. Need 100 psi on water line. 2. Need 10 psi on gas line. 3. Need engineer repair for B gdr truss in garage. 4. B gdr not strapped for enough uplift. Okay to side and insulate. T/S: 10/07/2010 10:27 AM DETAYLOR
R427 02	10/12/10 10/12/10	JH DP	FOUR TRADE ROUGH IN >2500 VRU #: 001992460 ready for reinspect and insulation. Thanks items #3&4 were not corrected from previous violations PAY \$50 RE FEE T/S: 10/13/2010 01:41 PM NTART
A814 01	10/14/10	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001994359 T/S: 10/13/2010 01:54 PM NTART

ADDRESS : 55 JAYLIN BLVD
CONTRACTOR : FAMILY HOME CONSTRUCTION
OWNER : JS PROPERTIES #10
PARCEL : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)

SUBDIV: JAYLIN OAKS
PHONE : (910) 321-1002
PHONE : (910) 551-4736

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 01	10/18/10 <i>10-18-10</i>	TI <i>APJH</i>	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001994441 T/S: 10/13/2010 02:11 PM NTART ----- T/S: 10/14/2010 08:09 AM NTART ----- T/S: 10/15/2010 10:36 AM NTART -----
R425 01	10/18/10 <i>10-18-10</i>	TI <i>APJH</i>	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001994458 T/S: 10/13/2010 02:12 PM NTART ----- T/S: 10/14/2010 08:09 AM NTART ----- T/S: 10/15/2010 10:36 AM NTART -----

----- COMMENTS AND NOTES -----

ADDRESS : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
 CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
 OWNER : JS PROPERTIES #10 PHONE : (910) 551-4736
 PARCEL : 01-0513- - -0217- -10-
 APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE ----- no t-pole -----
B103 01	9/13/10 9/13/10	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible
B105 01	9/16/10 9/16/10	JH AP	R*OPEN FLOOR VRU #: 001982826 READY FOR OPEN FLOOR INSPECTION, A.M. IF POSSIBLE.
B104 01	9/24/10 9/23/10	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001986736 Inspection on lug footing in the garage T/S: 09/23/2010 02:23 PM NTART -----
B101 02	9/24/10 9/24/10	JH DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001986801 T/S: 09/23/2010 02:23 PM NTART ----- WILL BE AN INSPECTION FOR THE LUG FOOTING IN THE GARAGE. Need engineer letter for added footing for laundry room in garage & need 6 mil poly on garage slab.
B101 03	9/30/10 9/30/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001988252 ready for inspection on garage slab. a.m. if possible.
R427 01	10/07/10 10/07/10	DT DA	FOUR TRADE ROUGH IN >2500 VRU #: 001990712 a.m. if possible, Thanks. 1. Need 100 psi on water line. 2. Need 10 psi on gas line. 3. Need engineer repair for B gdr truss in garage. 4. B gdr not strapped for enough uplift. Okay to side and insulate. T/S: 10/07/2010 10:27 AM DETAYLOR -----
R427 02	10/12/10 10/12/10	JH DP	FOUR TRADE ROUGH IN >2500 VRU #: 001992460 ready for reinspect and insulation. Thanks items #3&4 were not corrected from previous violations PAY \$50 RE FEE T/S: 10/13/2010 01:41 PM NTART -----
A814 01	10/14/10	FB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001994359

CONTINUED ONTO NEXT PAGE

ADDRESS : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
OWNER : JS PROPERTIES #10 PHONE : (910) 551-4736
PARCEL : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	10/15/10	AP	T/S: 10/13/2010 01:54 PM NTART ----- T/S: 10/15/2010 04:19 PM FBURGESS ----- 55 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 10
I129 01	10/18/10	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001994441
	10/18/10	AP	T/S: 10/13/2010 02:11 PM NTART ----- T/S: 10/14/2010 08:09 AM NTART ----- T/S: 10/15/2010 10:36 AM NTART -----
R425 01	10/18/10	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001994458
	10/18/10	AP	T/S: 10/13/2010 02:12 PM NTART ----- T/S: 10/14/2010 08:09 AM NTART ----- T/S: 10/15/2010 10:36 AM NTART -----
E207 02	10/25/10	TI	R*ELEC TEMP SERVICE POLE VRU #: 001997881
	10-25-10	AP JH	
E207 01	10/25/10	TI	R*ELEC TEMP SERVICE POLE VRU #: 001997873
	10/22/10	CA	T/S: 10/22/2010 02:03 PM NTART -----

----- COMMENTS AND NOTES -----

ADDRESS : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
 CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
 OWNER : JS PROPERTIES #10 PHONE : (910) 551-4736
 PARCEL : 01-0513- - -0217- -10-
 APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --

STRUCTURE: 000 000 80X50 3 BR NO DECKS/GARAGES/PORCHES/CRWL
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/10 9/07/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001979202 T/S: 09/03/2010 01:55 PM RDCONTE ----- no t-pole -----
B103 01	9/13/10 9/13/10	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001981372 Ready for foundation inspection, a.m. if possible
B105 01	9/16/10 9/16/10	JH AP	R*OPEN FLOOR VRU #: 001982826 READY FOR OPEN FLOOR INSPECTION, A.M. IF POSSIBLE.
B104 01	9/24/10 9/23/10	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001986736 Inspection on lug footing in the garage T/S: 09/23/2010 02:23 PM NTART -----
B101 02	9/24/10 9/24/10	JH DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001986801 T/S: 09/23/2010 02:23 PM NTART ----- WILL BE AN INSPECTION FOR THE LUG FOOTING IN THE GARAGE. Need engineer letter for added footing for laundry room in garage & need 6 mil poly on garage slab.
B101 03	9/30/10 9/30/10	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001988252 ready for inspection on garage slab. a.m. if possible.
R427 01	10/07/10 10/07/10	DT DA	FOUR TRADE ROUGH IN >2500 VRU #: 001990712 a.m. if possible, Thanks. 1. Need 100 psi on water line. 2. Need 10 psi on gas line. 3. Need engineer repair for B gdr truss in garage. 4. B gdr not strapped for enough uplift. Okay to side and insulate. T/S: 10/07/2010 10:27 AM DETAYLOR -----
R427 02	10/12/10 10/12/10	JH DP	FOUR TRADE ROUGH IN >2500 VRU #: 001992460 ready for reinspect and insulation. Thanks items #3&4 were not corrected from previous violations PAY \$50 RE FEE T/S: 10/13/2010 01:41 PM NTART -----
A814 01	10/14/10 10/15/10	FB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001994359 T/S: 10/13/2010 01:54 PM NTART -----

CONTINUED ONTO NEXT PAGE

ADDRESS : 55 JAYLIN BLVD SUBDIV: JAYLIN OAKS
CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
OWNER : JS PROPERTIES #10 PHONE : (910) 551-4736
PARCEL : 01-0513- - -0217- -10-
APPL NUMBER: 08-50020925 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 01	10/18/10 10/18/10	JH AP	T/S: 10/15/2010 04:19 PM FBURGESS ----- 55 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 10 R*INSULATION INSPECTION TIME: 17:00 VRU #: 001994441 T/S: 10/13/2010 02:11 PM NTART ----- T/S: 10/14/2010 08:09 AM NTART ----- T/S: 10/15/2010 10:36 AM NTART -----
R425 01	10/18/10 10/18/10	JH AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001994458 T/S: 10/13/2010 02:12 PM NTART ----- T/S: 10/14/2010 08:09 AM NTART ----- T/S: 10/15/2010 10:36 AM NTART -----
E207 02	10/25/10 10/25/10	JH AP	R*ELEC TEMP SERVICE POLE VRU #: 001997881 -----
E207 01	10/25/10 10/22/10	TI CA	R*ELEC TEMP SERVICE POLE VRU #: 001997873 T/S: 10/22/2010 02:03 PM NTART -----
H824 01	11/04/10 11/04/10	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002002897 T/S: 11/04/2010 09:29 AM SZIMMER ----- T/S: 11/04/2010 09:29 AM SZIMMER -----
R429 01	11/12/10 <u>11/12/10</u>	TI <u>AP DT</u>	FOUR TRADE FINAL VRU #: 002005445

----- COMMENTS AND NOTES -----

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: ___ Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Family Home Construction

Address: 55 Jayla Blvd
Spring Lake, NC 28390

Date: 11/12/10

Building Official: [Signature]

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 08-50020925

MFG Home: _____