

ADDRESS : SMITH DR  
CONTRACTOR :  
OWNER : SMITH RICKY PALMER  
PARCEL : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : 181 SMITH DRIVE ANGIER 27501, SANDY GROVE SUB DIV #9. OUT OF LILLINGTON 2MI, LEFT ON OLD BUIES CREEK RD #1542. TO ANGIER, 3MI SANDY GOVE ON LEFT, 7TH HOUSE ON LEFT.  
T/S: 09/23/2008 09:51 AM VBROWN ----

SUBDIV: SANDY GROVE  
PHONE :  
PHONE : (919) 639-6712

STRUCTURE: 000 000 18X28 1BDR 1BATH NO GAR NO DECK SFD

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 1.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : WELL

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08 <u>11-17-08</u>	TI <u>ARBS</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839

COMMENTS AND NOTES

-----  
ADDRESS : SMITH DR SUBDIV: SANDY GROVE  
CONTRACTOR : PHONE :  
OWNER : SMITH RICKY PALMER PHONE : (919) 639-6712  
PARCEL : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : 181 SMITH DRIVE ANGIER 27501, SANDY  
GROVE SUB DIV #9. OUT OF LILLINGTON  
2MI, LEFT ON OLD BUIES CREEK RD #1542.  
TO ANGIER, 3MI SANDY GOVE ON LEFT, 7TH  
HOUSE ON LEFT.  
T/S: 09/23/2008 09:51 AM VBROWN -----

-----  
STRUCTURE: 000 000 18X28 1BDR 1BATH NO GAR NO DECK SFD  
FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 1.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : WELL  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08 11/17/08	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839
A814 01	12/01/08	TI	ADDRESS CONFIRMATION VRU #: 001711001
P309 01	12/01/08 <u>12-1-08</u>	TI <u>DABS</u>	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001711019

----- COMMENTS AND NOTES -----

PREPARED 12/02/08, 11:31:37  
Harnett County

INSPECTION TICKET  
INSPECTOR: IVR

ADDRESS : SMITH DR  
CONTRACTOR :  
OWNER : SMITH RICKY PALMER  
PARCEL : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)

SUBDIV: SANDY GROVE  
PHONE :  
PHONE : (919) 639-6712

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08 11/17/08	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839
A814 01	12/01/08	TI	ADDRESS CONFIRMATION VRU #: 001711001
P309 01	12/01/08 12/01/08	BS DA	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001711019 Uncover plumbing in slab, must have a test on plumbing under slab.
P309 02	12/02/08 12/02/08	BS AP	R*PLUMB UNDER SLAB VRU #: 001711928
B103 01	12/02/08	TI	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001712512
B111 01	<u>12-2-08</u> 12/02/08	<u>APBS</u> TI	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001712520

----- COMMENTS AND NOTES -----

ADDRESS : 141 SMITH DR  
CONTRACTOR :  
OWNER : SMITH RICKY PALMER  
PARCEL : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : 181 SMITH DRIVE ANGIER 27501, SANDY GROVE SUB DIV #9. OUT OF LILLINGTON 2MI, LEFT ON OLD BUIES CREEK RD #1542. TO ANGIER, 3MI SANDY GOVE ON LEFT, 7TH HOUSE ON LEFT.  
T/S: 09/23/2008 09:51 AM VBROWN ----

SUBDIV: SANDY GROVE  
PHONE :  
PHONE : (919) 639-6712

STRUCTURE: 000 000 18X28 1BDR 1BATH NO GAR NO DECK SFD

FLOOD ZONE : FLOOD ZONE X

# BEDROOMS : 1.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW SEPTIC

WATER SUPPLY : WELL

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839
	11/17/08	AP	
A814 01	12/01/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001711001
	12/18/08	AP	141 SMITH DR CHECK FOR # BY DRIVE AND ON HOME
P309 01	12/01/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001711019
	12/01/08	DA	Uncover plumbing in slab, must have a test on plumbing under slab.
P309 02	12/02/08	BS	R*PLUMB UNDER SLAB VRU #: 001711928
	12/02/08	AP	
B103 01	12/02/08	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001712512
	12/02/08	AP	
B111 01	12/02/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001712520
	12/02/08	AP	
H824 01	2/17/09	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001735901
	2/17/09	AP	
R425 01	4/07/09	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001751734

4-7 DA

No HVNC  
COMMENTS AND NOTES

ADDRESS : 141 SMITH DR  
 CONTRACTOR :  
 OWNER : SMITH RICKY PALMER  
 PARCEL : 04-0672- - -0069- -07-  
 APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : 181 SMITH DRIVE ANGIER 27501, SANDY GROVE SUB DIV #9. OUT OF LILLINGTON 2MI, LEFT ON OLD BUIES CREEK RD #1542. TO ANGIER, 3MI SANDY GOVE ON LEFT, 7TH HOUSE ON LEFT.  
 T/S: 09/23/2008 09:51 AM VBROWN ----

SUBDIV: SANDY GROVE  
 PHONE :  
 PHONE : (919) 639-6712

**STRUCTURE: 000 000 18X28 1BDR 1BATH NO GAR NO DECK SFD**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 1.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : WELL

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839
	11/17/08	AP	
A814 01	12/01/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001711001
	12/18/08	AP	141 SMITH DR CHECK FOR # BY DRIVE AND ON HOME
P309 01	12/01/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001711019
	12/01/08	DA	Uncover plumbing in slab, must have a test on plumbing under slab.
P309 02	12/02/08	BS	R*PLUMB UNDER SLAB VRU #: 001711928
	12/02/08	AP	
B103 01	12/02/08	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001712512
	12/02/08	AP	
B111 01	12/02/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001712520
	12/02/08	AP	
H824 01	2/17/09	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001735901
	2/17/09	AP	
R425 01	4/07/09	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001751734
	4/07/09	DA	<ol style="list-style-type: none"> <li>1. Fire block between stairs stringers at the bottom.</li> <li>2. Need a receptical accessible from grade at the front and rear of house.</li> <li>3. Only one wire shall pass thru romex conector at panel.</li> <li>4. Only 2 wires per hole may pass thru top or bottom plate</li> <li>5. Cannot feed #14 wire with a #12 (receptacle at bottom of stairs and light switch.</li> <li>6. All wiring shall be fire caulked.</li> <li>7. Install dryer vent</li> <li>8. Install HVAC vents and flex.</li> <li>9. Bathroom receptacle shall be on its own circuit</li> <li>10. Kitchen shall have 2 small appliance branch circuits on countertop</li> <li>11. Need smoke detector on first floor.</li> <li>12. Need light in stair well swithced from top and bottom.</li> <li>13. Receptacle next to sliding door #12 wire shall be stapled within 12 inches of box</li> </ol> Do not insulate
R425 02	4/20/09	TI	FOUR TRADE ROUGH IN VRU #: 001757202

-----  
ADDRESS : 141 SMITH DR  
CONTRACTOR :  
OWNER . . : SMITH RICKY PALMER  
PARCEL . . : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)

SUBDIV: SANDY GROVE  
PHONE :  
PHONE : (919) 639-6712

-----  
REQUESTED INSP DESCRIPTION  
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

4-20-09 IVR

-----  
COMMENTS AND NOTES  
-----

ADDRESS : 141 SMITH DR  
CONTRACTOR :  
OWNER : SMITH RICKY PALMER  
PARCEL : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)

SUBDIV: SANDY GROVE  
PHONE :  
PHONE : (919) 639-6712

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	4/20/09	DA	1. Wiring shall be firecaulked before insulation is installed. 2. Need receptacle front and rear accessible from grade. 3. Kitchen must have 2 seperate circuits on countertop receptacles. 4. Smoke detector on first floor shall be interconnected to smoke detectors upstairs. DO NOT INSULATE. Note- heating and cooling to be wall mounted heat/cool- no ductwork
R425 03	4/22/09 4-22	TI AP	FOUR TRADE ROUGH IN VRU #: 001758135 KS

COMMENTS AND NOTES

ADDRESS . . : 141 SMITH DR  
 CONTRACTOR :  
 OWNER . . . : SMITH RICKY PALMER  
 PARCEL . . . : 04-0672- - -0069- -07-  
 APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : 181 SMITH DRIVE ANGIER 27501, SANDY  
 GROVE SUB DIV #9. OUT OF LILLINGTON  
 2MI, LEFT ON OLD BUIES CREEK RD #1542.  
 TO ANGIER, 3MI SANDY GOVE ON LEFT, 7TH  
 HOUSE ON LEFT.  
 T/S: 09/23/2008 09:51 AM VBROWN ----

SUBDIV: SANDY GROVE  
 PHONE :  
 PHONE : (919) 639-6712

**STRUCTURE: 000 000 18X28 1BDR 1BATH NO GAR NO DECK SFD**

FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . : 1.00  
 SEPTIC - EXISTING? . . . : NEW SEPTIC  
 PROPOSED USE . . . . : SFD  
 WATER SUPPLY . . . . : WELL

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839
	11/17/08	AP	
A814 01	12/01/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001711001
	12/18/08	AP	141 SMITH DR CHECK FOR # BY DRIVE AND ON HOME
P309 01	12/01/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001711019
	12/01/08	DA	Uncover plumbing in slab, must have a test on plumbing under slab.
P309 02	12/02/08	BS	R*PLUMB UNDER SLAB VRU #: 001711928
	12/02/08	AP	
B103 01	12/02/08	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001712512
	12/02/08	AP	
B111 01	12/02/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001712520
	12/02/08	AP	
H824 01	2/17/09	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001735901
	2/17/09	AP	
R425 01	4/07/09	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001751734
	4/07/09	DA	1. Fire block between stairs stringers at the bottom. 2. Need a receptical accessible from grade at the front and rear of house. 3. Only one wire shall pass thru romex conector at panel. 4. Only 2 wires per hole may pass thru top or bottom plate 5. Cannot feed #14 wire with a #12 (receptacle at bottom of stairs and light switch. 6. All wiring shall be fire caulked. 7. Install dryer vent 8. Install HVAC vents and flex. 9. Bathroom receptacle shall be on its own circuit 10. Kitchen shall have 2 small appliance branch circuits on countertop 11. Need smoke detector on first floor. 12. Need light in stair well swithced from top and bottom. 13. Receptacle next to sliding door #12 wire shall be stapled within 12 inches of box Do not insulate
R425 02	4/20/09	BS	FOUR TRADE ROUGH IN VRU #: 001757202



ADDRESS : 141 SMITH DR  
CONTRACTOR :  
OWNER : SMITH RICKY PALMER  
PARCEL : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : 181 SMITH DRIVE ANGIER 27501, SANDY  
GROVE SUB DIV #9. OUT OF LILLINGTON  
2MI, LEFT ON OLD BUIES CREEK RD #1542.  
TO ANGIER, 3MI SANDY GOVE ON LEFT, 7TH  
HOUSE ON LEFT.  
T/S: 09/23/2008 09:51 AM VBROWN ----

SUBDIV: SANDY GROVE  
PHONE :  
PHONE : (919) 639-6712

STRUCTURE: 000 000 18X28 1BDR 1BATH NO GAR NO DECK SFD

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 1.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : WELL

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839
	11/17/08	AP	
A814 01	12/01/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001711001
	12/18/08	AP	141 SMITH DR CHECK FOR # BY DRIVE AND ON HOME
P309 01	12/01/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001711019
	12/01/08	DA	Uncover plumbing in slab, must have a test on plumbing under slab.
P309 02	12/02/08	BS	R*PLUMB UNDER SLAB VRU #: 001711928
	12/02/08	AP	
B103 01	12/02/08	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001712512
	12/02/08	AP	
B111 01	12/02/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001712520
	12/02/08	AP	
H824 01	2/17/09	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001735901
	2/17/09	AP	
R425 01	4/07/09	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001751734
	4/07/09	DA	1. Fire block between stairs stringers at the bottom. 2. Need a receptical accessible from grade at the front and rear of house. 3. Only one wire shall pass thru romex conector at panel. 4. Only 2 wires per hole may pass thru top or bottom plate 5. Cannot feed #14 wire with a #12 (receptacle at bottom of stairs and light switch. 6. All wiring shall be fire caulked. 7. Install dryer vent 8. Install HVAC vents and flex. 9. Bathroom receptacle shall be on its own circuit 10. Kitchen shall have 2 small appliance branch circuits on countertop 11. Need smoke detector on first floor. 12. Need light in stair well swithced from top and bottom. 13. Receptacle next to sliding door #12 wire shall be stapled within 12 inches of box Do not insulate
R425 02	4/20/09	BS	FOUR TRADE ROUGH IN VRU #: 001757202

ADDRESS : 141 SMITH DR  
CONTRACTOR :  
OWNER : ~~SMITH~~ RICKY PALMER  
PARCEL : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)

SUBDIV: SANDY GROVE  
PHONE :  
PHONE : (919) 639-6712

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	4/20/09	DA	1. Wiring shall be firecaulked before insulation is installed. 2. Need receptacle front and rear accessible from grade. 3. Kitchen must have 2 seperate circuits on countertop receptacles. 4. Smoke detector on first floor shall be interconnected to smoke detectors upstairs. DO NOT INSULATE. Note- heating and cooling to be wall mounted heat/cool- no ductwork
R425 03	4/22/09 <u>4-22</u>	TI <u>AP</u>	FOUR TRADE ROUGH IN VRU #: 001758135
I129 01	4/24/09 <u>4-24</u>	TI <u>AP</u>	R*INSULATION INSPECTION VRU #: 001758952

----- COMMENTS AND NOTES -----

ADDRESS : 141 SMITH DR  
 CONTRACTOR :  
 OWNER : SMITH RICKY PALMER  
 PARCEL : 04-0672- - -0069- -07-  
 APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : 181 SMITH DRIVE ANGIER 27501, SANDY GROVE SUB DIV #9. OUT OF LILLINGTON 2MI, LEFT ON OLD BUIES CREEK RD #1542. TO ANGIER, 3MI SANDY GOVE ON LEFT, 7TH HOUSE ON LEFT.  
 T/S: 09/23/2008 09:51 AM VBROWN ----

STRUCTURE: 000 000 18X28 1BDR 1BATH NO GAR NO DECK SFD  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 1.00  
 SEPTIC - EXISTING? : NEW SEPTIC  
 PROPOSED USE : SFD  
 WATER SUPPLY : WELL

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839
	11/17/08	AP	
A814 01	12/01/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001711001
	12/18/08	AP	141 SMITH DR CHECK FOR # BY DRIVE AND ON HOME
P309 01	12/01/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001711019
	12/01/08	DA	Uncover plumbing in slab, must have a test on plumbing under slab.
P309 02	12/02/08	BS	R*PLUMB UNDER SLAB VRU #: 001711928
	12/02/08	AP	
B103 01	12/02/08	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001712512
	12/02/08	AP	
B111 01	12/02/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001712520
	12/02/08	AP	
H824 01	2/17/09	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001735901
	2/17/09	AP	
R425 01	4/07/09	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001751734
	4/07/09	DA	1. Fire block between stairs stringers at the bottom. 2. Need a receptical accessible from grade at the front and rear of house. 3. Only one wire shall pass thru romex conector at panel. 4. Only 2 wires per hole may pass thru top or bottom plate 5. Cannot feed #14 wire with a #12 (receptacle at bottom of stairs and light switch. 6. All wiring shall be fire caulked. 7. Install dryer vent 8. Install HVAC vents and flex. 9. Bathroom receptacle shall be on its own circuit 10. Kitchen shall have 2 small appliance branch circuits on countertop 11. Need smoke detector on first floor. 12. Need light in stair well swithced from top and bottom. 13. Receptacle next to sliding door #12 wire shall be stapled within 12 inches of box Do not insulate
R425 02	4/20/09	BS	FOUR TRADE ROUGH IN VRU #: 001757202

-----  
ADDRESS . : 141 SMITH DR SUBDIV: SANDY GROVE  
CONTRACTOR : PHONE :  
OWNER . . : SMITH RICKY PALMER PHONE : (919) 639-6712  
PARCEL . . : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)  
-----

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	4/20/09	DA	1. Wiring shall be firecaulked before insulation is installed. 2. Need receptacle front and rear accessible from grade. 3. Kitchen must have 2 seperate circuits on countertop receptacles. 4. Smoke detector on first floor shall be interconnected to smoke detectors upstairs. DO NOT INSULATE. Note- heating and cooling to be wall mounted heat/cool- no ductwork
R425 03	4/22/09	KS	FOUR TRADE ROUGH IN VRU #: 001758135
	4/22/09	AP	
I129 01	4/24/09	KS	R*INSULATION INSPECTION VRU #: 001758952
	4/24/09	AP	
R429 01	12/15/09	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 001861517
	<i>12-15-09</i>	<i>DABS</i>	T/S: 12/14/2009 10:40 AM VBROWN -----

----- COMMENTS AND NOTES -----

Application number, type . . . : 08 50020969 CP NEW RESIDENTIAL (SFD)  
Property address . . . . . : 141 SMITH DR

Type information, press Enter.

1. Must have upstairs heat installed. 2. Caulk all plumbing fixtures where they meet walls/floors. Toilets, vanities and countertops included. 3. exterior band at privacy deck must be a double. 4. Dryer vent termination shall have a self closing flap, but cannot have any type of screen or obstruction that will trap lint.

CALL to reschedule

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

More...

F3=Exit F5=Copy F6=Insert F7=Delete F8=Time stamp  
F12=Cancel F21=User defaults

ADDRESS : 141 SMITH DR SUBDIV: SANDY GROVE  
CONTRACTOR : PHONE :  
OWNER : SMITH RICKY PALMER PHONE : (919) 639-6712  
PARCEL : 04-0672- - -0069- -07-  
APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : 181 SMITH DRIVE ANGIER 27501, SANDY GROVE SUB DIV #9. OUT OF LILLINGTON 2MI, LEFT ON OLD BUIES CREEK RD #1542. TO ANGIER, 3MI SANDY GOVE ON LEFT, 7TH HOUSE ON LEFT.  
T/S: 09/23/2008 09:51 AM VBROWN ----

STRUCTURE: 000 000 18X28 1BDR 1BATH NO GAR NO DECK SFD

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 1.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : WELL

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/17/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001705839
	11/17/08	AP	
A814 01	12/01/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001711001
	12/18/08	AP	✓ 141 SMITH DR CHECK FOR # BY DRIVE AND ON HOME
P309 01	12/01/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001711019
	12/01/08	DA	Uncover plumbing in slab, must have a test on plumbing under slab.
P309 02	12/02/08	BS	R*PLUMB UNDER SLAB VRU #: 001711928
	12/02/08	AP	
B103 01	12/02/08	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001712512
	12/02/08	AP	
B111 01	12/02/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001712520
	12/02/08	AP	
H824 01	2/17/09	JM	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001735901
	2/17/09	AP	
R425 01	4/07/09	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001751734
	4/07/09	DA	1. Fire block between stairs stringers at the bottom. 2. Need a receptical accessible from grade at the front and rear of house. 3. Only one wire shall pass thru romex conector at panel. 4. Only 2 wires per hole may pass thru top or bottom plate 5. Cannot feed #14 wire with a #12 (receptacle at bottom of stairs and light switch. 6. All wiring shall be fire caulked. 7. Install dryer vent 8. Install HVAC vents and flex. 9. Bathroom receptacle shall be on its own circuit 10. Kitchen shall have 2 small appliance branch circuits on countertop 11. Need smoke detector on first floor. 12. Need light in stair well swithced from top and bottom. 13. Receptacle next to sliding door #12 wire shall be stapled within 12 inches of box Do not insulate

ADDRESS : 141 SMITH DR  
 CONTRACTOR :  
 OWNER : SMITH RICKY PALMER  
 PARCEL : 04-0672- - -0069- -07-  
 APPL NUMBER: 08-50020969 CP NEW RESIDENTIAL (SFD)

SUBDIV: SANDY GROVE  
 PHONE :  
 PHONE : (919) 639-6712

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 02	4/20/09 4/20/09	BS DA	FOUR TRADE ROUGH IN VRU #: 001757202 1. Wiring shall be firecaulked before insulation is installed. 2. Need receptacle front and rear accessible from grade. 3. Kitchen must have 2 seperate circuits on countertop receptacles. 4. Smoke detector on first floor shall be interconnected to smoke detectors upstairs. DO NOT INSULATE. Note- heating and cooling to be wall mounted heat/cool- no ductwork
R425 03	4/22/09 4/22/09	KS AP	FOUR TRADE ROUGH IN VRU #: 001758135
I129 01	4/24/09 4/24/09	KS AP	R*INSULATION INSPECTION VRU #: 001758952
R429 01	12/15/09 12/15/09	BS DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 001861517 T/S: 12/14/2009 10:40 AM VBROWN ----- 1. Must have upstairs heat installed. 2. Caulk all plumbing fixtures where they meet walls/floors. Toilets, vanities and countertops included. 3. exterior band at privacy deck must be a double. 4. Dryer vent termination shall have a self closing flap, but cannot have any type of screen or obstruction that will trap lint. Call to reschedule
R131 01	1/08/10 1/07/10	TI CA	ONE TRADE FINAL TIME: 17:00 VRU #: 001868520 T/S: 01/07/2010 10:15 AM DJOHNSON ----- T/S: 01/07/2010 02:10 PM NTART -----
R429 02	1/08/10	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 001868835 T/S: 01/07/2010 02:10 PM NTART -----

COMMENTS AND NOTES

**COUNTY OF HARNETT  
DEPARTMENT OF BUILDING INSPECTION  
AND PLANNING/DEVELOPMENT  
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Conditional Use Permit No.: \_\_\_\_\_

Type of Construction: V

Building Permit No.: 08-50020969

Owner of Building: Ricky Palmer Smith

Electrical Permit No.: 08-50020969

Building Address: 141 Smith Drive

Insulation Permit No.: 08-50020969

Zoning District: NA


Plumbing Permit No.: 08-50020969

Zoning Permit No.: NA

Mech. Permit No.: 08-50020969

Date: 01-08-10

Envir. C.O. No.: 08-50020969

 \_\_\_\_\_  
Brad Sutton

\_\_\_\_\_

Building Official

Zoning Official