

Property ID:
 Lot #:
 File #:
 Code:

**SOIL/SITE EVALUATION
 for ON-SITE WASTEWATER SYSTEM**

Owner: 08500 21181

Applicant:

Address:

Date Evaluated:

Proposed Facility: SFA

Design Flow (.1949): 76

Property Size:

Location of Site: 1179

Property Recorded:

Water Supply: Public [] Individual [] Well [] Spring [] Other
 Evaluation Method: Auger Boring [] Pit [] Cut
 Type of Wastewater: Sewage [] Industrial Process [] Mixed

P R O F I L E #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR	
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz		
5 3'		0-26	GA JL	VFA JF					.5	
		28-78	SHK SCL	FA JF						
		0-20	GA JL	VFA JF					.5	
		20-38	SHK SCL	FA JF						
		0-32	GA JL	VFA SF					.5	
		32-32								
		0-32	GA JL	VFA JF					.5	
		32-32	SHK SCL	FA JF						
		0-20	GA JL	VFA JF					.5	
		20-32	SHK SCL	FA JF						

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	251.	251.
Site LTAR	.5	.5

Other Factors (.1946): _____
 Site Classification (.1948): B
 Evaluated By: [Signature]
 Others Present: