Department of Environment, readin, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

| Owner: | | | Applicant | Applicant: | | |
|--------------------|------------------|--------------------|----------------------------|--------------------|----------|--|
| Address: | | | Date Evaluated: 7/2 2/2009 | | | |
| roposed Facility: | | Design Flow (.1949 |): | Property Size: | | |
| ocation of Site: | | | | Property Recorded: | | |
| Vater Supply: | Public | [] Individual | [] Well | [] Spring | [] Other | |
| valuation Method: | [] Auger Boring | | [] Pit | [] Cut | | |
| vpe of Wastewater: | [] Sewage | | [] Industrial Process | [] Mixed | | |

| Р К О Е | | | SOIL MORPHOLOGY | | OTHER PROFILE FACTORS | | | | |
|---------------------------|---|---------------------------|--|------------------------------------|-----------------------|------------------------------|-------------------------|-------------------------|----------------------------|
| L E # | ,1940 Landscape Position/ Slope% | Horizon Depth (IN.) | .1941 Structure/ Textur e | .1941 Consistence Mineralogy | Wetness/ | .1943 Soil Depth (IN.) | ,1956 Sapro Class | .1944 Restr Horiz | Profile Class & LTAR |
| | W | 0-10 10-34 | G/SL SBU/C | VK-NSNP Fr SISP | 10 4A 7/132" | | | | PS. 4 |
| | c. 5% | C-18 | G/52 | VA-USNP | | | | | Pr. 4 |
| | | 18-33 | 534/C | Fr-813P | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | · | | | | | | | |

| Description | Initial System | Repair System | | |
|-------------------------|----------------|---------------|--|--|
| Available Space (.1945) | | | | |
| System Type(s) | Puy + 216 | 1-y-25E | | |
| Site LTAR | .4 | ',4 | | |

Other Factors (.1946):

Site Classification (.1948): PS

Evaluated By:

Others Present: