
ADDRESS : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER : SHAW A LIMITED PARTNERSHIP
PARCEL : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
RIGHT ONTO SR#1144 LEFT ONTO SR#1120
LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09 <i>5-13-09</i>	TI <i>AL JV</i>	R*ELEC TEMP SERVICE POLE VRU #: 001767172 <i>no permit card to sign</i>

COMMENTS AND NOTES

ADDRESS . . : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . : SHAW A LIMITED PARTNERSHIP
PARCEL . . : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
RIGHT ONTO SR#1144 LEFT ONTO SR#1120
LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	<u>5/26/09</u>	<u>DA DI</u>	

----- COMMENTS AND NOTES -----

DO NOT REMOVE!

Harnett County Inspection Department

102 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7527 • Fax: (910) 893-2793

Job Name: Shaw Construction Date: _____

Address: 91 South Dakota Ct.

Lot No.: 47 Permit No.: _____

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|-------------------------------------|----------------------------------|--|-------------------------------------|---------------------------------------|---------------------------------|--------------------------------------|
| <input type="checkbox"/> Footing | <input type="checkbox"/> Foundation | <input type="checkbox"/> Bldg. | <input type="checkbox"/> Elec. | <input type="checkbox"/> Plumb. | <input type="checkbox"/> Mech. | <input type="checkbox"/> Insul. | <input type="checkbox"/> Floor Fram. |
| <input type="checkbox"/> Floor Slab | <input type="checkbox"/> MFG. Home | <input type="checkbox"/> Modular | <input type="checkbox"/> Damp/Water Proof. | <input type="checkbox"/> Structural | <input type="checkbox"/> Wall Sheath. | <input type="checkbox"/> Other | |

Violations Found: 1) All trenches must be minimum 16 inches wide.

2) Bottom of trenches must be 12 inches below grade (undisturbed soil).

3) Piers footings too small, not marked for concrete.

Code Enforcement Official

Date: 5/26/09

Signature: D Taylor

It is unlawful for any sub contractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation.

Harnett County

INSPECTOR: IVR

DATE 5/29/09

ADDRESS : 91 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP
 PARCEL : 01-0536-01- -0111- -18-
 APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
 RIGHT ONTO SR#1144 LEFT ONTO SR#1120
 LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
 DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	TI	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	<i>5-29-09</i>	<i>DA JH</i>	

COMMENTS AND NOTES

Application number, type 09 50021486 CP NEW RESIDENTIAL (SFD)
Property address 91 SOUTH DAKOTA CT

Need to remove all roots and loose dirt from footings



OK Exit Cancel Copy Insert Delete Time stamp User defaults

ADDRESS . . : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . . : SHAW A LIMITED PARTNERSHIP
PARCEL . . . : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
RIGHT ONTO SR#1144 LEFT ONTO SR#1120
LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	5/29/09	DA	Need to remove all roots and loose dirt from footings
B101 03	6/05/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001777648
	6/05/09	CA	
B101 04	6/08/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778299
	6-8-09	AP JH	

COMMENTS AND NOTES

ADDRESS : 91 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP
 PARCEL : 01-0536-01- -0111- -18-
 APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
 RIGHT ONTO SR#1144 LEFT ONTO SR#1120
 LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
 DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	5/29/09	DA	Need to remove all roots and loose dirt from footings
B101 03	6/05/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001777648
	6/05/09	CA	
B101 04	6/08/09	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778299
	6/08/09	AP	
A814 01	6/22/09	TI	ADDRESS CONFIRMATION VRU #: 001784339
B103 01	6/22/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784354
	6/22/09	CA	
B103 02	6/23/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784875

6-23-09 AP JV

COMMENTS AND NOTES

ADDRESS : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER : SHAW A LIMITED PARTNERSHIP
PARCEL : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
RIGHT ONTO SR#1144 LEFT ONTO SR#1120
LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	5/29/09	DA	Need to remove all roots and loose dirt from footings
B101 03	6/05/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001777648
	6/05/09	CA	
B101 04	6/08/09	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778299
	6/08/09	AP	
B103 01	6/22/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784354
	6/22/09	CA	
A814 01	6/22/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001784339
	7/06/09	AP	91 SOUTH DAKOTA CT LOT 47 SPRING LAKE 28390 T/S: 07/06/2009 12:38 PM TWARD
B103 02	6/23/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784875
	6/23/09	AP	
B105 01	6/30/09	TI	R*OPEN FLOOR TIME: 17:00 VRU #: 001785948
	6/29/09	CA	
B105 02	8/04/09	TI	R*OPEN FLOOR VRU #: 001804012

8-4-09 AP JH

COMMENTS AND NOTES

ADDRESS : 91 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP
 PARCEL : 01-0536-01- -0111- -18-
 APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
 RIGHT ONTO SR#1144 LEFT ONTO SR#1120
 LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
 DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK


FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	5/29/09	DA	Need to remove all roots and loose dirt from footings
B101 03	6/05/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001777648
	6/05/09	CA	
B101 04	6/08/09	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778299
	6/08/09	AP	
B103 01	6/22/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784354
	6/22/09	CA	
A814 01	6/22/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001784339
	7/06/09	AP	91 SOUTH DAKOTA CT LOT 47 SPRING LAKE 28390 T/S: 07/06/2009 12:38 PM TWARD
B103 02	6/23/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784875
	6/23/09	AP	
B105 01	6/30/09	TI	R*OPEN FLOOR TIME: 17:00 VRU #: 001785948
	6/29/09	CA	
B105 02	8/04/09	JH	R*OPEN FLOOR VRU #: 001804012
	8/04/09	AP	T/S: 08/04/2009 01:56 PM JHALL
R427 01	8/27/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001813641

8-27-09 *OP* *JH*

COMMENTS AND NOTES



8/27/2009 10:35:16 AM

Application number, type	09 50021486 CP NEW RESIDENTIAL (SFD)
Property address	91 SOUTH DAKOTA CT

- 1)Front porch needs to be flashed & shingles.
- 2)Nail all lvs per drawings.
- 3)Nail all 2ply roof truss per truss drawings.
- 4)Strap all pex water lines every 32" per code throughout house.
- 5)Install ducts for exhaust.
- 6)Missing nails in floor truss hangers @ front door.
- 7)Bond faucet to tub in master bathroom.
- 8)Window @ the top of the stairs needs to be tempered.
- 9)Strap trunk line in attic @ the end.
- 10)Need 24" walkway to unit in attic.
- 11)Need receptacle on front of house accessible from grade.



OK	Exit	Cancel	Copy	Insert	Delete	Time stamp	User defaults
----	------	--------	------	--------	--------	------------	---------------

ADDRESS : 91 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP
 PARCEL : 01-0536-01- -0111- -18-
 APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
 RIGHT ONTO SR#1144 LEFT ONTO SR#1120
 LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
 DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	5/29/09	DA	Need to remove all roots and loose dirt from footings
B101 03	6/05/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001777648
	6/05/09	CA	
B101 04	6/08/09	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778299
	6/08/09	AP	
B103 01	6/22/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784354
	6/22/09	CA	
A814 01	6/22/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001784339
	7/06/09	AP	91 SOUTH DAKOTA CT LOT 47 SPRING LAKE 28390 T/S: 07/06/2009 12:38 PM TWARD
B103 02	6/23/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784875
	6/23/09	AP	
B105 01	6/30/09	TI	R*OPEN FLOOR TIME: 17:00 VRU #: 001785948
	6/29/09	CA	
B105 02	8/04/09	JH	R*OPEN FLOOR VRU #: 001804012
	8/04/09	AP	T/S: 08/04/2009 01:56 PM JHALL
R427 01	8/27/09	JH	FOUR TRADE ROUGH IN >2500 VRU #: 001813641
	8/27/09	DP	1)Front porch needs to be flashed & shingles. <input checked="" type="checkbox"/> Nail all lvls per drawings. <input checked="" type="checkbox"/> Nail all 2ply roof truss per truss drawings. 4)Strap all pex water lines every 32" per code throughout house. <input checked="" type="checkbox"/> Install ducts for exhaust. 6)Missing nails in floor truss hangers @ front door. <input checked="" type="checkbox"/> Bond faucet to tub in master bathroom. 8)Window @ the top of the stairs needs to be tempered. <input checked="" type="checkbox"/> Strap trunk line in attic @ the end. <input checked="" type="checkbox"/> Need 24" walkway to unit in attic. <input checked="" type="checkbox"/> Need receptacle on front of house accessible from grade.
R427 02	9/10/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001818889

PREPARED 9/09/09, 14:03:34
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 15
DATE 9/10/09


ADDRESS : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER : SHAW A LIMITED PARTNERSHIP
PARCEL : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

9-10-09 *DP JH*

COMMENTS AND NOTES



9/10/2009 8:39:11 AM

Application number, type 09 50021486 CP NEW RESIDENTIAL (SFD)

Property address 91 SOUTH DAKOTA CT

- 1)Water lines @ water heater not strapped every 32".
- 2)Missing nails in floor truss hangers @ front door on floortruss.
- 3)Window @ the top of stairs needs to be tempered.



OK Exit Cancel Copy Insert Delete Time stamp User defaults

ADDRESS : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER : SHAW A LIMITED PARTNERSHIP
PARCEL : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
RIGHT ONTO SR#1144 LEFT ONTO SR#1120
LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	5/29/09	DA	Need to remove all roots and loose dirt from footings
B101 03	6/05/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001777648
	6/05/09	CA	
B101 04	6/08/09	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778299
	6/08/09	AP	
B103 01	6/22/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784354
	6/22/09	CA	
A814 01	6/22/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001784339
	7/06/09	AP	91 SOUTH DAKOTA CT LOT 47 SPRING LAKE 28390 T/S: 07/06/2009 12:38 PM TWARD
B103 02	6/23/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784875
	6/23/09	AP	
B105 01	6/30/09	TI	R*OPEN FLOOR TIME: 17:00 VRU #: 001785948
	6/29/09	CA	
B105 02	8/04/09	JH	R*OPEN FLOOR VRU #: 001804012
	8/04/09	AP	T/S: 08/04/2009 01:56 PM JHALL
R427 01	8/27/09	JH	FOUR TRADE ROUGH IN >2500 VRU #: 001813641
	8/27/09	DP	1)Front porch needs to be flashed & shingles. 2)Nail all lvls per drawings. 3)Nail all 2ply roof truss per truss drawings. 4)Strap all pex water lines every 32" per code throughout house. 5)Install ducts for exhaust. 6)Missing nails in floor truss hangers @ front door. 7)Bond faucet to tub in master bathroom. 8)Window @ the top of the stairs needs to be tempered. 9)Strap trunk line in attic @ the end. 10)Need 24" walkway to unit in attic. 11)Need receptacle on front of house accessible from grade.
R427 02	9/10/09	JH	FOUR TRADE ROUGH IN >2500 VRU #: 001818889

ADDRESS . . : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . . : SHAW A LIMITED PARTNERSHIP
PARCEL . . . : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	9/10/09	DP	1)Water lines @ water heater not strapped every 32". 2)Missing nails in floor truss hangers @ front door on floortruss. 3)Window @ the top of stairs needs to be tempered.
R427 03	10/02/09 <i>10-2-09</i>	TI <i>ARTH</i>	FOUR TRADE ROUGH IN >2500 VRU #: 001830454
----- COMMENTS AND NOTES -----			

ADDRESS : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER : SHAW A LIMITED PARTNERSHIP
PARCEL : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	9/10/09	DP	1)Water lines @ water heater not strapped every 32". 2)Missing nails in floor truss hangers @ front door on floortruss. 3)Window @ the top of stairs needs to be tempered.
R427 03	10/02/09	JH	FOUR TRADE ROUGH IN >2500 VRU #: 001830454
	10/02/09	AP	
I129 01	10/07/09	TI	R*INSULATION INSPECTION VRU #: 001832054
	<u>10/7/09</u>	<u>DADI</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 91 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER : SHAW A LIMITED PARTNERSHIP
PARCEL : 01-0536-01- -0111- -18-
APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	9/10/09	DP	1)Water lines @ water heater not strapped every 32". 2)Missing nails in floor truss hangers @ front door on floortruss. 3)Window @ the top of stairs needs to be tempered.
R427 03	10/02/09 10/02/09	JH AP	FOUR TRADE ROUGH IN >2500 VRU #: 001830454 -----
I129 01	10/07/09 10/07/09	DE DA	R*INSULATION INSPECTION VRU #: 001832054 1. No insulation under attic catwalk and platform. 2. Replace broken stud at top of stairway T/S: 10/07/2009 10:38 AM DETAYLOR -----
I129 02	10/13/09 <u>10/13/09</u>	TI AP DK	R*INSULATION INSPECTION VRU #: 001835602

----- COMMENTS AND NOTES -----

ADDRESS : 91 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP
 PARCEL : 01-0536-01- -0111- -18-
 APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
 RIGHT ONTO SR#1144 LEFT ONTO SR#1120
 LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
 DAKOTA FIFTH LOT ON LEFT LOT 47 JB

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE :

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	5/29/09	DA	Need to remove all roots and loose dirt from footings
B101 03	6/05/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001777648
	6/05/09	CA	
B101 04	6/08/09	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778299
	6/08/09	AP	
B103 01	6/22/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784354
	6/22/09	CA	
A814 01	6/22/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001784339
	7/06/09	AP	✓ 91 SOUTH DAKOTA CT LOT 47 SPRING LAKE 28390 T/S: 07/06/2009 12:38 PM TWARD
B103 02	6/23/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784875
	6/23/09	AP	
B105 01	6/30/09	TI	R*OPEN FLOOR TIME: 17:00 VRU #: 001785948
	6/29/09	CA	
B105 02	8/04/09	JH	R*OPEN FLOOR VRU #: 001804012
	8/04/09	AP	T/S: 08/04/2009 01:56 PM JHALL
R427 01	8/27/09	JH	FOUR TRADE ROUGH IN >2500 VRU #: 001813641
	8/27/09	DP	1)Front porch needs to be flashed & shingles. 2)Nail all lvls per drawings. 3)Nail all 2ply roof truss per truss drawings. 4)Strap all pex water lines every 32" per code throughout house. 5)Install ducts for exhaust. 6)Missing nails in floor truss hangers @ front door. 7)Bond faucet to tub in master bathroom. 8)Window @ the top of the stairs needs to be tempered. 9)Strap trunk line in attic @ the end. 10)Need 24" walkway to unit in attic. 11)Need receptacle on front of house accessible from grade.
R427 02	9/10/09	JH	FOUR TRADE ROUGH IN >2500 VRU #: 001818889

 ADDRESS . . : 91 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
 CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
 OWNER . . . : SHAW A LIMITED PARTNERSHIP PHONE :
 PARCEL . . . : 01-0536-01- -0111- -18-
 APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	9/10/09	DP	1)Water lines @ water heater not strapped every 32". 2)Missing nails in floor truss hangers @ front door on floortruss. 3)Window @ the top of stairs needs to be tempered.
R427 03	10/02/09	JH	FOUR TRADE ROUGH IN >2500 VRU #: 001830454
	10/02/09	AP	
I129 01	10/07/09	DT	R*INSULATION INSPECTION VRU #: 001832054
	10/07/09	DA	1. No insulation under attic catwalk and platform. 2. Replace broken stud at top of stairway T/S: 10/07/2009 10:38 AM DETAYLOR -----
I129 02	10/13/09	DT	R*INSULATION INSPECTION VRU #: 001835602
	10/13/09	AP	
H824 01	1/13/10	OT	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001871102
	1/13/10	AP	T/S: 01/14/2010 10:46 AM SSTEWARD ----- T/S: 01/14/2010 10:47 AM SSTEWARD -----
R429 01	1/21/10	TI	FOUR TRADE FINAL VRU #: 001872639
	<u>1/21/10</u>	<u>DA</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 91 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP
 PARCEL : 01-0536-01- -0111- -18-
 APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE :

DIRECTIONS : HWY 201 SOUTH APPROX 10 MILES TAKE A
 RIGHT ONTO SR#1144 LEFT ONTO SR#1120
 LEFT ONTO SIERRA TRAIL RIGHT ONTO SOUTH
 DAKOTA FIFTH LOT ON LEFT LOT 47 JB

STRUCTURE: 000 000 68X27 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	5/13/09	JH	R*ELEC TEMP SERVICE POLE VRU #: 001767172
	5/13/09	AP	no permit card to sign
B101 01	5/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001770809
	5/26/09	DA	1. Trenches not 16 inches wide. 2. Trenches not 12 inches below grade. 3. Piers not marked for concrete.
B101 02	5/29/09	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001773894
	5/29/09	DA	Need to remove all roots and loose dirt from footings
B101 03	6/05/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001777648
	6/05/09	CA	
B101 04	6/08/09	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778299
	6/08/09	AP	
B103 01	6/22/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784354
	6/22/09	CA	
A814 01	6/22/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001784339
	7/06/09	AP	✓ 91 SOUTH DAKOTA CT LOT 47 SPRING LAKE 28390 T/S: 07/06/2009 12:38 PM TWARD
B103 02	6/23/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001784875
	6/23/09	AP	
B105 01	6/30/09	TI	R*OPEN FLOOR TIME: 17:00 VRU #: 001785948
	6/29/09	CA	
B105 02	8/04/09	JH	R*OPEN FLOOR VRU #: 001804012
	8/04/09	AP	T/S: 08/04/2009 01:56 PM JHALL
R427 01	8/27/09	JH	FOUR TRADE ROUGH IN >2500 VRU #: 001813641
	8/27/09	DP	1)Front porch needs to be flashed & shingles. 2)Nail all lvl's per drawings. 3)Nail all 2ply roof truss per truss drawings. 4)Strap all pex water lines every 32" per code throughout house. 5)Install ducts for exhaust. 6)Missing nails in floor truss hangers @ front door. 7)Bond faucet to tub in master bathroom. 8)Window @ the top of the stairs needs to be tempered. 9)Strap trunk line in attic @ the end. 10)Need 24" walkway to unit in attic. 11)Need receptacle on front of house accessible from grade.

ADDRESS : 91 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP
 PARCEL : 01-0536-01- -0111- -18-
 APPL NUMBER: 09-50021486 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R427 02	9/10/09 9/10/09	JH DP	FOUR TRADE ROUGH IN >2500 VRU #: 001818889 1)Water lines @ water heater not strapped every 32". 2)Missing nails in floor truss hangers @ front door on floortruss. 3)Window @ the top of stairs needs to be tempered.
R427 03	10/02/09 10/02/09	JH AP	FOUR TRADE ROUGH IN >2500 VRU #: 001830454
I129 01	10/07/09 10/07/09	DT DA	R*INSULATION INSPECTION VRU #: 001832054 1. No insulation under attic catwalk and platform. 2. Replace broken stud at top of stairway T/S: 10/07/2009 10:38 AM DETAYLOR -----
I129 02	10/13/09 10/13/09	DT AP	R*INSULATION INSPECTION VRU #: 001835602
H824 01	1/13/10 1/13/10	OT AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001871102 T/S: 01/14/2010 10:46 AM SSTEWARD ----- T/S: 01/14/2010 10:47 AM SSTEWARD -----
R429 01	1/21/10 1/21/10	DT DA	FOUR TRADE FINAL VRU #: 001872639 1. Right front handrail loose. 2. Need expansion tank for water heater. 3. Microwave needs 20 amp receptacle for 20 amp breaker. 4. Attic air handler missing condensate drains. 5. Install medicine cabs or repair walls. T/S: 01/21/2010 11:45 AM DETAYLOR -----
R431 01	1/26/10 <u>1/26/10</u>	TI <u>AP DT</u>	FOUR TRADE FINAL >2500 VRU #: 001875525 The plumber said the expansion tank is under the house right beside the pressure reducing valve.

COMMENTS AND NOTES

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential Conditional Use Permit No.: _____
Type of Construction: _____ Building Permit No.: _____
Owner of Building: Shaw A Limited Part Electrical Permit No.: _____
Building Address: 91 South Dakota Ct Insulation Permit No.: _____
Zoning District: Spring Lake, NC 28390 Plumbing Permit No.: _____
Zoning Permit No.: _____ Mech. Permit No.: 05-50021486
Date: 1/26/10 Envir. C.O. No.: _____
[Signature] Building Official _____ Zoning Official _____