

PREPARED 2/24/09, 14:15:44
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 1
DATE 2/25/09

ADDRESS : 184 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED	INSP	DESCRIPTION	TIME	VRU #
	COMPLETED	RESULT	RESULTS/COMMENTS		
B101 01	2/25/09 <i>2/25/09</i>	TI <i>AR DT</i>	R*BLDG FOOTING / TEMP SVC POLE	17:00	001738095

COMMENTS AND NOTES

ADDRESS : 184 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
A814 01	3/20/09	TI	ADDRESS CONFIRMATION VRU #: 001745520
B103 01	3/20/09 <i>3/20/09</i>	TI <i>AB DT</i>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538

COMMENTS AND NOTES

ADDRESS . . : 184 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . . : WOODSHIRE PARTNERS LLC PHONE :
PARCEL . . . : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 195 JB

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	TI	R*PLUMB UNDER SLAB VRU #: 001746387
	<u>3.24.09</u>	<u>DPBS</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 184 BLUE OAK DR
 CONTRACTOR : CAVINESS LAND DEVELOPMENT
 OWNER : WOODSHIRE PARTNERS LLC
 PARCEL : 01-0536-06- -0028- -35-
 APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 195 JB

SUBDIV: WOODSHIRE PH 5
 PHONE : (919) 481-0503
 PHONE :

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	DS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	TI	R*PLUMB UNDER SLAB VRU #: 001747997

3-29 AP

KS

COMMENTS AND NOTES

ADDRESS : 184 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 195 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	BS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	KS	R*PLUMB UNDER SLAB VRU #: 001747997
	3/26/09	AP	
B111 01	3/31/09	DT	R*BLDG SLAB INSP VRU #: 001749555
	3/31/09	DA	1. Lug footers in kitchen and for sunroom not 9 inches deep. Dig to correct depth and have strings present for re-inspection.
B111 02	4/01/09	TI	R*BLDG SLAB INSP VRU #: 001750033
	4/1/09	DP DT	

COMMENTS AND NOTES

DO NOT REMOVE!

Harnett County Inspection Department

102 East Front Street • P.O. Box 65
Lillington, NC 27546
Phone: (910) 893-7527 • Fax: (910) 893-2793

Job Name: Caviness Land Date: 4/1/09

Address: 184 Blue Oak

Lot No.: 195 Permit No.: _____

(Check Box for Violation)

Footing

Foundation

Bldg.

Elec.

Plumb.

Mech.

Insul.

Floor Fram.

Floor Slab

MFG. Home

Modular

Damp/Water Proof.

Structural

Wall Sheath.

Other

Violations Found: 1) Previous violation notice (attached) started to dig sunroom lug footer and to leave strings up.

\$50 re-inspection fee.

Code Enforcement Official

Date: 4/1/09

Signature: [Handwritten Signature]

It is unlawful for any sub contractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation.

ADDRESS : 184 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 195 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	BS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	KS	R*PLUMB UNDER SLAB VRU #: 001747997
	3/26/09	AP	
B111 01	3/31/09	TI	R*BLDG SLAB INSP VRU #: 001749555
	3/31/09	DA	

COMMENTS AND NOTES

ADDRESS : 184 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
 OWNER : WOODSHIRE PARTNERS LLC PHONE :
 PARCEL : 01-0536-06- -0028- -35-
 APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 195 JB

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	BS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	KS	R*PLUMB UNDER SLAB VRU #: 001747997
	3/26/09	AP	
B111 01	3/31/09	DT	R*BLDG SLAB INSP VRU #: 001749555
	3/31/09	DA	1. Lug footers in kitchen and for sunroom not 9 inches deep. Dig to correct depth and have strings present for re-inspection.
B111 02	4/01/09	DT	R*BLDG SLAB INSP VRU #: 001750033
	4/01/09	DP	1. Strings not up for measuring, and sunroom lug footer not dug.
B111 03	4/03/09	TI	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001750611
	<u>4/13/09</u>	<u>AP DT</u>	CUSTOMER PAID REINSPECTION FEE. RESCHED FOR FRI 4-3-09

COMMENTS AND NOTES

ADDRESS : 184 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER : WOODSHIRE PARTNERS LLC PHONE :
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 195 JB

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	BS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	KS	R*PLUMB UNDER SLAB VRU #: 001747997
	3/26/09	AP	
B111 01	3/31/09	DT	R*BLDG SLAB INSP VRU #: 001749555
	3/31/09	DA	1. Lug footers in kitchen and for sunroom not 9 inches deep. Dig to correct depth and have strings present for re-inspection.
B111 02	4/01/09	DT	R*BLDG SLAB INSP VRU #: 001750033
	4/01/09	DP	1. Strings not up for measuring, and sunroom lug footer not dug.
B111 03	4/03/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001750611
	4/03/09	AP	CUSTOMER PAID REINSPECTION FEE. RESCHED FOR FRI 4-3-09
R427 01	4/28/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001760859
	4/28/09	CA	
R427 02	4/29/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001761451

4/29/09 DA DT

COMMENTS AND NOTES

DO NOT REMOVE!

Harnett County Inspection Department

102 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7527 • Fax: (910) 893-2793

Job Name: Caviness Land Dev. Date: _____

Address: 184 Blue Oak Dr.

Lot No.: 195 Permit No.: _____

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|-------------------------------------|----------------------------------|--|-------------------------------------|---------------------------------------|---------------------------------|--------------------------------------|
| <input type="checkbox"/> Footing | <input type="checkbox"/> Foundation | <input type="checkbox"/> Bldg. | <input type="checkbox"/> Elec. | <input type="checkbox"/> Plumb. | <input type="checkbox"/> Mech. | <input type="checkbox"/> Insul. | <input type="checkbox"/> Floor Fram. |
| <input type="checkbox"/> Floor Slab | <input type="checkbox"/> MFG. Home | <input type="checkbox"/> Modular | <input type="checkbox"/> Damp/Water Proof. | <input type="checkbox"/> Structural | <input type="checkbox"/> Wall Sheath. | <input type="checkbox"/> Other | |

Violations Found: 1) No plumbing boots.
2) Drain and water line test not on.
3) E trusses (sunroom) need uplift straps at joint 5.
4) Need fire caulk for electrical to left of computer room door in bonus.
5) Need nail guards for electrical horizontal in front bedroom
6) Kitchen window not installed. + bonus.

Okay to side & insulate

Code Enforcement Official
 Signature: [Signature]

Date: 4/29/09

It is unlawful for any sub contractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation.

ADDRESS : 184 BLUE OAK DR
 CONTRACTOR : CAVINESS LAND DEVELOPMENT
 OWNER : WOODSHIRE PARTNERS LLC
 PARCEL : 01-0536-06- -0028- -35-
 APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 195 JB

SUBDIV: WOODSHIRE PH 5
 PHONE : (919) 481-0503
 PHONE :

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	BS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	KS	R*PLUMB UNDER SLAB VRU #: 001747997
	3/26/09	AP	
B111 01	3/31/09	DT	R*BLDG SLAB INSP VRU #: 001749555
	3/31/09	DA	1. Lug footers in kitchen and for sunroom not 9 inches deep. Dig to correct depth and have strings present for re-inspection.
B111 02	4/01/09	DT	R*BLDG SLAB INSP VRU #: 001750033
	4/01/09	DP	1. Strings not up for measuring, and sunroom lug footer not dug.
B111 03	4/03/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001750611
	4/03/09	AP	CUSTOMER PAID REINSPECTION FEE. RESCHED FOR FRI 4-3-09
R427 01	4/28/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001760859
	4/28/09	CA	
R427 02	4/29/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001761451
	4/29/09	DA	1. drain and water line tests not complete. 2. No plumbing boots. 3. Need nail guards for electrical horizontals in bonus room and front bedroom. 4. Need fire caulk for electrical at top plate to left of computer room door. 5. Kitchen window not installed. 6. E truss in sunroom need uplift straps at joint 5. Okay to side and insulate.
I129 01	4/30/09	TI	R*INSULATION INSPECTION VRU #: 001762293
	<u>4/30/09</u>	<u>DA DT</u>	
R427 03	4/30/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001762319
	<u>4/30/09</u>	<u>DA DT</u>	

COMMENTS AND NOTES

ADDRESS : 184 BLUE OAK DR
 CONTRACTOR : CAVINESS LAND DEVELOPMENT
 OWNER : WOODSHIRE PARTNERS LLC
 PARCEL : 01-0536-06- -0028- -35-
 APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 195 JB

SUBDIV: WOODSHIRE PH 5
 PHONE : (919) 481-0503
 PHONE :

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	BS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	KS	R*PLUMB UNDER SLAB VRU #: 001747997
	3/26/09	AP	
B111 01	3/31/09	DT	R*BLDG SLAB INSP VRU #: 001749555
	3/31/09	DA	1. Lug footers in kitchen and for sunroom not 9 inches deep. Dig to correct depth and have strings present for re-inspection.
B111 02	4/01/09	DT	R*BLDG SLAB INSP VRU #: 001750033
	4/01/09	DP	1. Strings not up for measuring, and sunroom lug footer not dug.
B111 03	4/03/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001750611
	4/03/09	AP	CUSTOMER PAID REINSPECTION FEE. RESCHED FOR FRI 4-3-09
R427 01	4/28/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001760859
	4/28/09	CA	
R427 02	4/29/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001761451
	4/29/09	DA	1. drain and water line tests not complete. 2. No plumbing boots. 3. Need nail guards for electrical horizontals in bonus room and front bedroom. 4. Need fire caulk for electrical at top plate to left of computer room door. 5. Kitchen window not installed. 6. E truss in sunroom need uplift straps at joint 5. Okay to side and insulate.
I129 01	4/30/09	DT	R*INSULATION INSPECTION VRU #: 001762293
	4/30/09	DA	1. Kitchen window still not installed. 2. E trusses still not strapped for uplift. 3. Trap above panel in garage must be insulated.
R427 03	4/30/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001762319
	4/30/09	DA	1. Kitchen window still not installed. 2. E trusses still not strapped for uplift. 3. Trap above panel in garage must be insulated.

ADDRESS : 184 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER : WOODSHIRE PARTNERS LLC PHONE :
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 02	5/01/09 <u>5/1/09</u>	TI <u>DP DT</u>	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001762616
R427 04	5/01/09 <u>5/1/09</u>	TI <u>DP DT</u>	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001762624

----- COMMENTS AND NOTES -----

DO NOT REMOVE!

Harnett County Inspection Department

102 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7527 • Fax: (910) 893-2793

Job Name: Caviness Land Dev. Date: 5/1/09 10:25 a.m.

Address: 184 Blue Oak Dr.

Lot No.: 195 Permit No.: _____

(Check Box for Violation)

Footing

Foundation

Bldg.

Elec.

Plumb.

Mech.

Insul.

Floor Fram.

Floor Slab

MFG. Home

Modular

Damp/Water Proof.

Structural

Wall Sheath.


Other

Violations Found: No insulation around kitchen window.

\$50.00 Re-inspection fee.

Code Enforcement Official

Date: 5/1/09

Signature: 

It is unlawful for any sub contractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation.

ADDRESS : 184 BLUE OAK DR
CONTRACTOR : CAVINESS, LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 02	5/01/09	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001762616
	5/01/09	DP	1. No insulation around kithcen window.
R427 04	5/01/09	DT	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001762624
	5/01/09	AP	
I129 03	5/04/09	TI	R*INSULATION INSPECTION VRU #: 001763192
	<u>5/4/09</u>	<u>AP DT</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 184 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
 CONTRACTOR : CAVINESS, LAND DEVELOPMENT PHONE : (919) 481-0503
 OWNER : WOODSHIRE PARTNERS LLC PHONE :
 PARCEL : 01-0536-06- -0028- -35-
 APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 195 JB

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09 2/25/09	DT AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095 T-Pole passed.
B103 01	3/20/09 3/20/09	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
A814 01	3/20/09 3/20/09	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520 184 blue oak dr lot 195
P309 01	3/24/09 3/24/09	BS DP	R*PLUMB UNDER SLAB VRU #: 001746387 uncover plumbing and refill test pipe
P309 02	3/26/09 3/26/09	KS AP	R*PLUMB UNDER SLAB VRU #: 001747997
B111 01	3/31/09 3/31/09	DT DA	R*BLDG SLAB INSP VRU #: 001749555 1. Lug footers in kitchen and for sunroom not 9 inches deep. Dig to correct depth and have strings present for re-inspection.
B111 02	4/01/09 4/01/09	DT DP	R*BLDG SLAB INSP VRU #: 001750033 1. Strings not up for measuring, and sunroom lug footer not dug.
B111 03	4/03/09 4/03/09	DT AP	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001750611 CUSTOMER PAID REINSPECTION FEE. RESCHED FOR FRI 4-3-09
R427 01	4/28/09 4/28/09	DT CA	FOUR TRADE ROUGH IN >2500 VRU #: 001760859
R427 02	4/29/09 4/29/09	TI DA	FOUR TRADE ROUGH IN >2500 VRU #: 001761451 1. drain and water line tests not complete. 2. No plumbing boots. 3. Need nail guards for electrical horizontals in bonus room and front bedroom. 4. Need fire caulk for electrical at top plate to left of computer room door. 5. Kitchen window not installed. 6. E truss in sunroom need uplift straps at joint 5. Okay to side and insulate.
I129 01	4/30/09 4/30/09	DT DA	R*INSULATION INSPECTION VRU #: 001762293 1. Kitchen window still not installed. 2. E trusses still not strapped for uplift. 3. Trap above panel in garage must be insulated.
R427 03	4/30/09 4/30/09	DT DA	FOUR TRADE ROUGH IN >2500 VRU #: 001762319 1. Kitchen window still not installed. 2. E trusses still not strapped for uplift. 3. Trap above panel in garage must be insulated.

ADDRESS : 184 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER : WOODSHIRE PARTNERS LLC PHONE :
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 02	5/01/09	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001762616
	5/01/09	DP	1. No insulation around kithcen window.
R427 04	5/01/09	DT	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001762624
	5/01/09	AP	
I129 03	5/04/09	DT	R*INSULATION INSPECTION VRU #: 001763192
	5/04/09	AP	
H824 01	5/29/09	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001776178
	5/29/09	AP	
R431 01	7/08/09	TI	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001791409
	<u>7/8/09</u>	DT DA	T/S: 07/07/2009 02:16 PM RDCONTE -----

----- COMMENTS AND NOTES -----

ADDRESS : 184 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 02	5/01/09	DT	3. Trap above panel in garage must be insulated. R*INSULATION INSPECTION TIME: 17:00 VRU #: 001762616
R427 04	5/01/09	DP	1. No insulation around kitchen window.
I129 03	5/01/09	DT	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001762624
H824 01	5/01/09	AP	
R431 01	5/04/09	DT	R*INSULATION INSPECTION VRU #: 001763192
	5/04/09	AP	
R431 01	5/29/09	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001776178
	5/29/09	AP	
R431 01	7/08/09	DT	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001791409
	7/08/09	DA	T/S: 07/07/2009 02:16 PM RDCONTE ----- 1. Half bath sink and toilet must be caulked. 2. Stairs missing handrail. 3. Air handlers must be labeled at appliance and panel. T/S: 07/08/2009 11:49 AM DETAYLOR -----
R431 02	7/09/09 7-9	TI AP	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001792142 T/S: 07/08/2009 02:24 PM NTART -----

----- COMMENTS AND NOTES -----

ADDRESS . . : 184 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
 OWNER . . : WOODSHIRE PARTNERS LLC PHONE :
 PARCEL . . : 01-0536-06- -0028- -35-
 APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 195 JB

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	BS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	KS	R*PLUMB UNDER SLAB VRU #: 001747997
	3/26/09	AP	
B111 01	3/31/09	DT	R*BLDG SLAB INSP VRU #: 001749555
	3/31/09	DA	1. Lug footers in kitchen and for sunroom not 9 inches deep. Dig to correct depth and have strings present for re-inspection.
B111 02	4/01/09	DT	R*BLDG SLAB INSP VRU #: 001750033
	4/01/09	DP	1. Strings not up for measuring, and sunroom lug footer not dug.
B111 03	4/03/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001750611
	4/03/09	AP	CUSTOMER PAID REINSPECTION FEE. RESCHED FOR FRI 4-3-09
R427 01	4/28/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001760859
	4/28/09	CA	
R427 02	4/29/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001761451
	4/29/09	DA	1. drain and water line tests not complete. 2. No plumbing boots. 3. Need nail guards for electrical horizontals in bonus room and front bedroom. 4. Need fire caulk for electrical at top plate to left of computer room door. 5. Kitchen window not installed. 6. E truss in sunroom need uplift straps at joint 5. Okay to side and insulate.
I129 01	4/30/09	DT	R*INSULATION INSPECTION VRU #: 001762293
	4/30/09	DA	1. Kitchen window still not installed. 2. E trusses still not strapped for uplift. 3. Trap above panel in garage must be insulated.
R427 03	4/30/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001762319
	4/30/09	DA	1. Kitchen window still not installed. 2. E trusses still not strapped for uplift.

ADDRESS : 184 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER : WOODSHIRE PARTNERS LLC PHONE :
PARCEL : 01-0536-06- -0028- -35-
APPL NUMBER: 09-50021512 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 195 JB

STRUCTURE: 000 000 30X57 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/25/09	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001738095
	2/25/09	AP	T-Pole passed.
B103 01	3/20/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001745538
	3/20/09	AP	
A814 01	3/20/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001745520
	3/20/09	AP	184 blue oak dr lot 195
P309 01	3/24/09	BS	R*PLUMB UNDER SLAB VRU #: 001746387
	3/24/09	DP	uncover plumbing and refill test pipe
P309 02	3/26/09	KS	R*PLUMB UNDER SLAB VRU #: 001747997
	3/26/09	AP	
B111 01	3/31/09	DT	R*BLDG SLAB INSP VRU #: 001749555
	3/31/09	DA	1. Lug footers in kitchen and for sunroom not 9 inches deep. Dig to correct depth and have strings present for re-inspection.
B111 02	4/01/09	DT	R*BLDG SLAB INSP VRU #: 001750033
	4/01/09	DP	1. Strings not up for measuring, and sunroom lug footer not dug.
B111 03	4/03/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001750611
	4/03/09	AP	CUSTOMER PAID REINSPECTION FEE. RESCHED FOR FRI 4-3-09
R427 01	4/28/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001760859
	4/28/09	CA	
R427 02	4/29/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001761451
	4/29/09	DA	1. drain and water line tests not complete. 2. No plumbing boots. 3. Need nail guards for electrical horizontals in bonus room and front bedroom. 4. Need fire caulk for electrical at top plate to left of computer room door. 5. Kitchen window not installed. 6. E truss in sunroom need uplift straps at joint 5. Okay to side and insulate.
I129 01	4/30/09	DT	R*INSULATION INSPECTION VRU #: 001762293
	4/30/09	DA	1. Kitchen window still not installed. 2. E trusses still not strapped for uplift. 3. Trap above panel in garage must be insulated.
R427 03	4/30/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001762319
	4/30/09	DA	1. Kitchen window still not installed. 2. E trusses still not strapped for uplift. 3. Trap above panel in garage must be insulated.

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential

PERMIT NUMBERS

Owner: Carrasco Land Devel

Building Permit No.: _____

911 Address: _____

Electrical Permit No.: _____

184 Blue Oak Dr.

Insulation Permit No.: _____

State: _____ Zip Code: _____

Plumbing Permit No.: _____

Mech. Permit No.: _____

Date: 7-9-09

MFG. Home: _____

Ken Stahl

Building Official

0950021512