

PREPARED 3/05/09, 13:58:31
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 26
DATE 3/06/09

ADDRESS . . : 16 EASTWOOD CT
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER . . . : WOODSHIRE PARTNERS LLC
PARCEL . . . : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED	INSP	DESCRIPTION
	COMPLETED	RESULT	RESULTS/COMMENTS

B101 01	3/06/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	<u>3/6/09</u>	<u>AP DI</u>	

COMMENTS AND NOTES

ADDRESS . . : 16 EASTWOOD CT
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER . . . : WOODSHIRE PARTNERS LLC
PARCEL . . . : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	TI	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001749589
	<u>3/31/09</u>	<u>AR DJ</u>	

COMMENTS AND NOTES

ADDRESS : 16 EASTWOOD CT
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001749589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION VRU #: 001754159
B105 01	4/13/09	TI	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357

413

AP

KS

COMMENTS AND NOTES

*had to wait bottom chord to
sill on left side +
part of right side.*

ADDRESS : 128 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09 3/06/09	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
B103 01	3/31/09 3/31/09	DT AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001'49589
A814 01	4/13/09 4/21/09	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159 128 blue oak dr lot 201
B105 01	4/13/09 4/13/09	KS AP	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357 Had to nail about 10 bottom chord to sill.
R427 01	5/12/09 <u>5/12/09</u>	TI <u>DA DT</u>	FOUR TRADE ROUGH IN >2500 VRU #: 001766542

COMMENTS AND NOTES

977

DO NOT REMOVE!

Harnett County Inspection Department

102 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7527 • Fax: (910) 893-2793

Job Name: Caviness Land Date: _____

Address: 128 Blue Oak Dr.

Lot No.: 201 Permit No.: _____

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|-------------------------------------|----------------------------------|--|-------------------------------------|---------------------------------------|--|--------------------------------------|
| <input type="checkbox"/> Footing | <input type="checkbox"/> Foundation | <input type="checkbox"/> Bldg. | <input type="checkbox"/> Elec. | <input type="checkbox"/> Plumb. | <input type="checkbox"/> Mech. | <input checked="" type="checkbox"/> Insul. | <input type="checkbox"/> Floor Fram. |
| <input type="checkbox"/> Floor Slab | <input type="checkbox"/> MFG. Home | <input type="checkbox"/> Modular | <input type="checkbox"/> Damp/Water Proof. | <input type="checkbox"/> Structural | <input type="checkbox"/> Wall Sheath. | <input type="checkbox"/> Other | |

Violations Found: 1) Need correct truss documents
2) No water in stand pipe
3) Leak on 3 inch drain under master
4) Need fire caulk in several locations.
Do not side or insulate.

Code Enforcement Official

Date: 5/12/09

Signature: [Handwritten Signature]

It is unlawful for any sub contractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation.

ADDRESS : 128 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -41-
APPL NUMBER : 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001749589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159
	4/21/09	AP	128 blue oak dr lot 201
B105 01	4/13/09	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357
	4/13/09	AP	Had to nail about 10 bottom chord to sill.
R427 01	5/12/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001766542
	5/12/09	DA	1. Need complete, organized set of truss documents. 2. Fire caulk needed throughout house. 3. No water in stand pipe. 4. Leak on three nch drain at clean out under master. 5. Insulation baffles not secure. Do not side or insulate.
R427 02	5/13/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001767441
	5/13/09	DP	1. 3 inch drain still leaking at clean out. 2. Truss documents do not match B trusses. Okay to side
R427 03	5/15/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001768902
	5/15/09	DA DT	

COMMENTS AND NOTES

DO NOT REMOVE!

Harnett County Inspection Department

102 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7527 • Fax: (910) 893-2793

Job Name: Caviness Date: 5/15/09

Address: 128 Blue Oak

Lot No.: 301 Permit No.: _____

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|-------------------------------------|----------------------------------|--|-------------------------------------|---------------------------------------|---------------------------------|--------------------------------------|
| <input type="checkbox"/> Footing | <input type="checkbox"/> Foundation | <input type="checkbox"/> Bldg. | <input type="checkbox"/> Elec. | <input type="checkbox"/> Plumb. | <input type="checkbox"/> Mech. | <input type="checkbox"/> Insul. | <input type="checkbox"/> Floor Fram. |
| <input type="checkbox"/> Floor Slab | <input type="checkbox"/> MFG. Home | <input type="checkbox"/> Modular | <input type="checkbox"/> Damp/Water Proof. | <input type="checkbox"/> Structural | <input type="checkbox"/> Wall Sheath. | <input type="checkbox"/> Other | |

Violations Found: 1) DE GIR cross not strapped for uplift.
2) Leak on 3rd floor

Code Enforcement Official _____ Date: _____

Signature: [Handwritten Signature]

It is unlawful for any sub contractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation.

ADDRESS . . : 128 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . : WOODSHIRE PARTNERS LLC PHONE :
PARCEL . . : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001749589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159
	4/21/09	AP	128 blue oak dr lot 201
B105 01	4/13/09	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357
	4/13/09	AP	Had to nail about 10 bottom chord to sill.
R427 01	5/12/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001766542
	5/12/09	DA	1. Need complete, organized set of truss documents. 2. Fire caulk needed throughout house. 3. No water in stand pipe. 4. Leak on three nch drain at clean out under master. 5. Insulation baffles not secure. Do not side or insulate.
R427 02	5/13/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001767441
	<u>5/13/09</u>	<u>DP DT</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 128 BLUE OAK DR
 CONTRACTOR : CAVINESS LAND DEVELOPMENT
 OWNER : WOODSHIRE PARTNERS LLC
 PARCEL : 01-0536-06- -0028- -41-
 APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
 PHONE : (919) 481-0503
 PHONE :

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001749589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159
	4/21/09	AP	128 blue oak dr lot 201
B105 01	4/13/09	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357
	4/13/09	AP	Had to nail about 10 bottom chord to sill.
R427 01	5/12/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001766542
	5/12/09	DA	1. Need complete, organized set of truss documents. 2. Fire caulk needed throughout house. 3. No water in stand pipe. 4. Leak on three inch drain at clean out under master. 5. Insulation baffles not secure. Do not side or insulate.
R427 02	5/13/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001767441
	5/13/09	DP	1. 3 inch drain still leaking at clean out. 2. Truss documents do not match B trusses. Okay to side
R427 03	5/15/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001768902
	5/15/09	DA	1. EGDR trusses not strapped for enough uplift. 2. Leak on three inch drain clean out.
R427 04	5/20/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001770577
	<u>5/20/09</u>	<u>AP DT</u>	
I129 01	5/20/09	TI	R*INSULATION INSPECTION TIME: 17:00 VRU #: 00177058!
	<u>5/20/09</u>	<u>AP DT</u>	

COMMENTS AND NOTES

ADDRESS : 128 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
 OWNER : WOODSHIRE PARTNERS LLC PHONE :
 PARCEL : 01-0536-06- -0028- -41-
 APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 193 JB

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001719589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159
	4/21/09	AP	128 blue oak dr lot 201
B105 01	4/13/09	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357
	4/13/09	AP	Had to nail about 10 bottom chord to sill.
R427 01	5/12/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001766542
	5/12/09	DA	1. Need complete, organized set of truss documents. 2. Fire caulk needed throughout house. 3. No water in stand pipe. 4. Leak on three inch drain at clean out under master. 5. Insulation baffles not secure. Do not side or insulate.
R427 02	5/13/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001767441
	5/13/09	DP	1. 3 inch drain still leaking at clean out. 2. Truss documents do not match B trusses. Okay to side
R427 03	5/15/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001768902
	5/15/09	DA	1. EGDR trusses not strapped for enough uplift. 2. Leak on three inch drain clean out.
R427 04	5/20/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001770577
	5/20/09	AP	
I129 01	5/20/09	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001770585
	5/20/09	AP	
H824 01	7/01/09	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001790000
	7/01/09	AP	T/S: 07/02/2009 10:56 AM S STEWART T/S: 07/02/2009 11:10 AM S STEWART
R431 01	12/10/09	TI	FOUR TRADE FINAL >2500 VRU #: 001859958
	<u>12/10/09</u>	<u>DA DT</u>	

COMMENTS AND NOTES

VIOLATION NOTICE

DO NOT REMOVE!

Harnett County Inspection Department

108 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7525 Ext. 1 • Fax: (910) 893-2793

Job Name: Lawrence Land Date: 12/10/09

Address: 128 Blue Oak Dr

Lot No.: 201 Permit No.: _____

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|-------------------------------------|----------------------------------|--|-------------------------------------|---------------------------------------|---------------------------------|---|
| <input type="checkbox"/> Footing | <input type="checkbox"/> Foundation | <input type="checkbox"/> Bldg. | <input type="checkbox"/> Elec. | <input type="checkbox"/> Plumb. | <input type="checkbox"/> Mech. | <input type="checkbox"/> Insul. | <input checked="" type="checkbox"/> Floor Fram. |
| <input type="checkbox"/> Floor Slab | <input type="checkbox"/> MFG. Home | <input type="checkbox"/> Modular | <input type="checkbox"/> Damp/Water Proof. | <input type="checkbox"/> Structural | <input type="checkbox"/> Wall Sheath. | <input type="checkbox"/> Other | |

Violations Found: 1) D/S sink not caulked

2) Light missing outside master bedroom

3) Master tub outlet not wired

4) Need ladder to access attic

Code Enforcement Official

Signature: [Signature] Date: _____

It is unlawful for any subcontractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation

ADDRESS : 128 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001749589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159
	4/21/09	AP	128 blue oak dr lot 201
B105 01	4/13/09	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357
	4/13/09	AP	Had to nail about 10 bottom chord to sill.
R427 01	5/12/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001766542
	5/12/09	DA	1. Need complete, organized set of truss documents. 2. Fire caulk needed throughout house. 3. No water in stand pipe. 4. Leak on three inch drain at clean out under master. 5. Insulation baffles not secure. Do not side or insulate.
R427 02	5/13/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001767441
	5/13/09	DP	1. 3 inch drain still leaking at clean out. 2. Truss documents do not match B trusses. Okay to side
R427 03	5/15/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001768902
	5/15/09	DA	1. EGDR trusses not strapped for enough uplift. 2. Leak on three inch drain clean out.
R427 04	5/20/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001770577
	5/20/09	AP	
I129 01	5/20/09	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001770589
	5/20/09	AP	
H824 01	7/01/09	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001790000
	7/01/09	AP	T/S: 07/02/2009 10:56 AM S STEWART ----- T/S: 07/02/2009 11:10 AM S STEWART -----
R431 01	12/10/09	DT	FOUR TRADE FINAL >2500 VRU #: 001859958
	12/10/09	DA	1. Master tub receptacle not wired. 2. Missing light outside master bedroom. 3. Downstairs bath sink not caulked. 4. Need ladder to access attic. T/S: 12/10/2009 02:56 PM DETAYLOR -----
R431 02	12/30/09	TI	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001866060
			T/S: 12/29/2009 11:40 AM VBROWN -----

12-30 DP KS

COMMENTS AND NOTES

ADDRESS : 128 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001'49589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159
	4/21/09	AP	128 blue oak dr lot 201
B105 01	4/13/09	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357
	4/13/09	AP	Had to nail about 10 bottom chord to sill.
R427 01	5/12/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001766542
	5/12/09	DA	1. Need complete, organized set of truss documents. 2. Fire caulk needed throughout house. 3. No water in stand pipe. 4. Leak on three nch drain at clean out under master. 5. Insulation baffles not secure. Do not side or insulate.
R427 02	5/13/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001767441
	5/13/09	DP	1. 3 inch drain still leaking at clean out. 2. Truss documents do not match B trusses. Okay to side
R427 03	5/15/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001768902
	5/15/09	DA	1. EGDR trusses not strapped for enough uplift. 2. Leak on three inch drain clean out.
R427 04	5/20/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001770577
	5/20/09	AP	
I129 01	5/20/09	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 00177058!
	5/20/09	AP	
H824 01	7/01/09	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 0017900' 0
	7/01/09	AP	T/S: 07/02/2009 10:56 AM SSTEWARD ----- T/S: 07/02/2009 11:10 AM SSTEWARD -----
R431 01	12/10/09	DT	FOUR TRADE FINAL >2500 VRU #: 001859958
	12/10/09	DA	1. Master tub receptacle not wired. 2. Missing light outside master bedroom. 3. Downstairs bath sink not caulked. 4. Need ladder to access attic. T/S: 12/10/2009 02:56 PM DETAYLOR -----
R431 02	12/30/09	KS	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001866060
	12/30/09	DP	T/S: 12/29/2009 11:40 AM VBROWN ----- House locked--unable to do inspection \$50 re-inspection fee

ADDRESS . : 128 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER . . : WOODSHIRE PARTNERS LLC
PARCEL . . : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SF)

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R431 03	12/31/09	TI <i>DP-IMR</i>	T/S: 12/30/2009 09:50 AM KSLATTUM ----- FOUR TRADE FINAL >2500 VRU #: 001866490

----- COMMENTS AND NOTES -----

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DO NOT REMOVE

DATE: 12-31-09

PERMIT # 09-50021514

ADDRESS: 128 blue oak

VIOLATIONS:

1. Drain line to dishwasher not installed
2. Recept. on back porch is required
3. Bigger ladder needed to inspect the attic
4. R-38 is required in attics
5. Microwave circuit must be 20 amp and the outlet must be a 20 amp also, not 15/20 (Nec-table 210-21.b)
6. The outside a/c units are not fused correctly

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

ADDRESS : 128 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : C/VINNESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER : WOODSHIRE PARTNERS LLC PHONE :
PARCEL : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
S/D 2ND LEFT LOT 193 JB

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001749589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159
	4/21/09	AP	128 blue oak dr lot 201
B105 01	4/13/09	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357
	4/13/09	AP	Had to nail about 10 bottom chord to sill.
R427 01	5/12/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001766542
	5/12/09	DA	1. Need complete, organized set of truss documents. 2. Fire caulk needed throughout house. 3. No water in stand pipe. 4. Leak on three inch drain at clean out under master. 5. Insulation baffles not secure. Do not side or insulate.
R427 02	5/13/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001767441
	5/13/09	DP	1. 3 inch drain still leaking at clean out. 2. Truss documents do not match B trusses. Okay to side
R427 03	5/15/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001768902
	5/15/09	DA	1. EGDR trusses not strapped for enough uplift. 2. Leak on three inch drain clean out.
R427 04	5/20/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001770577
	5/20/09	AP	
I129 01	5/20/09	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001770581
	5/20/09	AP	
H824 01	7/01/09	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001790000
	7/01/09	AP	T/S: 07/02/2009 10:56 AM S STEWART ----- T/S: 07/02/2009 11:10 AM S STEWART -----
R431 01	12/10/09	DT	FOUR TRADE FINAL >2500 VRU #: 001859958
	12/10/09	DA	1. Master tub receptacle not wired. 2. Missing light outside master bedroom. 3. Downstairs bath sink not caulked. 4. Need ladder to access attic. T/S: 12/10/2009 02:56 PM DETAYLOR -----
R431 02	12/30/09	KS	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001866060
	12/30/09	DP	T/S: 12/29/2009 11:40 AM VBROWN ----- House locked--unable to do inspection \$50 re-inspection fee

ADDRESS . . : 128 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CIVINNESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . : WOODSHIRE PARTNERS LLC PHONE :
PARCEL . . : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R431 03	12/31/09 12/31/09	MP DP	T/S: 12/30/2009 09:50 AM KSLATTUM ----- FOUR TRADE FINAL >2500 VRU #: 001866490 T/S: 12/31/2009 10:48 AM MREARIC ----- X. drain line to dishwasher is not installed 2. recept on back porch is required X. bigger ladder is needed for attic inspectin X. R-38 is required in attic X. microwave circuit must be a 20 amp and the outlet must be a <u>20 amp also</u> .. not 15/20 nec table 210-21.b X. the outside a/c units are not fused correctly
R431 04	1/26/10 <u>1-26-10</u>	TI DP TH	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001875749 T/S: 01/25/2010 10:55 AM VBROWN -----

----- COMMENTS AND NOTES -----

ADDRESS : 128 BLUE OAK DR SUBDIV: WOODSHIRE PH 5
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
 OWNER : WOODSHIRE PARTNERS LLC PHONE :
 PARCEL : 01-0536-06- -0028- -41-
 APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 27 W TO NURSERY RD TO LEMULE BLACK RD
 S/D 2ND LEFT LOT 193 JB

STRUCTURE: 000 000 57.3X49.3 3BDR SLAB W/ GARAGE
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001740927
	3/06/09	AP	
B103 01	3/31/09	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001749589
	3/31/09	AP	
A814 01	4/13/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001754159
	4/21/09	AP	128 blue oak dr lot 201
B105 01	4/13/09	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001754357
	4/13/09	AP	Had to nail about 10 bottom chord to sill.
R427 01	5/12/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001766542
	5/12/09	DA	1. Need complete, organized set of truss documents. 2. Fire caulk needed throughout house. 3. No water in stand pipe. 4. Leak on three nch drain at clean out under master. 5. Insulation baffles not secure. Do not side or insulate.
R427 02	5/13/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001767441
	5/13/09	DP	1. 3 inch drain still leaking at clean out. 2. Truss documents do not match B trusses. Okay to side
R427 03	5/15/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001768902
	5/15/09	DA	1. EGDR trusses not strapped for enough uplift. 2. Leak on three inch drain clean out.
R427 04	5/20/09	DT	FOUR TRADE ROUGH IN >2500 VRU #: 001770577
	5/20/09	AP	
I129 01	5/20/09	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001770585
	5/20/09	AP	
H824 01	7/01/09	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001790000
	7/01/09	AP	T/S: 07/02/2009 10:56 AM S STEWART ----- T/S: 07/02/2009 11:10 AM S STEWART -----
R431 01	12/10/09	DT	FOUR TRADE FINAL >2500 VRU #: 001859958
	12/10/09	DA	1. Master tub receptacle not wired. 2. Missing light outside master bedroom. 3. Downstairs bath sink not caulked. 4. Need ladder to access attic. T/S: 12/10/2009 02:56 PM DETAYLOR -----
R431 02	12/30/09	KS	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001866060
	12/30/09	DP	T/S: 12/29/2009 11:40 AM VBROWN ----- House locked--unable to do inspection \$50 re-inspection fee

CONTINUED ONTO NEXT PAGE

ADDRESS : 128 BLUE OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-06- -0028- -41-
APPL NUMBER: 09-50021514 CP NEW RESIDENTIAL (SFD)

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R431 03	12/31/09 12/31/09	MR DP	T/S: 12/30/2009 09:50 AM KSLATTUM ----- FOUR TRADE FINAL >2500 VRU #: 001866490 T/S: 12/31/2009 10:48 AM MREARIC ----- 1. drain line to dishwasher is not installed 2. recept on back porch is required 3. bigger ladder is needed for attic inspectin 4. R-38 is required in attic 5. microwave circuit must be a 20 amp and the outlet mus: be a 20 amp also.. not 15/20 nec table 210-21.b 6. the outside a/c units are not fused correctly
R431 04	1/26/10 1/26/10	JH DP	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001875749 T/S: 01/25/2010 10:55 AM VBROWN ----- Previous violat:ons # 5 microwave not on 20amp circuit & also need receptacle on front porch.-
R431 05	2/03/10 <u>2/3/10</u>	TI <u>AS DT</u>	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001879022 T/S: 02/02/2010 11:57 AM VBROWN -----

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential

Conditional Use Permit No.: _____

Type of Construction: _____

Building Permit No.: _____

Owner of Building: Caviness Land Dev.

Electrical Permit No.: _____

Building Address: 128 Blue Oak Dr.

Insulation Permit No.: _____

Zoning District: Lilling on, NC 27546

Plumbing Permit No.: _____

Zoning Permit No.: _____

Mech. Permit No.: OT 50021514

Date: 2/3/10

Envir. C.O. No.: _____

[Signature]
Building Official

Zoning Official