

Property ID:
 Lot #:
 File #:
 Code:

**SOIL/SITE EVALUATION
 for ON-SITE WASTEWATER SYSTEM**

Owner:
 Address:
 Proposed Facility: *SFP*
 Location of Site:
 Water Supply: Public Individual Well
 Evaluation Method: Auger Boring Pit
 Type of Wastewater: Sewage Industrial Process

Applicant: *21847*
 Date Evaluated: *4-9-13-09*
 Property Size:
 Property Recorded:

P R O F I L E #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1 2 3	<i>L 3-4%</i>	<i>0-8</i>	<i>SL</i>	<i>FR GR NSNP</i>					<i>.3</i>
		<i>8-42</i>	<i>SCL</i>	<i>FR 1 1/2 BK S.P.</i>	<i>36" 7.54K 42</i>				
3	<i>L 3-4%</i>	<i>0-30</i>	<i>SL</i>	<i>FR GR NSNP</i>					<i>.4</i>
		<i>30-48</i>	<i>SCL</i>	<i>FR 1 1/2 BK S.P.</i>	<i>44" 7.54K 42</i>				
4	<i>L 4%</i>	<i>0-30</i>	<i>SL</i>	<i>FR GR NSNP</i>					<i>.4</i>
		<i>30-48</i>	<i>SCL</i>	<i>FR 1 1/2 BK S.P.</i>	<i>42" 7.89K 42</i>				

Description	Initial System	Repair System
Available Space (.1945)	<i>✓</i>	<i>✓</i>
System Type(s)	<i>25%</i>	<i>25%</i>
Site LTAR	<i>.3</i>	<i>.3 → .4</i>

Other Factors (.1946): _____
 Site Classification (.1948): *PS*
 Evaluated By: *JK*
 Others Present: