Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:
Address:
Applicant:

Proposed Facility: 4 BEDROOM HOME Design Flow (.1949): 480 gpd
Location of Site:
Date Evaluated: 5/11/09
Property Size:
Property Recorded:

Water Supply: [X] Public [ ] Individual [ ] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	OTHER PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	LS 0-2%	0-22"	G S	VFR NS/NP					PS .55
		22-48"	SBK SCL	FR SS/NP					
2		0-28"	G S	VFR NS/NP					PS .55
		28-48"	SBK SCL	FR SS/NP					
3		0-24"	G S	VFR NS/NP					PS .55
		24-48"	SBK SCL	FR SS/NP					

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	CON	CON
Site LTAR	.55	.55

3 x 100' @ 24"-30"
= REPAIR

Other Factors (.1946):
Site Classification (.1948): PS
Evaluated By: OT
Others Present: BM