Division of Environmental Health
On-site Wastewater Section

Property ID:

Lot #:

File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:		Applicant	:	
Address:			Date Evaluated: 5∫&	1)09
Proposed Facility: 4	BROOM HUME Design Flow (.1949	1): 480-pd	Property Size:	101
Location of Site: •		5.	Property Recorded:	
Water Supply:	Public [] Individual	[] Well	[] Spring	
Evaluation Method:	N Auger Boring	[]Pit	[] Cut	[]Other
Type of Wastewater:	∭ Sewage	[] Industrial Process	[] Mixed	

P R O F I	.1940	1 1	SOIL MORPHOLOGY		PROFILE FACTORS				
L E #	Landscape Position/ Slope%		.1941 Structure/ Texture	,1941 Consistence Mineralogy	1942 Soil Wetness/** Color	1042	4000	.1944	Class
1	L5 0:296	0-32	GS	neu velni) Olass	nonz	PS
		37-128	888 Sta	FR SS INP					.6
							<u> </u>		4
2		034	6 5	ufo walmp					1
			SBX SYSCL	to solve					P 3
		40.258"	C S	MER HOLND	भूज . १४४९				ي, و
	ŀ							ļ	
	-	-							
	}								
	F								

Description	Initial System	Repair System
Available Space (.1945)	\checkmark	1
System Type(s)	Con	256260
Site LTAR	. 6	. 6

Other Factors (.1946):

Site Classification (.1948): \$\infty\$

Evaluated By:

Others Present: