Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

# SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:
Address:
Applicant:
Proposed Facility: 3 BEDROOM HOME Design Flow (.1949): 360 gpd
Date Evaluated:
Property Size:
Property Recorded:
Location of Site:
Water Supply: [X] Public [ ] Individual [ ] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

| PROFILE # | .1940 Landscape Position/ Slope% | Horizon Depth (IN.) | SOIL MORPHOLOGY .1941 | | OTHER PROFILE FACTORS | | | | Profile Class & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| | | | .1941 Structure/ Texture | .1941 Consistence Mineralogy | .1942 Soil Wetness/ Color | .1943 Soil Depth (IN.) | .1956 Sapro Class | .1944 Restr Horiz | |
| 1 | LS 2-5% | 0-24 | G S | VFR NS/NP | | | | | PS .5 |
| | | 24-40" | SBK SCL | FR SS/SP | | | | | |
| | | | | | | | | | |
| 2 | | 0-18 | G S | VFR NS/NP | | | | | PS .5 |
| | | 18-40" | SBK SCL | FR SS/SP | | | | | |

| Description | Initial System | Repair System |
|---|---|---|
| Available Space (.1945) | ✓ | ✓ |
| System Type(s) | PUMP 25% RED | PUMP 25% RED |
| Site LTAR | .5 | .5 |

Other Factors (.1946):
Site Classification (.1948): PS
Evaluated By: GT
Others Present: BM