

PREPARED: 1/12/10, 14:00:07  
Harnett County

INSPECTION TICKET  
INSPECTOR: IVR

PAGE 9  
DATE 1/13/10

-----  
ADDRESS : 5715 CHRISTIAN LIGHT RD SUBDIV:  
CONTRACTOR : PHONE :  
OWNER : LAMBERT COLBY & LYNN PHONE : (919) 567-0634  
PARCEL : 05-0634- - -0038- - -  
APPL NUMBER: 09-50022543 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : FROM 401 TRUN LEFT ON CHIRSTIAN LIGHT  
RD TRAVEL 6 MILES PROEPRTY IS ON LEFT  
BEOFRE 5860 CHRSTIAN LIGHT RD  
T/S: 07/28/2009 03:25 PM JBRCK ----

-----  
STRUCTURE: 000 000 85X56 4BDR CRAWL W/ GARAGE  
FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . . : 3000000.00 PROPOSED USE . . . . . : SFD  
SEPTIC - EXISTING? . . . . : NEW TANK WATER SUPPLY . . . . . : COUNTY

-----  
PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/13/10 <u>1/13/10</u>	TI <u>APB</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001870112

-----  
COMMENTS AND NOTES  
-----


**Howerton Services, LLC**  
7316 Laketree Drive  
Raleigh, NC 27615  
(919) 270-3460

October 5, 2009

Subject: Lambert Residence  
5829 Christian Light Road  
Fuquay Varina, NC 27526

The following is a plan revision to the above referenced home site:

The 24" width for the continuous footings shown in the plans may be revised to a 20" width, and the depth remaining the same. This change meets all requirements of the North Carolina Building Code for Residences.



ADDRESS : 5715 CHRISTIAN LIGHT RD  
CONTRACTOR :  
OWNER : LAMBERT COLBY & LYNN  
PARCEL : 05-0634- - -0038- - -  
APPL NUMBER: 09-50022543 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : FROM 401 TRUN LEFT ON CHIRSTIAN LIGHT  
RD TRAVEL 6 MILES PROEPRTY IS ON LEFT  
BEOFRE 5860 CHRSTIAN LIGHT RD  
T/S: 07/28/2009 03:25 PM JBROCK ----

STRUCTURE: 000 000 85X56 4BDR CRAWL W/ GARAGE  
FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3000000.00  
SEPTIC - EXISTING? : NEW TANK  
PROPOSED USE : SFD  
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/13/10 1/13/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001870112 1. Footing ok to pour. After the foundation inspection is done and passed, but before the open floor inspection is called in, please have the garage slab prepped and ready to pour. There are structural footings in the garage slab we will need to see before the concrete is placed. We can inspect the garage slab along with the open floor inspection.
B103 01	1/28/10 <u>1-28-10</u>	TI <u>APBS</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001876900

----- COMMENTS AND NOTES -----

ADDRESS : 5715 CHRISTIAN LIGHT RD SUBDIV:  
 CONTRACTOR : PHONE :  
 OWNER : LAMBERT COLBY & LYNN PHONE : (919) 567-0634  
 PARCEL : 05-0634- - -0038- - -  
 APPL NUMBER: 09-50022543 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : FROM 401 TRUN LEFT ON CHIRSTIAN LIGHT  
 RD TRAVEL 6 MILES PROEPRTY IS ON LEFT  
 BEOFRE 5860 CHRSTIAN LIGHT RD  
 T/S: 07/28/2009 03:25 PM JBROCK ----

STRUCTURE: 000 000 85X56 4BDR CRAWL W/ GARAGE  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/13/10 1/13/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001870112 1. Footing ok to pour. After the foundation inspection is done and passed, but before the open floor inspection is called in, please have the garage slab prepped and ready to pour. There are structural footings in the garage slab we will need to see before the concrete is placed. We can inspect the garage slab along with the open floor inspection.
B103 01	1/28/10 1/28/10	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001876900 T/S: January 28, 2010 10:20 AM BSUTTON
A814 01	2/03/10 2/04/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001879071 5715 christian light rd # on house and by drive fuquay varina 27526 T/S: 02/04/2010 01:09 PM TWARD
B105 01	2/12/10 <i>2/12/10</i>	TI <i>APB</i>	R*OPEN FLOOR VRU #: 001882001

COMMENTS AND NOTES

ADDRESS : 5715 CHRISTIAN LIGHT RD  
 CONTRACTOR :  
 OWNER : LAMBERT COLBY & LYNN  
 PARCEL : 05-0634- - -0038- - -  
 APPL NUMBER: 09-50022543 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : FROM 401 TRUN LEFT ON CHIRSTIAN LIGHT  
 RD TRAVEL 6 MILES PROEPRTY IS ON LEFT  
 BEOFRE 5860 CHRSTIAN LIGHT RD  
 T/S: 07/28/2009 03:25 PM JBROCK ----

**STRUCTURE: 000 000 85X56 4BDR CRAWL W/ GARAGE**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00  
 SEPTIC - EXISTING? : NEW TANK  
 PROPOSED USE : SFD  
 WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/13/10 1/13/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001870112 1. Footing ok to pour. After the foundation inspection is done and passed, but before the open floor inspection is called in, please have the garage slab prepped and ready to pour. There are structural footings in the garage slab we will need to see before the concrete is placed. We can inspect the garage slab along with the open floor inspection.
B103 01	1/28/10 1/28/10	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001876900 T/S: January 28, 2010 10:20 AM BSUTTON -----
A814 01	2/03/10 2/04/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001879071 5715 christian light rd # on house and by drive ----- fuquay varina 27526 T/S: 02/04/2010 01:09 PM TWARD -----
B105 01	2/12/10 2/12/10	BS AP	R*OPEN FLOOR VRU #: 001882001 T/S: February 12, 2010 02:37 PM BSUTTON -----
B111 01	2/18/10 <u>2.18.10</u>	TI <u>APB</u>	R*BLDG SLAB INSP VRU #: 001884147

COMMENTS AND NOTES

ADDRESS : 5715 CHRISTIAN LIGHT RD SUBDIV:  
 CONTRACTOR : PHONE :  
 OWNER : LAMBERT COLBY & LYNN PHONE : (919) 567-0634  
 PARCEL : 05-0634- - -0038- - -  
 APPL NUMBER: 09-50022543 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : FROM 401 TRUN LEFT ON CHIRSTIAN LIGHT  
 RD TRAVEL 6 MILES PROEPRTY IS ON LEFT  
 BEOFRE 5860 CHRSTIAN LIGHT RD  
 T/S: 07/28/2009 03:25 PM JBROCK ----

**STRUCTURE: 000 000 85X56 4BDR CRAWL W/ GARAGE**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/13/10 1/13/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001870112 1. Footing ok to pour. After the foundation inspection is done and passed, but before the open floor inspection is called in, please have the garage slab prepped and ready to pour. There are structural footings in the garage slab we will need to see before the concrete is placed. We can inspect the garage slab along with the open floor inspection.
B103 01	1/28/10 1/28/10	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001876900 T/S: January 28, 2010 10:20 AM BSUTTON -----
A814 01	2/03/10 2/04/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001879071 5715 christian light rd # on house and by drive ----- fuquay varina 27526 T/S: 02/04/2010 01:09 PM TWARD -----
B105 01	2/12/10 2/12/10	BS AP	R*OPEN FLOOR VRU #: 001882001 T/S: February 12, 2010 02:37 PM BSUTTON -----
B111 01	2/18/10 2/18/10	BS AP	R*BLDG SLAB INSP VRU #: 001884147 T/S: February 18, 2010 01:42 PM BSUTTON -----
R427 01	4/12/10 <u>4/12/10</u>	TI <u>APBS</u>	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001907617 T/S: 04/09/2010 07:58 AM DJOHNSON -----

COMMENTS AND NOTES

ADDRESS : 5715 CHRISTIAN LIGHT RD SUBDIV:  
 CONTRACTOR : PHONE :  
 OWNER : LAMBERT COLBY & LYNN PHONE : (919) 567-0634  
 PARCEL : 05-0634- - -0038- - -  
 APPL NUMBER: 09-50022543 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : FROM 401 TRUN LEFT ON CHIRSTIAN LIGHT  
 RD TRAVEL 6 MILES PROEPRTY IS ON LEFT  
 BEOFRE 5860 CHRSTIAN LIGHT RD  
 T/S: 07/28/2009 03:25 PM JBROCK ----

**STRUCTURE: 000 000 85X56 4BDR CRAWL W/ GARAGE**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/13/10 1/13/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001870112 1. Footing ok to pour. After the foundation inspection is done and passed, but before the open floor inspection is called in, please have the garage slab prepped and ready to pour. There are structural footings in the garage slab we will need to see before the concrete is placed. We can inspect the garage slab along with the open floor inspection.
B103 01	1/28/10 1/28/10	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001876900 T/S: January 28, 2010 10:20 AM BSUTTON -----
A814 01	2/03/10 2/04/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001879071 5715 christian light rd # on house and by drive ----- fuquay varina 27526 T/S: 02/04/2010 01:09 PM TWARD -----
B105 01	2/12/10 2/12/10	BS AP	R*OPEN FLOOR VRU #: 001882001 T/S: February 12, 2010 02:37 PM BSUTTON -----
B111 01	2/18/10 2/18/10	BS AP	R*BLDG SLAB INSP VRU #: 001884147 T/S: February 18, 2010 01:42 PM BSUTTON -----
R427 01	4/12/10 4/12/10	BS DA	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001907617 T/S: 04/09/2010 07:58 AM DJOHNSON ----- 1. Need egress kits on casement windows upstairs. 2. Install platforms below bedroom windows upstairs to get sill height below 44 inches. 3. Test on plumbing below 100 psi. ok to side/insulate
I129 01	4/20/10 <u>4/20/10</u>	TI <u>TI</u>	R*INSULATION INSPECTION VRU #: 001912732
R427 02	4/20/10 <u>4/20/10</u>	TI <u>TI</u>	FOUR TRADE ROUGH IN >2500 VRU #: 001912740

COMMENTS AND NOTES

ADDRESS : 5715 CHRISTIAN LIGHT RD  
 CONTRACTOR :  
 OWNER : LAMBERT COLBY & LYNN  
 PARCEL : 05-0634- - -0038- - -  
 APPL NUMBER: 09-50022543 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : FROM 401 TRUN LEFT ON CHIRSTIAN LIGHT  
 RD TRAVEL 6 MILES PROEPRTY IS ON LEFT  
 BEOFRE 5860 CHRSTIAN LIGHT RD  
 T/S: 07/28/2009 03:25 PM JBROCK ----

STRUCTURE: 000 000 85X56 4BDR CRAWL W/ GARAGE  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00  
 SEPTIC - EXISTING? : NEW TANK  
 PROPOSED USE : SFD  
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/13/10 1/13/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001870112 1. Footing ok to pour. After the foundation inspection is done and passed, but before the open floor inspection is called in, please have the garage slab prepped and ready to pour. There are structural footings in the garage slab we will need to see before the concrete is placed. We can inspect the garage slab along with the open floor inspection.
B103 01	1/28/10 1/28/10	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001876900 T/S: January 28, 2010 10:20 AM BSUTTON
A814 01	2/03/10 2/04/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001879071 ✓ 5715 christian light rd # on house and by drive fuquay varina 27526 T/S: 02/04/2010 01:09 PM TWARD
B105 01	2/12/10 2/12/10	BS AP	R*OPEN FLOOR VRU #: 001882001 T/S: February 12, 2010 02:37 PM BSUTTON
B111 01	2/18/10 2/18/10	BS AP	R*BLDG SLAB INSP VRU #: 001884147 T/S: February 18, 2010 01:42 PM BSUTTON
R427 01	4/12/10 4/12/10	BS DA	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001907617 T/S: 04/09/2010 07:58 AM DJOHNSON 1. Need egress kits on casement windows upstairs. 2. Install platforms below bedroom windows upstairs to get sill height below 44 inches. 3. Test on plumbing below 100 psi. ok to side/insulate
I129 01	4/20/10 4/20/10	BS AP	R*INSULATION INSPECTION VRU #: 001912732 Check casement windows for egress kits at final
R427 02	4/20/10 4/20/10	BS AP	FOUR TRADE ROUGH IN >2500 VRU #: 001912740 Check casement windows for egress kits at final
H824 01	8/19/10 8/19/10	JM AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001972975 T/S: 08/20/2010 10:43 AM SSTEWARD T/S: 08/20/2010 10:43 AM SSTEWARD
R431 01	9/03/10	TI	FOUR TRADE FINAL >2500 VRU #: 001977503

9-3-10 DABS

COMMENTS AND NOTES



ADDRESS : 5715 CHRISTIAN LIGHT RD  
 SUBDIV: \_\_\_\_\_  
 CONTRACTOR : \_\_\_\_\_  
 PHONE : \_\_\_\_\_  
 OWNER : LAMBERT COLBY & LYNN  
 PHONE : (919) 567-0634  
 PARCEL : 05-0634- - -0038- - -  
 APPL NUMBER: 09-50022543 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : FROM 401 TRUN LEFT ON CHIRSTIAN LIGHT  
 RD TRAVEL 6 MILES PROEPRTY IS ON LEFT  
 BEOFRE 5860 CHRSTIAN LIGHT RD  
 T/S: 07/28/2009 03:25 PM JBROCK ----

STRUCTURE: 000 000 85X56 4BDR CRAWL W/ GARAGE  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/13/10 1/13/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001870112 1. Footing ok to pour. After the foundation inspection is done and passed, but before the open floor inspection is called in, please have the garage slab prepped and ready to pour. There are structural footings in the garage slab we will need to see before the concrete is placed. We can inspect the garage slab along with the open floor inspection.
B103 01	1/28/10 1/28/10	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001876900 T/S: January 28, 2010 10:20 AM BSUTTON -----
A814 01	2/03/10 2/04/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001879071 ✓ 5715 christian light rd # on house and by drive ----- fuquay varina 27526 T/S: 02/04/2010 01:09 PM TWARD -----
B105 01	2/12/10 2/12/10	BS AP	R*OPEN FLOOR VRU #: 001882001 T/S: February 12, 2010 02:37 PM BSUTTON -----
B111 01	2/18/10 2/18/10	BS AP	R*BLDG SLAB INSP VRU #: 001884147 T/S: February 18, 2010 01:42 PM BSUTTON -----
R427 01	4/12/10 4/12/10	BS DA	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001907617 T/S: 04/09/2010 07:58 AM DJOHNSON ----- 1. Need egress kits on casement windows upstairs. 2. Install platforms below bedroom windows upstairs to get sill height below 44 inches. 3. Test on plumbing below 100 psi. ok to side/insulate
I129 01	4/20/10 4/20/10	BS AP	R*INSULATION INSPECTION VRU #: 001912732 Check casement windows for egress kits at final-----
R427 02	4/20/10 4/20/10	BS AP	FOUR TRADE ROUGH IN >2500 VRU #: 001912740 Check casement windows for egress kits at final-----
H824 01	8/19/10 8/19/10	JM AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001972975 T/S: 08/20/2010 10:43 AM SSTEWARD ----- T/S: 08/20/2010 10:43 AM SSTEWARD -----
R431 01	9/03/10 9/03/10	BS DA	FOUR TRADE FINAL >2500 VRU #: 001977503 Need plastic under house and porches. 2 Receptacle missing in hall bath.
R431 02	9/10/10 <u>9-10-10</u>	TI <u>APBS</u>	FOUR TRADE FINAL >2500 VRU #: 001980689

COMMENTS AND NOTES

County of Harnett  
Building Inspections Department  
Planning Services

**Certificate of Compliance: \_\_\_\_\_ Occupancy: X**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

**Permit Numbers**

Name: Colby and Lynn Lambert

Building: 09-50022543

Electrical: 09-50022543

Address: 5715 Christian Light Road

Insulation: 09-50022543

Fuquay Varina NC 27526

Plumbing: 09-50022543

Mechanical: 09-50022543

MFG Home: NA NA NA NA

Date: 09-10-2010

Building Official: BSutton