Department of Environment, Health an ... Natural Resources Division of Environmental Health On-Site Wastewater Section

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Applicant:

Initial

System

CNU

Available Space (.1945)

System Type(s)

Site LTAR

Repair System

Conv

.8

Owner:

sheet: Property ID: Lot #: File #: Code:

Local Wate Evalu	ess: osed Facility tion of Site: r Supply: lation Metho of Wastewal	d:	Date Evaluated: 9 / / 6 Design Flow (.1949): Property Size: Property Recorded: Public Individual Well Spring Other Auger Boring Pit Cut Sewage Industrial Process Mixed							
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
	15 8%	0-48	CIU	VANSNE					5.8	
		0-48	615	VERDIA	·				5.8	
									<u> </u>	
						-				
Description		Initia	1 Paneis	System	Other Factors (10/6):					

Other Factors (.1946):

Site Classification (.1948):

Evaluated By:

Others Property

Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY

ABK-ANGULAR BLOCKY

PL-PLATY

STRUCTURE

SG-SINGLE GRAIN M- MASSIVE

PR-PRISMATIC

Show profile locations and other site features (dimensions, references or benchmark, and North)