
ADDRESS . . :	137 MEADOW RIDGE DR	SUBDIV:	
CONTRACTOR :	BECKER WILLIAM H	PHONE :	(910) 263-2700
OWNER . . :	SIMPSON JOHN W	PHONE :	(910) 892-3620
PARCEL . . :	02-1518- - -0200- -11-		
APPL NUMBER:	09-50022873 CP NEW RESIDENTIAL (SFD)		

DIRECTIONS : T/S: 09/18/2009 09:14 AM VBROWN ----
 MEADOW RIDGE DRIVE, MEADOWRIDGE SUB DIV
 #26. 421S TO DUNN, LEFT ON RED HILL
 CHURCH RD 2.3MI, RIGHT ON THREE BRIDGES
 RD 1.3MI, RIGHT ON MEADOW LARK RD
 0.1MI, LEFT ON MORRISON DRIVE 0.1MI,
 RIGHT ON MEADOW RIDGE DRIVE #26.

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/23/09 <u>10-23-09</u>	TI <u>ARBS</u>	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001841055 T/S: 10/22/2009 12:40 PM DJOHNSON ----- TSP ALSO. T/S: 10/22/2009 12:41 PM DJOHNSON -----

----- COMMENTS AND NOTES -----

ADDRESS : 137 MEADOW RIDGE DR SUBDIV:
 CONTRACTOR : BECKER WILLIAM H PHONE : (910) 263-2700
 OWNER : SIMPSON JOHN W PHONE : (910) 892-3620
 PARCEL : 02-1518- - -0200- -11-
 APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 09/18/2009 09:14 AM VBROWN ----
 MEADOW RIDGE DRIVE, MEADOWRIDGE SUB DIV
 #26. 421S TO DUNN, LEFT ON RED HILL
 CHURCH RD 2.3MI, RIGHT ON THREE BRIDGES
 RD 1.3MI, RIGHT ON MEADOW LARK RD
 0.1MI, LEFT ON MORRISON DRIVE 0.1MI,
 RIGHT ON MEADOW RIDGE DRIVE #26.

STRUCTURE: 000 000 28X32 3BDR 2BATH SFD WITH DECK CRAWL
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/23/09 10/26/09	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001841055 T/S: 10/22/2009 12:40 PM DJOHNSON ----- TSP ALSO T/S: 10/22/2009 12:41 PM DJOHNSON ----- T/S: 10/26/2009 12:08 PM NTART -----
A814 01	10/27/09	TI	ADDRESS CONFIRMATION VRU #: 001842293
B103 01	10/27/09 <u>10-27</u>	TI <u>AB</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001842301

----- COMMENTS AND NOTES -----

TSP is ready.
Permise # on attached page.

S Harnett County Special Notes Display

Functions: Help

10/26/2009 4:15:03 PM

Property address 137 MEADOW RIDGE DR 02
 PARCEL NUMBER 02-1518-0200-11

Source	Misc Info code	Note	Date
APPL	BPDN	T/S: 09/18/2009 09:14 AM VBROWN ---	9/18/09
APPL	BPDN	MEADOW RIDGE DRIVE, MEADOWRIDGE SUB DIV	9/18/09
APPL	BPDN	#26. 421S TO DUNN, LEFT ON RED HILL	9/18/09
APPL	BPDN	CHURCH RD 2.3MI, RIGHT ON THREE BRIDGES	9/18/09
APPL	BPDN	RD 1.3MI, RIGHT ON MEADOW LARK RD	9/18/09
APPL	BPDN	0.1MI, LEFT ON MORRISON DRIVE 0.1MI,	9/18/09
APPL	BPDN	RIGHT ON MEADOW RIDGE DRIVE #26.	9/18/09
APPL	BPDN	T/S: 10/26/2009 04:11 PM NTART -----	10/26/09
APPL	BPDN	PREMISE # 69865576 *****	10/26/09
APPL	BPMN	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	9/17/09
APPL	BPMN	PERMIT INCLUDES BLDG, ELEC, MECH, PLUMB	9/17/09
APPL	BPMN	INSULATION AND LAND USE.	9/17/09
APPL	BPMN	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	9/17/09

OK Exit Cancel

22873

ADDRESS : 137 MEADOW RIDGE DR SUBDIV:
 CONTRACTOR : BECKER WILLIAM H PHONE : (910) 263-2700
 OWNER : SIMPSON JOHN W PHONE : (910) 892-3620
 PARCEL : 02-1518- - -0200- -11-
 APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 09/18/2009 09:14 AM VBROWN ----
 MEADOW RIDGE DRIVE, MEADOWRIDGE SUB DIV
 #26. 421S TO DUNN, LEFT ON RED HILL
 CHURCH RD 2.3MI, RIGHT ON THREE BRIDGES
 RD 1.3MI, RIGHT ON MEADOW LARK RD
 0.1MI, LEFT ON MORRISON DRIVE 0.1MI,
 RIGHT ON MEADOW RIDGE DRIVE #26.
 T/S: 10/26/2009 04:11 PM NTART ----
 PREMISE # 69865576 *****

STRUCTURE: 000 000 28X32 3BDR 2BATH SFD WITH DECK CRAWL
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/23/09 10/26/09	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001841055 T/S: 10/22/2009 12:40 PM DJOHNSON ---- TSP ALSO T/S: 10/22/2009 12:41 PM DJOHNSON ---- T/S: 10/26/2009 12:08 PM NTART ---- T/S: 10/26/2009 04:12 PM NTART ----
B103 01	10/27/09 10/27/09	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001842301
A814 01	10/27/09 11/04/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001842293 137 MEADOW RIDGE DR DUNN 28334 T/S: 11/04/2009 03:59 PM TWARD ----
B105 01	10/30/09 10/30/09	BS AP	R*OPEN FLOOR VRU #: 001844232 T/S: October 30, 2009 01:24 PM BSUTTON ----
R425 01	12/07/09 <u>12-07</u>	TI <u>DA</u>	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001858059 T/S: 12/04/2009 09:17 AM VBROWN ----

----- COMMENTS AND NOTES -----

ADDRESS : 137 MEADOW RIDGE DR SUBDIV:
CONTRACTOR : BECKER WILLIAM H PHONE : (910) 263-2700
OWNER : SIMPSON JOHN W PHONE : (910) 892-3620
PARCEL : 02-1518- - -0200- -11-
APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 09/18/2009 09:14 AM VBROWN ----
MEADOW RIDGE DRIVE, MEADOWRIDGE SUB DIV
#26. 421S TO DUNN, LEFT ON RED HILL
CHURCH RD 2.3MI, RIGHT ON THREE BRIDGES
RD 1.3MI, RIGHT ON MEADOW LARK RD
0.1MI, LEFT ON MORRISON DRIVE 0.1MI,
RIGHT ON MEADOW RIDGE DRIVE #26.
T/S: 10/26/2009 04:11 PM NTART ----
PREMISE # 69865576 *****

STRUCTURE: 000 000 28X32 3BDR 2BATH SFD WITH DECK CRAWL
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/23/09 10/26/09	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001841055 T/S: 10/22/2009 12:40 PM DJOHNSON ----- TSP ALSO T/S: 10/22/2009 12:41 PM DJOHNSON ----- T/S: 10/26/2009 12:08 PM NTART ----- T/S: 10/26/2009 04:12 PM NTART -----
B103 01	10/27/09 10/27/09	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001842301
A814 01	10/27/09 11/04/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001842293 137 MEADOW RIDGE DR ----- DUNN 28334 T/S: 11/04/2009 03:59 PM TWARD -----
B105 01	10/30/09 10/30/09	BS AP	R*OPEN FLOOR VRU #: 001844232 T/S: October 30, 2009 01:24 PM BSUTTON -----
R425 01	12/07/09 12/07/09	KS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001858059 T/S: 12/04/2009 09:17 AM VBROWN ----- 1. Receptacles not installed beneath living room windsows 2. Bath vent not installed in half bath 3. Smoke detector outside master needs moving. OK to side and insulate T/S: 12/07/2009 01:09 PM KSLATTUM -----
I129 01	12/09/09 <u>12-09</u>	TI <u>AP</u>	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001859271 T/S: 12/08/2009 10:53 AM RDCONTE ----- INSULATION PER KEN
R425 02	12/09/09 <u>12-09</u>	TI <u>AP</u>	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001859206 T/S: 12/08/2009 10:28 AM VBROWN -----

----- COMMENTS AND NOTES -----

ADDRESS : 137 MEADOW RIDGE DR SUBDIV:
 CONTRACTOR : BECKER WILLIAM H PHONE : (910) 263-2700
 OWNER : SIMPSON JOHN W PHONE : (910) 892-3620
 PARCEL : 02-1518- - -0200- -11-
 APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 09/18/2009 09:14 AM VBROWN ----
 MEADOW RIDGE DRIVE, MEADOWRIDGE SUB DIV
 #26. 421S TO DUNN, LEFT ON RED HILL
 CHURCH RD 2.3MI, RIGHT ON THREE BRIDGES
 RD 1.3MI, RIGHT ON MEADOW LARK RD
 0.1MI, LEFT ON MORRISON DRIVE 0.1MI,
 RIGHT ON MEADOW RIDGE DRIVE #26.
 T/S: 10/26/2009 04:11 PM NTART ----
 PREMISE # 69865576 *****

STRUCTURE: 000 000 28X32 3BDR 2BATH SFD WITH DECK CRAWL

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/23/09 10/26/09	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001841055 T/S: 10/22/2009 12:40 PM DJOHNSON ---- TSP ALSO T/S: 10/22/2009 12:41 PM DJOHNSON ---- T/S: 10/26/2009 12:08 PM NTART ---- T/S: 10/26/2009 04:12 PM NTART ----
B103 01	10/27/09 10/27/09	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001842301
A814 01	10/27/09 11/04/09	TW AP	✓ ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001842293 ✓ 137 MEADOW RIDGE DR DUNN 28334 T/S: 11/04/2009 03:59 PM TWARD ----
B105 01	10/30/09 10/30/09	BS AP	R*OPEN FLOOR VRU #: 001844232 T/S: October 30, 2009 01:24 PM BSUTTON ----
R425 01	12/07/09 12/07/09	KS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001858059 T/S: 12/04/2009 09:17 AM VBROWN ---- 1. Receptacles not installed beneath living room windsows 2. Bath vent not installed in half bath 3. Smoke detector outside master needs moving. OK to side and insulate T/S: 12/07/2009 01:09 PM KSLATTUM ----
I129 01	12/09/09 12/09/09	KS AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001859271 T/S: 12/08/2009 10:53 AM RDCONTE ---- INSULATION PER KEN
R425 02	12/09/09 12/09/09	KS AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001859206 T/S: 12/08/2009 10:28 AM VBROWN ----
H824 01	1/07/10 1/07/10	JM DA	ENVR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001868470 PER JAMES MANHART NEEDS WATER LINE AND POWER LINE CHECKED BEFORE FINAL CAN BE ISSUED. T/S: 01/07/2010 08:31 AM SSTEWARD ---- T/S: 01/07/2010 08:32 AM SSTEWARD ----
H824 02	2/04/10	JM	✓ ENVR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001880244

PREPARED 5/20/10, 14:31:26
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 6
DATE 5/21/10

ADDRESS : 137 MEADOW RIDGE DR
CONTRACTOR : BECKER WILLIAM H
OWNER : SIMPSON JOHN W
PARCEL : 02-1518- - -0200- -11-
APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)

SUBDIV:
PHONE : (910) 263-2700
PHONE : (910) 892-3620

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	2/04/10	AP	T/S: 02/05/2010 10:37 AM SSTEWARD ----- T/S: 02/05/2010 10:37 AM SSTEWARD -----
R429 01	5/21/10 <u>5-21-10</u>	TI <u>DPBS</u>	FOUR TRADE FINAL TIME: 17:00 VRU #: 001930163 T/S: 05/20/2010 12:04 PM JBROCK -----

----- COMMENTS AND NOTES -----

ADDRESS : 137 MEADOW RIDGE DR SUBDIV:
 CONTRACTOR : BECKER WILLIAM H PHONE : (910) 263-2700
 OWNER : SIMPSON JOHN W PHONE : (910) 892-3620
 PARCEL : 02-1518- - -0200- -11-
 APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 09/18/2009 09:14 AM VBROWN ----
 MEADOW RIDGE DRIVE, MEADOWRIDGE SUB DIV
 #26. 421S TO DUNN, LEFT ON RED HILL
 CHURCH RD 2.3MI, RIGHT ON THREE BRIDGES
 RD 1.3MI, RIGHT ON MEADOW LARK RD
 0.1MI, LEFT ON MORRISON DRIVE 0.1MI,
 RIGHT ON MEADOW RIDGE DRIVE #26.
 T/S: 10/26/2009 04:11 PM NTART ----
 PREMISE # 69865576 *****

STRUCTURE: 000 000 28X32 3BDR 2BATH SFD WITH DECK CRAWL

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/23/09 10/26/09	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001841055 T/S: 10/22/2009 12:40 PM DJOHNSON ---- TSP ALSO T/S: 10/22/2009 12:41 PM DJOHNSON ---- T/S: 10/26/2009 12:08 PM NTART ---- T/S: 10/26/2009 04:12 PM NTART ----
B103 01	10/27/09 10/27/09	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001842301
A814 01	10/27/09 11/04/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001842293 ✓ 137 MEADOW RIDGE DR DUNN 28334 T/S: 11/04/2009 03:59 PM TWARD ----
B105 01	10/30/09 10/30/09	BS AP	R*OPEN FLOOR VRU #: 001844232 T/S: October 30, 2009 01:24 PM BSUTTON ----
R425 01	12/07/09 12/07/09	KS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001858059 T/S: 12/04/2009 09:17 AM VBROWN ---- 1. Receptacles not installed beneath living room windsows 2. Bath vent not installed in half bath 3. Smoke detector outside master needs moving. OK to side and insulate T/S: 12/07/2009 01:09 PM KSLATTUM ----
I129 01	12/09/09 12/09/09	KS AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001859271 T/S: 12/08/2009 10:53 AM RDCONTE ---- INSULATION PER KEN
R425 02	12/09/09 12/09/09	KS AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001859206 T/S: 12/08/2009 10:28 AM VBROWN ----
H824 01	1/07/10 1/07/10	JM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001868470 PER JAMES MANHART NEEDS WATER LINE AND POWER LINE CHECKED BEFORE FINAL CAN BE ISSUED. T/S: 01/07/2010 08:31 AM SSTEWARD ---- T/S: 01/07/2010 08:32 AM SSTEWARD ----
H824 02	2/04/10	JM	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001880244

ADDRESS : 137 MEADOW RIDGE DR
CONTRACTOR : BECKER WILLIAM H
OWNER : SIMPSON JOHN W
PARCEL : 02-1518- - -0200- -11-
APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)

SUBDIV:
PHONE : (910) 263-2700
PHONE : (910) 892-3620

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	2/04/10	AP	T/S: 02/05/2010 10:37 AM SSTEWARD ----- T/S: 02/05/2010 10:37 AM SSTEWARD -----
R429 01	5/21/10	BS	FOUR TRADE FINAL TIME: 17:00 VRU #: 001930163
	5/21/10	DP	T/S: 05/20/2010 12:04 PM JBROCK ----- 1. No handrail on front stairs. 2. Plumbing vent capped on roof. 3. Utility room on back of house shall have 6 minimum clearance siding to grade 4. All arc fault breaker shall be listed combination type. 5. Attic unit wired and breaker sized for 10 kw heat, unit is marked 5 kw heat. 6.No insulation markers in attic. 7. Handrails in stairway not returned to wall. Inspection stopped. \$50 re fee
R429 02	5/26/10	TI	FOUR TRADE FINAL VRU #: 001932078

5-26 ~~TI~~ DA

----- COMMENTS AND NOTES -----

**Violation Notice
Do Not Remove**

**Harnett County Inspection Department
102 East Front St P.O. Box 65
Lillington, NC 27546
Phone (910) 893-7525 Fax (910) 893-2793**

0950022873

May 26, 2010

1. Cannot have open risers on stairs
2. Need receptacle for hvac pump in crawl space
3. Need receptacle at end of peninsula
4. Side water heater storage

**Ken Slattum
Code Administrator**

ADDRESS : 137 MEADOW RIDGE DR SUBDIV:
CONTRACTOR : BECKER WILLIAM H PHONE : (910) 263-2700
OWNER : SIMPSON JOHN W PHONE : (910) 892-3620
PARCEL : 02-1518- - -0200- -11-
APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 09/18/2009 09:14 AM VBROWN ----
MEADOW RIDGE DRIVE, MEADOWRIDGE SUB DIV
#26. 421S TO DUNN, LEFT ON RED HILL
CHURCH RD 2.3MI, RIGHT ON THREE BRIDGES
RD 1.3MI, RIGHT ON MEADOW LARK RD
0.1MI, LEFT ON MORRISON DRIVE 0.1MI,
RIGHT ON MEADOW RIDGE DRIVE #26.
T/S: 10/26/2009 04:11 PM NTART ----
PREMISE # 69865576 *****

STRUCTURE: 000 000 28X32 3BDR 2BATH SFD WITH DECK CRAWL

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/23/09 10/26/09	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001841055 T/S: 10/22/2009 12:40 PM DJOHNSON ---- TSP ALSO T/S: 10/22/2009 12:41 PM DJOHNSON ---- T/S: 10/26/2009 12:08 PM NTART ---- T/S: 10/26/2009 04:12 PM NTART ----
B103 01	10/27/09 10/27/09	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001842301
A814 01	10/27/09 11/04/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001842293 ✓ 137 MEADOW RIDGE DR DUNN 28334 T/S: 11/04/2009 03:59 PM TWARD ----
B105 01	10/30/09 10/30/09	BS AP	R*OPEN FLOOR VRU #: 001844232 T/S: October 30, 2009 01:24 PM BSUTTON ----
R425 01	12/07/09 12/07/09	KS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001858059 T/S: 12/04/2009 09:17 AM VBROWN ---- 1. Receptacles not installed beneath living room windsows 2. Bath vent not installed in half bath 3. Smoke detector outside master needs moving. OK to side and insulate T/S: 12/07/2009 01:09 PM KSLATTUM ----
I129 01	12/09/09 12/09/09	KS AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001859271 T/S: 12/08/2009 10:53 AM RDCONTE ---- INSULATION PER KEN
R425 02	12/09/09 12/09/09	KS AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001859206 T/S: 12/08/2009 10:28 AM VBROWN ----
H824 01	1/07/10 1/07/10	JM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001868470 PER JAMES MANHART NEEDS WATER LINE AND POWER LINE CHECKED BEFORE FINAL CAN BE ISSUED. T/S: 01/07/2010 08:31 AM SSTEWARD ---- T/S: 01/07/2010 08:32 AM SSTEWARD ----
H824 02	2/04/10	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001880244

ADDRESS . : 137 MEADOW RIDGE DR SUBDIV:
CONTRACTOR : BECKER WILLIAM H PHONE : (910) 263-2700
OWNER . . : SIMPSON JOHN W PHONE : (910) 892-3620
PARCEL . . : 02-1518- - -0200- -11-
APPL NUMBER: 09-50022873 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	2/04/10	AP	T/S: 02/05/2010 10:37 AM SSTEWARD ----- T/S: 02/05/2010 10:37 AM SSTEWARD -----
R429 01	5/21/10 5/21/10	BS DP	FOUR TRADE FINAL TIME: 17:00 VRU #: 001930163 T/S: 05/20/2010 12:04 PM JBROCK ----- 1. No handrail on front stairs. 2. Plumbing vent capped on roof. 3. Utility room on back of house shall have 6 minimum clearance siding to grade 4. All arc fault breaker shall be listed combination type. 5. Attic unit wired and breaker sized for 10 kw heat, unit is marked 5 kw heat. 6.No insulation markers in attic. 7. Handrails in stairway not returned to wall. Inspection stopped. \$50 re fee
R429 02	5/26/10 5/26/10	KS DA	FOUR TRADE FINAL VRU #: 001932078 T/S: 05/26/2010 12:14 PM VBROWN ----- DA INSP CUSTOMER CALLED AND WANTED RESCHD FOR THURS T/S: 05/26/2010 01:25 PM KSLATTUM ----- 1. Cannot have open risers on stairs 2. Need receptacle for hvac pump 3. Need receptacle at end of peninsula 4. Install siding on water heater shed
R429 03	5/27/10 <u>5-27</u>	TI <u>AI</u>	FOUR TRADE FINAL TIME: 17:00 VRU #: 001933118 T/S: 05/26/2010 12:15 PM VBROWN -----

----- COMMENTS AND NOTES -----

