Department of Environment, Health and Natural Resources Sheet: Division of Environmental Health Property ID: On-Site Wastewater Section Lot #: SOIL/SITE EVALUATION Code: for ON-SITE WASTEWATER SYSTEM Code: Owner: Applicant: Address: Date Evaluated: 10 30 00 000 0000000000000000000000000										
P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (in.)	SOIL MORPHOLOGY .1941		OTHER DOCTUE FLACTOR					
			. 1941 Structure/ Toxture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	PROFILE FACTOR .1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
١	25	0-470	63	VER NOLVY					S . P	
3		0-248	G ≤	VFR NSINP					5.8	

Description	Initial System	Repair System	Other Factors (.1946):	
Available Space (.1945)			Site Classification (.1948): 5 Evaluated By: O	
System Type(s)	CON	Can	Others Present:	
Site LTAR	. 8	.8	Ouras ricsciii,	

4-50 e 24-36" = REPAIR