Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

System

CON

٠٤

Available Space (.1945)

System Type(s)

Site LTAR

Repair System

⊂0.N

Owner:

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

R O F I	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Clasa	.1944 Restr Horiz	Profile Class & LTAR
<u> </u>	L5 Q-570	0-48"	GS	VFTZ NSTUP					
ð		0-72"	G 5	1F0 n3 Np					
			——————————————————————————————————————						
:									
			 						
			·						
		•				-			
		···				<u> </u>			

Other Factors (.1946):

Site Classification (.1948): 5

Others Present:

Evaluated By: or