Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Water Evalu	ess:	d:	Date Evaluated: Design Flow (.1949): Service Property Size: Property Recorded: Public Individual Well Spring Other Auger Boring Pit Cut Sewage Industrial Process Mixed						
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
,	5-219 Fè	0-121"	65	MAS UST OND					5.8
ę		042	6 9	VFR NSIM					5.8
<u></u>									
									
									
					TT-14-TT-14-11-1-1-1-1-1-1-1-1-1-1-1-1-1				
		· .							
		Initia							· · · · · · · · · · · · · · · · · · ·

System Site Classification (.1948):5 Evaluated By: NB Others Present:

Other Factors (.1946):

12150 6 18 24 : noal

Repair System

Available Space (.1945)

System Type(s)

Site LTAR