Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

			Date Evaluated: 11) 20 00 Property Size: Property Recorded: Public Individual Well Spring Other Auger Boring Pit Cut Sewage Industrial Process Mixed							
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)		RPHOLOGY 1941 .1941 Consistence Mineralogy	. 1942 Soil Wetness/ Color	OTHER PROFILE FACTO .1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
,	のみや F2	0-458	G 5	VFZ-NS/UP					8,8	
Э		0-14	65	ALL SIM					P. 2	
				,						

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948): 5
Available Space (.1945)	I	√	Evaluated By:
System Type(s)	CON	CO 14	Others Present:
Site LTAR	.9	76	