

PREPARED 3/24/10, 13:58:12
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 14
DATE 3/25/10

ADDRESS : 89900 *UNASSIGNED
CONTRACTOR : PUGH ENTERPRISES, LLC
OWNER : JOHNSON HERBERT H
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
TAKE MAIN STREET NORTH, T/R ON 421. T/L
ONTO LESLIE CAMPBELL AVE. T/R ONTO
FAIRGROUND ROAD. T/L ON BRINKLEY.
PWR CO: WAITING ON CUS

SUBDIV: WILL JOHNSON DIVISION
PHONE : (919) 931-2581
PHONE :

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : NEW TANK

PROPOSED USE : SFD

WATER SUPPLY : NEW WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
--------	------------------------	----------------	---------------------------------

B101 01	3/25/10 <i>✓</i>	TI <i>KS AP</i>	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723 T/S: 03/24/2010 12:44 PM JBROCK -----
---------	---------------------	--------------------	--

----- COMMENTS AND NOTES -----

PREPARED 4/01/10, 14:01:15
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 23
DATE 4/05/10

ADDRESS : 89900 *UNASSIGNED
CONTRACTOR : PUGH ENTERPRISES, LLC
OWNER : JOHNSON HERBERT H
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
TAKE MAIN STREET NORTH, T/R ON 421. T/L
ONTO LESLIE CAMPBELL AVE. T/R ONTO
FAIRGROUND ROAD. T/L ON BRINKLEY.
PWR CO: WAITING ON CUS

SUBDIV: WILL JOHNSON DIVISION
PHONE : (919) 931-2581
PHONE :

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW TANK

WATER SUPPLY : NEW WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/25/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723
	3/25/10	AP	T/S: 03/24/2010 12:44 PM JBROCK
AB14 01	3/30/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001901982
	4/01/10	AP	T/S: 03/29/2010 01:35 PM RDCONTE
			102 BRINKLEY RD # ON HOME AND BY DRIVE
			DUNN 28334
			T/S: 04/01/2010 10:04 AM TWARD
B103 01	4/05/10	TI	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001904069
	4-5-10	APBS	T/S: 04/01/2010 01:09 PM RDCONTE

COMMENTS AND NOTES

PREPARED 4/05/10, 13:58:28
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 21
DATE 4/06/10

ADDRESS : 102 BRINKLEY RD
CONTRACTOR : PUGH ENTERPRISES, LLC
OWNER : JOHNSON HERBERT H
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
TAKE MAIN STREET NORTH, T/R ON 421. T/L
ONTO LESLIE CAMPBELL AVE. T/R ONTO
FAIRGROUND ROAD. T/L ON BRINKLEY.
PWR CO: WAITING ON CUS

SUBDIV: WILL JOHNSON DIVISION
PHONE : (919) 931-2581
PHONE :

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW TANK

WATER SUPPLY : NEW WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/25/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723
	3/25/10	AP	T/S: 03/24/2010 12:44 PM JBROCK -----
A814 01	3/30/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001901982
	4/01/10	AP	T/S: 03/29/2010 01:35 PM RDCONTE ----- 102 BRINKLEY RD # ON HOME AND BY DRIVE----- DUNN 28334 -----
			T/S: 04/01/2010 10:04 AM TWARD -----
B103 01	4/05/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001904069
	4/05/10	AP	T/S: 04/01/2010 01:09 PM RDCONTE ----- T/S: April 05, 2010 11:24 AM BSUTTON -----
B105 01	4/06/10 <u>4-6-10</u>	TI <u>APB</u>	R*OPEN FLOOR VRU #: 001905200 VOICE MESSAGE LEFT

----- COMMENTS AND NOTES -----

PREPARED 4/22/10, 14:02:12
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 16
DATE 4/23/10

ADDRESS : 102 BRINKLEY RD
CONTRACTOR : PUGH ENTERPRISES, LLC
OWNER : JOHNSON HERBERT H
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
TAKE MAIN STREET NORTH, T/R ON 421. T/L
ONTO LESLIE CAMPBELL AVE. T/R ONTO
FAIRGROUND ROAD. T/L ON BRINKLEY.
PWR CO: WAITING ON CUS

SUBDIV: WILL JOHNSON DIVISION
PHONE : (919) 931-2581
PHONE :

2141738

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : NEW TANK

PROPOSED USE : SFD

WATER SUPPLY : NEW WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/25/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723
	3/25/10	AP	T/S: 03/24/2010 12:44 PM JBROCK -----
A814 01	3/30/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001901982
	4/01/10	AP	T/S: 03/29/2010 01:35 PM RDCONTE ----- 102 BRINKLEY RD # ON HOME AND BY DRIVE----- DUNN 28334 ----- T/S: 04/01/2010 10:04 AM TWARD -----
B103 01	4/05/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001904069
	4/05/10	AP	T/S: 04/01/2010 01:09 PM RDCONTE ----- T/S: April 05, 2010 11:24 AM BSUTTON -----
B105 01	4/06/10	BS	R*OPEN FLOOR VRU #: 001905200
	4/06/10	AP	VOICE MESSAGE LEFT T/S: April 06, 2010 02:01 PM BSUTTON -----
R425 01	4/23/10	TI	FOUR TRADE ROUGH IN VRU #: 001914753
	4-23	DA	NEED INSPECTION AFTER LUNCH

COMMENTS AND NOTES

VIOLATION NOTICE

DO NOT REMOVE!

Harnett County Inspection Department

108 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7525 Ext. 1 • Fax: (910) 893-2793

Job Name: Pugh Enterprise Date: 4-23-10

Address: 102 Birchley Road

Lot No.: _____ Permit No.: 89-50023347

(Check Box for Violation)

☐ Footing	☐ Foundation	☐ Bldg.	☐ Elec.	☐ Plumb.	☐ Mech.	☐ Insul.	☐ Floor Fram.
☐ Floor Slab	☐ MFG. Home	☐ Modular	☐ Damp/Water Proof.	☐ Structural	☐ Wall Sheath.	☐ Other	

Violations Found: ① Brick flashing for weep holes not installed

② Remove brick/block etc from porch - cannot use debris for fill.

③ Hips + Valleys shall be ~~sp~~ supported to load wall.

④ Collarties missing in front bedroom

⑤ Roof shall be as far rough in -

⑥ Do not slice Do Not Insulate.

Code Enforcement Official

Signature: Ke Shatt Date: 4-23-10

It is unlawful for any subcontractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation

ADDRESS : 102 BRINKLEY RD SUBDIV: WILL JOHNSON DIVISION
CONTRACTOR : PUGH ENTERPRISES, LLC PHONE : (919) 931-2581
OWNER : JOHNSON HERBERT H PHONE :
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
TAKE MAIN STREET NORTH, T/R ON 421. T/L
ONTO LESLIE CAMPBELL AVE. T/R ONTO
FAIRGROUND ROAD. T/L ON BRINKLEY.
PWR CO: WAITING ON CUS

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW TANK

WATER SUPPLY : NEW WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/25/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723
	3/25/10	AP	T/S: 03/24/2010 12:44 PM JBROCK -----
A814 01	3/30/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001901982
	4/01/10	AP	T/S: 03/29/2010 01:35 PM RDCONTE ----- 102 BRINKLEY RD # ON HOME AND BY DRIVE----- DUNN 28334 ----- T/S: 04/01/2010 10:04 AM TWARD -----
B103 01	4/05/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001904069
	4/05/10	AP	T/S: 04/01/2010 01:09 PM RDCONTE ----- T/S: April 05, 2010 11:24 AM BSUTTON -----
B105 01	4/06/10	BS	R*OPEN FLOOR VRU #: 001905200
	4/06/10	AP	VOICE MESSAGE LEFT T/S: April 06, 2010 02:01 PM BSUTTON -----
R425 01	4/23/10	KS	FOUR TRADE ROUGH IN VRU #: 001914753
	4/23/10	DA	NEED INSPECTION AFTER LUNCH 1. Brick flashing not installed for weep holes. 2. Remove brick/block from porch. must be clean fill. 3. Hips and valleys shall be supported to load bearing wall. 4. Collar ties missing from front bedroom. 5. Roof shall be on for rough-in 6. Do not side or insulate T/S: 04/23/2010 02:01 PM KSLATTUM ----- T/S: 04/23/2010 02:03 PM KSLATTUM -----
R425 02	4/28/10	TI	FOUR TRADE ROUGH IN VRU #: 001917126

7-28

AP

----- COMMENTS AND NOTES -----

ADDRESS : 102 BRINKLEY RD
CONTRACTOR : PUGH ENTERPRISES, LLC
OWNER : JOHNSON HERBERT H
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
TAKE MAIN STREET NORTH, T/R ON 421. T/L
ONTO LESLIE CAMPBELL AVE. T/R ONTO
FAIRGROUND ROAD. T/L ON BRINKLEY.
PWR CO: WAITING ON CUS

SUBDIV: WILL JOHNSON DIVISION
PHONE : (919) 931-2581
PHONE :

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW TANK

WATER SUPPLY : NEW WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/25/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723
	3/25/10	AP	T/S: 03/24/2010 12:44 PM JBROCK -----
A814 01	3/30/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001901982
	4/01/10	AP	T/S: 03/29/2010 01:35 PM RDCONTE ----- 102 BRINKLEY RD # ON HOME AND BY DRIVE----- DUNN 28334 ----- T/S: 04/01/2010 10:04 AM TWARD -----
B103 01	4/05/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001904069
	4/05/10	AP	T/S: 04/01/2010 01:09 PM RDCONTE ----- T/S: April 05, 2010 11:24 AM BSUTTON -----
B105 01	4/06/10	BS	R*OPEN FLOOR VRU #: 001905200
	4/06/10	AP	VOICE MESSAGE LEFT T/S: April 06, 2010 02:01 PM BSUTTON -----
R425 01	4/23/10	KS	FOUR TRADE ROUGH IN VRU #: 001914753
	4/23/10	DA	NEED INSPECTION AFTER LUNCH 1. Brick flashing not installed for weep holes. 2. Remove brick/block from porch. must be clean fill. 3. Hips and valleys shall be supported to load bearing wall. 4. Collar ties missing from front bedroom. 5. Roof shall be on for rough-in 6. Do not side or insulate T/S: 04/23/2010 02:01 PM KSLATTUM ----- T/S: 04/23/2010 02:03 PM KSLATTUM -----
R425 02	4/28/10	KS	FOUR TRADE ROUGH IN VRU #: 001917126
	4/28/10	AP	
I129 01	4/30/10 4-38-10	TI AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001918572 T/S: 04/29/2010 12:25 PM VBROWN -----

COMMENTS AND NOTES

ADDRESS : 102 BRINKLEY RD
CONTRACTOR : PUGH ENTERPRISES, LLC
OWNER : JOHNSON HERBERT H
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
TAKE MAIN STREET NORTH, T/R ON 421. T/L
ONTO LESLIE CAMPBELL AVE. T/R ONTO
FAIRGROUND ROAD. T/L ON BRINKLEY.
PWR CO: WAITING ON CUS
T/S: 06/16/2010 12:26 PM RDCONTE ---
****PREMISE # 03503960****

SUBDIV: WILL JOHNSON DIVISION
PHONE : (919) 931-2581
PHONE :

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW TANK

WATER SUPPLY : NEW WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/25/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723
	3/25/10	AP	T/S: 03/24/2010 12:44 PM JBROCK
A814 01	3/30/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001901982
	4/01/10	AP	T/S: 03/29/2010 01:35 PM RDCONTE
			✓ 102 BRINKLEY RD # ON HOME AND BY DRIVE----- DUNN 28334
			T/S: 04/01/2010 10:04 AM TWARD
B103 01	4/05/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001904069
	4/05/10	AP	T/S: 04/01/2010 01:09 PM RDCONTE
			T/S: April 05, 2010 11:24 AM BSUTTON
B105 01	4/06/10	BS	R*OPEN FLOOR VRU #: 001905200
	4/06/10	AP	VOICE MESSAGE LEFT
			T/S: April 06, 2010 02:01 PM BSUTTON
R425 01	4/23/10	KS	FOUR TRADE ROUGH IN VRU #: 001914753
	4/23/10	DA	NEED INSPECTION AFTER LUNCH
			1. Brick flashing not installed for weep holes.
			2. Remove brick/block from porch. must be clean fill.
			3. Hips and valleys shall be supported to load bearing wall.
			4. Collar ties missing from front bedroom.
			5. Roof shall be on for rough-in
			6. Do not side or insulate
			T/S: 04/23/2010 02:01 PM KSLATTUM
			T/S: 04/23/2010 02:03 PM KSLATTUM
R425 02	4/28/10	KS	FOUR TRADE ROUGH IN VRU #: 001917126
	4/28/10	AP	
I129 01	4/30/10	KS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001918572
	4/30/10	AP	T/S: 04/29/2010 12:25 PM VBROWN
H824 01	6/15/10	BM	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001941806
	6/15/10	AP	T/S: 06/16/2010 09:01 AM SZIMMER
			T/S: 06/16/2010 09:02 AM SZIMMER
R429 01	6/17/10	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 001942135
	6-17	DP	T/S: 06/16/2010 12:27 PM RDCONTE
			PLEASE CALL TO MEET 919-931-2581

COMMENTS AND NOTES

u t

VIOLATION NOTICE

DO NOT REMOVE!

Harnett County Inspection Department

108 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7525 Ext. 1 • Fax: (910) 893-2793

Job Name: Pugh Enterprises, LLC Date: 6-17-18

Address: 102 Brinkley Rd

Lot No.: _____ Permit No.: 09-500-23347

(Check Box for Violation)

☐ Footing	☐ Foundation	☐ Bldg.	☐ Elec.	☐ Plumb.	☐ Mech.	☐ Insul.	☐ Floor Fram.
☐ Floor Slab	☐ MFG. Home	☐ Modular	☐ Damp/Water Proof.	☐ Structural	☐ Wall Sheath.	☐ Other	

Violations Found: ① No 911's on house or Road ② No Rear steps ③ Toilets not caulked at floor ④ Motor/to faucet not bonded together for jacuzzi ⑤ Water heater shall be on solid pad ⑥ water heater PRT shall go to exterior ⑦ Receptacle not installed in front closet ⑧ Pull down stairs hinge not nailed per installation instructions ⑨ Brick missing at left front of house ⑩ No Access door

\$50.00 Reinsp. fee.

Code Enforcement Official

Signature: Ke Stahl Date: 6-17-18

It is unlawful for any subcontractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation

ADDRESS : 102 BRINKLEY RD SUBDIV: WILL JOHNSON DIVISION
CONTRACTOR : PUGH ENTERPRISES, LLC PHONE : (919) 931-2581
OWNER : JOHNSON HERBERT H PHONE :
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
TAKE MAIN STREET NORTH, T/R ON 421. T/L
ONTO LESLIE CAMPBELL AVE. T/R ONTO
FAIRGROUND ROAD. T/L ON BRINKLEY.
PWR CO: WAITING ON CUS
T/S: 06/16/2010 12:26 PM RDCONTE ---
****PREMISE # 03503960****

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW TANK

WATER SUPPLY : NEW WELL

PERMIT: CPNP 00 CP MISC NOTIFICATION PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H800 01	12/21/09 6/09/10	BM AP	ENVIR. HLTH. CONFIRMATION VRU #: 001858724 T/S: 12/23/2009 11:16 AM SSTEWARD T/S: 06/09/2010 10:40 AM SZIMMER
H800 02	3/08/10 2/24/10	BM AP	ENVIR. HLTH. CONFIRMATION VRU #: 001885838 T/S: 02/24/2010 10:26 AM SSTEWARD
H800 03	6/07/10 6/09/10	BM AP	ENVIR. HLTH. CONFIRMATION VRU #: 001931191 T/S: 06/09/2010 11:02 AM SSTEWARD

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/25/10 3/25/10	KS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723 T/S: 03/24/2010 12:44 PM JBROCK
A814 01	3/30/10 4/01/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001901982 T/S: 03/29/2010 01:35 PM RDCONTE 102 BRINKLEY RD # ON HOME AND BY DRIVE----- DUNN 28334 T/S: 04/01/2010 10:04 AM TWARD
B103 01	4/05/10 4/05/10	BS AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001904069 T/S: 04/01/2010 01:09 PM RDCONTE T/S: April 05, 2010 11:24 AM BSUTTON
B105 01	4/06/10 4/06/10	BS AP	R*OPEN FLOOR VRU #: 001905200 VOICE MESSAGE LEFT T/S: April 06, 2010 02:01 PM BSUTTON
R425 01	4/23/10 4/23/10	KS DA	FOUR TRADE ROUGH IN VRU #: 001914753 NEED INSPECTION AFTER LUNCH 1. Brick flashing not installed for weep holes. 2. Remove brick/block from porch. must be clean fill. 3. Hips and valleys shall be supported to load bearing wall. 4. Collar ties missing from front bedroom. 5. Roof shall be on for rough-in

CONTINUED ONTO NEXT PAGE

PREPARED: 6/18/10, 7:38:49
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 2
DATE 6/18/10

ADDRESS : 102 BRINKLEY RD
CONTRACTOR : PUGH ENTERPRISES, LLC
OWNER : JOHNSON HERBERT H
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)

SUBDIV: WILL JOHNSON DIVISION
PHONE : (919) 931-2581
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			6. Do not side or insulate T/S: 04/23/2010 02:01 PM KSLATTUM ----- T/S: 04/23/2010 02:03 PM KSLATTUM -----
R425 02	4/28/10	KS	FOUR TRADE ROUGH IN VRU #: 001917126
	4/28/10	AP	
II29 01	4/30/10	KS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001918572
	4/30/10	AP	T/S: 04/29/2010 12:25 PM VBROWN -----
H824 01	6/15/10	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001941806
	6/15/10	AP	T/S: 06/16/2010 09:01 AM SZIMMER ----- T/S: 06/16/2010 09:02 AM SZIMMER -----
R429 01	6/17/10	KS	FOUR TRADE FINAL TIME: 17:00 VRU #: 001942135
	6/17/10	DP	T/S: 06/16/2010 12:27 PM RDCONTE ----- PLEASE CALL TO MEET 919-931-2581 1. No 911 numbers - Not at Road. ✓ 2. No rear steps ✓ 3. Toilets not caulked 4. Jacuzzi motor not bonded 5. Water heater not on solid pad 6. Water heater PRV not to exterior 7. Receptacle not installed in front hall closet. 8. Pull down stairs not installed properly. 9. Brick missing from front of house 10. No access door.
R429 02	6/18/10 6-118	TI DP	FOUR TRADE FINAL TIME: 17:00 VRU #: 001942986 T/S: 06/17/2010 01:52 PM JBROCK -----

COMMENTS AND NOTES

Deck Thru bolts
No Tamper resistant in front
hall

Hannett County

INSPECTOR: IVR

DATE

6/22/10

ADDRESS : 102 BRINKLEY RD
 CONTRACTOR : PUGH ENTERPRISES, LLC
 OWNER : JOHNSON HERBERT H
 PARCEL : 02-1518- - -0020- -16-
 APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)

SUBDIV: WILL JOHNSON DIVISION
 PHONE : (919) 931-2581
 PHONE :

DIRECTIONS : T/S: 12/03/2009 04:40 PM RDCONTE ---
 HERBERT H JOHNSON LOT:A / BRINKLEY ROAD
 TAKE MAIN STREET NORTH, T/R ON 421. T/L
 ONTO LESLIE CAMPBELL AVE. T/R ONTO
 FAIRGROUND ROAD. T/L ON BRINKLEY.
 PWR CO: WAITING ON CUS
 T/S: 06/16/2010 12:26 PM RDCONTE ---
 *****PREMISE # 03503960*****

STRUCTURE: 000 000 55X53.5 CRAWL 4BD/3BA W/10X16 PATIO

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW TANK

WATER SUPPLY : NEW WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/25/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001899723
	3/25/10	AP	T/S: 03/24/2010 12:44 PM JBROCK
A814 01	3/30/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001901982
	4/01/10	AP	T/S: 03/29/2010 01:35 PM RDCONTE
			102 BRINKLEY RD # ON HOME AND BY DRIVE
			DUNN 28334
			T/S: 04/01/2010 10:04 AM TWARD
B103 01	4/05/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001904069
	4/05/10	AP	T/S: 04/01/2010 01:09 PM RDCONTE
			T/S: April 05, 2010 11:24 AM BSUTTON
B105 01	4/06/10	BS	R*OPEN FLOOR VRU #: 001905200
	4/06/10	AP	VOICE MESSAGE LEFT
			T/S: April 06, 2010 02:01 PM BSUTTON
R425 01	4/23/10	KS	FOUR TRADE ROUGH IN VRU #: 001914753
	4/23/10	DA	NEED INSPECTION AFTER LUNCH
			1. Brick flashing not installed for weep holes.
			2. Remove brick/block from porch. must be clean fill.
			3. Hips and valleys shall be supported to load bearing wall.
			4. Collar ties missing from front bedroom.
			5. Roof shall be on for rough-in
			6. Do not side or insulate
			T/S: 04/23/2010 02:01 PM KSLATTUM
			T/S: 04/23/2010 02:03 PM KSLATTUM
R425 02	4/28/10	KS	FOUR TRADE ROUGH IN VRU #: 001917126
	4/28/10	AP	
I129 01	4/30/10	KS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001918572
	4/30/10	AP	T/S: 04/29/2010 12:25 PM VBROWN
H824 01	6/15/10	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001941806
	6/15/10	AP	T/S: 06/16/2010 09:01 AM SZIMMER
			T/S: 06/16/2010 09:02 AM SZIMMER
R429 01	6/17/10	KS	FOUR TRADE FINAL TIME: 17:00 VRU #: 001942135
	6/17/10	DP	T/S: 06/16/2010 12:27 PM RDCONTE

CONTINUED ONTO NEXT PAGE

ADDRESS : 102 BRINKLEY RD SUBDIV: WILL JOHNSON DIVISION
CONTRACTOR : PUGH ENTERPRISES, LLC PHONE : (919) 931-2581
OWNER : JOHNSON HERBERT H PHONE :
PARCEL : 02-1518- - -0020- -16-
APPL NUMBER: 09-50023347 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			----- PLEASE CALL TO MEET 919-931-2581 1. No 911 numbers 2. No rear steps 3. Toilets not caulked 4. Jacuzzi motor not bonded 5. Water heater not on solid pad 6. Water heater PRV not to exterior 7. Receptacle not installed in front hall closet. 8. Pull down stairs not installed properly. 9. Brick missing from front of house 10. No access door. -----
R429 02	6/18/10 6/18/10	KS DP	FOUR TRADE FINAL TIME: 17:00 VRU #: 001942986 T/S: 06/17/2010 01:52 PM JBROCK ----- 1. No 911 numbers at road 2. Rear deck not thru bolted 3. Receptacle in front closet not tamper resistant 4 Pull down stairs still not installed properly 5. Jacuzzi to metal faucets not bonded. -----
R429 04	6/22/10 " "	TI BS	T/S: 06/18/2010 10:22 AM KSLATTUM ----- FOUR TRADE FINAL TIME: 17:00 VRU #: 001944206 T/S: 06/21/2010 02:26 PM VBROWN -----

----- COMMENTS AND NOTES -----

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: _____ Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Permit Numbers

Name: Herbert H Johnson

Building: 09-50023347

Electrical: 09-50023347

Address: 102 Brinkley Road

Insulation: 09-50023347

Dunn NC 28334

Plumbing: 09-50023347

Mechanical: 09-50023347

MFG Home: NA NA NA NA

Date: 06-21-10

Building Official: BSutton