Department of Environment, Health and Natural Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address: Date Evaluated:
Proposed Facility: 3BED x 100m home Design Flow (.1949): 360 gpd Property Size:
Location of Site: Property Recorded:
Water Supply: ☒ Public ☐ Individual ☐ Well ☐ Spring ☐ Other
Evaluation Method: ☒ Auger Boring ☐ Pit ☐ Cut
Type of Wastewater: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 Landscape Position/ Slope % | Horizon Depth (In.) | SOIL MORPHOLOGY .1941 | | OTHER PROFILE FACTORS | | | | Profile Class & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| | | | .1941 Structure/ Texture | .1941 Consistence Mineralogy | .1942 Soil Wetness/ Color | .1943 Soil Depth (IN.) | .1956 Sapro Class | .1944 Restr Horiz | |
| 1 | LS 0-2% | 0-12" | GLS | VFR NS/NP | | | | | |
| | | 12-36" | SBK SCL | FR SS/SP | | | | | PS .4 |
| | | | | | | | | | |
| | | 0-14" | G LS | VFR NS/NP | | | | | |
| | | 14-34" | SBK SCL | FR SS/SP | | | | | PS .4 |
| | | | | | | | | | |
| | | 0-22" | G LS | VFR NS/NP | | | | | |
| | | 22-38" | SBK SCL | FR SS/SP | | | | | PS .4 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| Description | Initial System | Repair System |
|---|---|---|
| Available Space (.1945) | ✓ | ✓ |
| System Type(s) | 25% red | pump 25% red |
| Site LTAR | .4 | .4 |

Other Factors (.1946):
Site Classification (.1948): PS
Evaluated By: OT
Others Present: —