Divisio On-Sit Owner Addres Propos Locatio Water Evalua	on of Envir e Wastewa for ON-	onmental ter Sectio SOIL/SI SITE WA Applican SFD d:	Health n TE EVALUA ASTEWATE at: A4 D (A Date Desig	R SYSTEM Evaluated: 3-2 gn Flow (.1949): 5 erty Recorded: Individua	Property ID: Lot #: File #: Code: 260 Property Size: $4/80Well Spring OtherStit Cut$				
P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (in.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	L 6790	0-12	56	A GENER					
		12 - 46	SC-CIAY	An 125105.P.	420 200				• 3 - • 25
Z	6-7%	0-10	SL	In CA NEWP					
		10-44	SC-CIAN	Fr GA NEWP Far-15845.C.	40" 7.54 K 40"				.3-7.24
3	L 5-6	0-12	FL	Gr. GR.NSNP					
·		12-46	SC-CIAY	Gruber NSNP Bun 1 Jous.P.	42"7.548				3,25
L						<u>l</u>			

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948); 75
Available Space (.1945)			Products at Day
System Type(s)		NO WORTH POOL -	Ves of wese Others Present:
Site LTAR	.3	. ?	Ouleas Present.