Department of Environment, Health and Natural I Division of Environmental Health On-Site Wastewater Section

rces

Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Ap Address:	oplicant:	Г 1 . 1	11/17/2011		
Proposed Facility: Location of Site:	Desi	e Evaluated: ign Flow (.194 perty Recorded	49):	Property Size:	
Water Supply: Evaluation Method: ☑	/ Public T	Individual Pit	u: □ Well □ Cu	☐ Spring	Other
Type of Wastewater:	Sewage		ustrial Process	☐ Mixed	

P R O F I L E	.1940	21	SOILM	ORPHOLOGY .1941	·	OTHER PROFILE FACTOR	.s	200	
	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	LS2-5%	0-48	G/SL	VENSOP					5.8
					*				
	,	34-0	GISL	VENDNA					3.2
				1.,					
		34-0	G-BL	VANSNI				41	5.8
					*				¥8
		2-48	GBL	VANNINE					s. e
					45 ¥ ¥				
				8 4	-	·			
					14				
				Đ.					
#									
土									

Description	Initial System	Repair System
Available Space (.1945)		
System Type(s)	25 50	15/0
Site LTAR	8	. 8

Other Factors (.1946):
Site Classification (.1948):
Evaluated By:
Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	п	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

STRUCTURE

IV

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY

C-CLAY SC-SANDY CLAY

SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

EXPANSIVE

	T	T																	mark,								
				- 1																							
										٠.																- 1	
_	+-	+								-																	
													_	_		- >	2	-		_			_	-		-	
																			-								
-	+	+-																									
_	_	_								-	_		_					-		-	-				-		
																			t		à						
	+																										- 5
_	+	_		_			_					-	-	-				-				-					
-	+	-						_	_	_	_	-	-								1000						
																		ļ.									
-	+-	-				-					_	_		-											_		
													L_	_				-									
-	+	-		-	_	-			-				_														
											_	_	_	-			_	-	-								
1	+	-																									
_										_	_	_	-	-	-	_	-	+	-		_		-			-	_
																	1	1									
-	+	_																									
											_	_	_	_			-	-									_

PALPHINE B.ADAMS
RCHISONTOWN ROAD – NEAR OLIVIA
TEY – NORTH CAROLINA
MAY 4TH, 2010

To all parties interested in title to premises surveyed:

I hereby certify that this plat was prepared by me from an actual survey and it is true and correct to the best of my knowledge and belief.

Hal T.Siler, Professional Land Surveyor No. 1-0635 DALPHINE B. ADAMS 200.00' JANIE BUIE ST. JOHN 295.15 DAPHINE B. ADAMS ONE ACRE TRACT Deed Book 1723, Page 37-39 48.2 295.14. MCLEAN HEIRS

APP# 10-500-24128