Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

Systems

45/1860

28

PUMP 25%

र

Available Space (.1945) System Type(s)
Site LTAR

Owner:

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

P R O	.1940 Landscape Position/ Slope %	Depth (in.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.19 <b>42</b> Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	5-109,	0-25%,	6.5	YFR NO/MP					158
<u>ə</u>		048	6.5	Mes repro	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	4.1 y			5.8
<u>ን</u>		ক্ৰমুগু ক	G 5	425 40/4					5.8
	-								
	-								<del> </del>
$\dashv$									
_	·								

Other Factors (.1946):

Site Classification (.1948): Evaluated By:

Others Present: Bm