Department of Environment, Health and Natural Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address: Date Evaluated: 6/28/2010
Proposed Facility: Design Flow (.1949): Property Size:
Location of Site: Property Recorded:
Water Supply: ☑ Public ☐ Individual ☐ Well ☐ Spring ☐ Other
Evaluation Method: ☑ Auger Boring ☐ Pit ☐ Cut
Type of Wastewater: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 Landscape Position/ Slope % | Horizon Depth (In.) | SOIL MORPHOLOGY .1941 | | OTHER PROFILE FACTORS | | | | Profile Class & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| | | | .1941 Structure/ Texture | .1941 Consistence Mineralogy | .1942 Soil Wetness/ Color | .1943 Soil Depth (IN.) | .1956 Supro Class | .1944 Restr Horiz | |
| | LS 5% | 0-32 | G/SL | VFr NSNP | | | | | |
| | | 32-43 | SBK/SCL | Fr SSSP | 10YR7/1 40" | | | | PS.5 |
| | | | | | | | | | |
| | | 0-16 | G/SL | VFr NSNP | | | | | |
| | | 16-40 | SBK/SCL | Fr SSSP | 10YR7/1 35" | | | | PS.4 |
| | | | | | | | | | |
| | | 0-35 | G/SL | VFr NSNP | | | | | PS.5 |
| | | 35-40 | SBK/SCL | Fr SSSP | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| Description | Initial System | Repair System |
|---|---|---|
| Available Space (.1945) | / | / |
| System Type(s) | 25% | 25% |
| Site LTAR | .4 | .4 |

Other Factors (.1946):
Site Classification (.1948): PS
Evaluated By: [illegible]
Others Present: