Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applic Address: Proposed Facility: Location of Site: Water Supply: Evaluation Method: Type of Wastewater: P			Date Evaluated: 7						
R O F I L E	.1940 Landscape	Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
	Position/ Slope %		.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Dèpth ([N.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	4568	6-45	C/8L	VF NSNP				:	· PSit
		0-48	G/15	VERNP.			a . (• :		PS.1
			· .		- Andrews				
		,							
				· ·				<u> </u>	
\dashv									
+									
									
ption	System		Repair Sy	,	Factors (.1946);	<u>L</u>			
ble Space Type(s) AR	(.1945)			Site Clas	sification (.1948); Evaluated By; Others Present;				