Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: Address: Date Evaluated: 7 12 10 Proposed Facility: 3 COO SE Design Flow (.1949): 36 SE Property Size: Location of Site: Property Recorded: Water Supply: Public Individual Well Spring Other Evaluation Method: Auger Boring Pit Cut Type of Wastewater: Sewage Industrial Process Mixed									
P R O F I	.194 0		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	25%	0-48	GS	VERNSIM					18.8
2		ત -જ્યું,	G 5	VFICUSING	, a first	nd e. s s.			>>8
			,						
· ·				· · · · · · · · · · · · · · · · · · ·		·			
						·			
-									
\dashv									
icription ilable Spa lem Type(s LTAR	ca (.1945)	Initial System	Repair S		Factors (.1946); ssification (.1948); Evaluated By:				