Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Description

Site LTAR

System Type(s)

Available Space (.1945)

Initial

System

brubsen

Repair System

NOS gava

Water Evalua Type o	ss:								
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941 .1941 .1941 Structure/ Consistence Texture Mineralogy		OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944 Wetness/ Soil Sapro Restr Color Depth (IN.) Class Horiz				Profile Class & LTAR
1		0-38	G 5						
		96-70					-		
		70.5%	G 5		<u> </u>				PS.5
9		0-16	G 5					·····	
		16-38	5BR SKIL		10707/2033"				P5.5
				·					
L_									

Other Factors (.1946):

Site Classification (.1948): %

Evaluated By: 05

Others Present: 3,0