Division of Environmental Health
On-site Wastewater Section

Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner:
Address:
Applicant:
Proposed Facility: 3 BEDROOM
Design Flow (.1949): 360 gpd
Date Evaluated: 8/25/10
Property Size:
Location of Site:
Property Recorded:
Water Supply: [X] Public [ ] Individual [ ] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE	Landscape Position & Slope %	Horizon Depth (IN)	SOIL MORPHOLOGY Structure Texture	Consistence Mottling Mineralogy	OTHER PROFILE FACTORS Wetness Condition	Depth (IN)	Class	Hard	LTAR
1	LS 2-5	0-28"	G S	VFL-NS/NP					5.8
2		0-28"	G S	VFR NS/NP					5.8
3	LS 5-10%	0-41"	G S	VFR NS/NP					5.8
4		0-28"	G S	VFR NS/NP					5.8

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	CONV	CONV
Site LTAR	.8	.8

3x50 @ 24"

Other Factors (.1946):
Site Classification (.1948): S
Evaluated By: OT
Others Present: