Department of Environment, Health and Val Resources
Division of Environmental Health On-Site Wastewater Section

Sh Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Date Evaluated:

Applicant:

Owner.

Address:

	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Dèpth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
١	2-650	0-4	65	monsh		-			15.8
2		0.28	65	10200/10			2		3.8
3		048	63	respub					5,4
1								er 198 7	
							7-		
+	-								
7		1							
+			- +						

Other Factors (.1946):

Site Classification (.1948): 5
Evaluated By: 8 / 0\
Others Present:

System

Available Space (.1945)

System Type(s)
Site LTAR

Repair System