County of Harnett Building Inspections Department Planning Services

Certificate of Compliance: \times Occupancy: \times

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett

Certificate issued pursuant to the requirements of North County Zoning Ordinances. This certifies at the time of issuance various ordinances of the County of Harnett and the North Carolina County of Harnett and Ha	Permit Numbers
Use Classification: R-3	Building: 11-50026475
Name: Wyhr Const.	Electrical:
Address: 291 Kentucky Decby	Insulation:
	Plumbing:
	Mechanical:
	MFG Home:
Date: Z-2(-12 Building Official:	J Mahad Rearie

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

2/21/12

SUBDIV: TROTTERS RIDGE PH1-B 14LOTS ADDRESS . : 291 KENTUCKY DERBY LN

PHONE : (919) 528-1347 CONTRACTOR : WYNN CONSTRUCTION, INC.

PHONE : OWNER . . : WYNN CONSTRUCTION INC

PARCEL . .: 03-0507- - -0200- -18-

APPL NUMBER: 11-50026475 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 04/19/2011 11:43 AM VBROWN ----

KENTUCKY DERBY LANE, TROTTERS RIDGE #104. 27W, LEFT ON NURSERY RD, RIGHT ON DOCS RD, LEFT INTO TROTTERS RIDGE

ON KENTUCKY DERBY LANE.

TI

2-21-12 AP-MIZ

2/21/12

R431 02

STRUCTURE: 000 000 60X60 4BDR 3BATH W GAR, PATIO, MONO SLAB

FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE : SFD 4.00 # BEDROOMS :

WATER SUPPLY : COUNTY SEPTIC - EXISTING? . . . : NEW TANK

PERMIT: CPSF 00 CP * SFD DESCRIPTION INSP REOUESTED TYP/SQ COMPLETED RESULT RESULTS/COMMENTS ------R*PLUMB UNDER SLAB VRU #: 002166429 P309 01 12/02/11 MR T/S: 12/02/2011 12:30 PM MREARIC -----12/02/11 AP R*BLDG MONO SLAB/TEMP SVC POLE VRU #: 002166494 B114 01 12/05/11 MR T/S: 12/05/2011 01:26 PM MREARIC -----12/05/11 AP ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002166502 12/05/11 TW A814 01 291 KENTUCKY DERBY LN LOT 104 LILLINGTON 27546 12/06/11 AP ./S: 12/06/2011 01:36 PM TWARD -----FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002176295 MR R427 01 12/30/11 T/S: 12/28/2011 11:39 AM DJOHNSON -----DA 12/30/11 T/S: 12/30/2011 11:07 AM MREARIC ----foam holes in siding at sinks, at plate nail garage lvl per specs from both sides strap ends of lvl over 2nd fl toilet for uplift plate must have bolts @ 6' and within 12" of ends FOUR TRADE ROUGH IN >2500 VRU #: 002177137 1/04/12 MR R427 02 T/S: 01/04/2012 12:14 PM MREARIC -----AP 1/04/12 R*INSULATION INSPECTION VRU #: 002178036 1/06/12 MR T129 01 T/S: 01/06/2012 01:01 PM MREARIC -----1/06/12 ledge needed on wall, insul. ok R*INSULATION INSPECTION VRU #: 002179562 1/10/12 MR I129 02 T/S: 01/10/2012 11:55 AM MREARIC -----AP 1/10/12 ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002182111 1/13/12 BM H824 01 T/S: 01/17/2012 10:40 AM SZIMMER -----1/13/12 AP T/S: 01/17/2012 10:40 AM SZIMMER -----FOUR TRADE FINAL >2500 VRU #: 002194256 2/20/12 MR R431 01 T/S: 02/20/2012 11:45 AM MREARIC -----2/20/12 DP

----- COMMENTS AND NOTES ----

remove the duct to the attic room

FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 002195295

wire the ac float switch