

County of Harnett
Building Inspections Department
Planning Services

SCANNED

DATE

Certificate of Compliance: ___ Occupancy: ✓

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Permit Numbers

Name: Hugh Suites Builders LLC

Building: _____

Address: 161 Lasker Rd

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

Date: 8-23-11

Building Official: James T. Hill

65592005-11

PREPARED 8/19/11, 13:59:03
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 17
DATE 8/22/11

ADDRESS . : 161 LASATER RD SUBDIV:
CONTRACTOR : HUGH SURLS BUILDERS LLC PHONE : (919) 422-7065
OWNER . . : ADAMS J C PHONE : (919) 552-5700
PARCEL . . : 01-0525- - -0058- - -
APPL NUMBER: 11-50026594 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 05/04/2011 03:28 PM JBROCK ----
210 SOUTH 10 MILES LEFT ON LASATER RD
LOT IS 3/4 ON RIGHT

STRUCTURE: 000 000 68X63 3BDR CRAWL W/ GARAGE & PATIO

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3000000.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/26/11 5/26/11	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002085415
B103 01	6/08/11 6/08/11	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002090846
B105 01	6/13/11 6/13/11	JH AP	R*OPEN FLOOR VRU #: 002093068
A814 01	6/16/11 6/21/11	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002093077 161 LASATER RD BUNNLEVEL 28323 ***NOTE # ON HOME AND BY DRIVEWAY T/S: 06/21/2011 09:01 AM TWARD -----
R427 01	7/06/11 7/06/11	JH DA	FOUR TRADE ROUGH IN >2500 VRU #: 002104136 1)Nail all 2 & 3 ply truss per truss drawings. 2)Replace all short nails in truss & joist hangers with @ least a 10D common nail. 3)Add king stud @ porch beam in garage near stairs. 4)Nail all holes in hurricane clips in laundry room. 5)Replace notched floor joist under toilet in master bathroom. 6)Missing nail guard on 2" pipe in master bathroom@ bottom plate.
I129 01	7/08/11 7/08/11	JH AP	R*INSULATION INSPECTION VRU #: 002105698
R427 02	7/08/11 7/08/11	JH AP	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002106102 T/S: 07/07/2011 02:20 PM DJOHNSON -----
H824 01	7/15/11 7/15/11	BM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002110716 T/S: 07/18/2011 11:56 AM SZIMMER ----- T/S: 07/18/2011 11:56 AM SZIMMER -----
R431 01	8/22/11 <i>8-22-11 AP JH</i>	TI <i>AP JH</i>	FOUR TRADE FINAL >2500 VRU #: 002126194

----- COMMENTS AND NOTES -----