

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: J. R. Horton

Address: 44 State Dr

Date: 11-8-12

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

88692005-11

Building Official: James F. Bell

PREPARED 11/07/12, 14:18:04
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 1
DATE 11/08/12

ADDRESS : 44 SLATE DR
CONTRACTOR : D.R. HORTON INC
OWNER : DR HORTON INC
PARCEL : 01-0535-14- -0100- -39-
APPL NUMBER: 11-50026928 CP NEW RESIDENTIAL (SFD)

SUBDIV: STONE CROSS SECT 2 PH2A&B
PHONE : (919) 460-2969
PHONE : (919) 460-2933

DIRECTIONS : T/S: 06/16/2011 10:16 AM VBROWN ----
SLATE DRIVE, STONE CROSS #109.
210S, RIGHT ON OVERHILLS RD GO 4MI,
RIGHT ON STONECROSS DRIVE, RIGHT SLATE
DRIVE.

STRUCTURE: 000 000 49X60.50 3BDR MONO W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B114 01	8/31/12 8/31/12	MR AP	R*BLDG MONO SLAB/TEMP SVC POLE VRU #: 002273381 This is a crawl space lot not a mono slab. Need footing inspection. Trying to reach Jennifer to see what's going on. T/S: 08/31/2012 02:14 PM MREARIC ----- this is a footer
A814 01	9/07/12 9/07/12	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002275758 44 SLATE DR LOT 109 SPRING LAKE 28390----- T/S: 09/07/2012 12:30 PM TWARD -----
B101 01	9/07/12 9/07/12	MR AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002275766 MIKE DID THE FOOTING ON THIS HOUSE PER BRYAN ON THE 8/31/12 AS A MONO INSPECTION BUT IT IS NOT FIXED IN HTE - THIS NEEDA TO BE DONE TO FIX INSPECTION FOR THIS HOUSE T/S: 09/07/2012 10:14 AM MREARIC ----- this was done on 8/31/12 by mr
B103 01	9/11/12 9/11/12	JH DA	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002276640 left side of garage wall on inside of foundation wall does not have 2" projection.
B103 02	9/12/12 9/12/12	FS CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 002277457 T/S: 09/12/2012 03:28 PM FSPIVEY ----- footing repair
B103 03	9/13/12 9/13/12	JH AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002278042 -----
B105 01	9/17/12 9/17/12	JH DA	R*OPEN FLOOR VRU #: 002279388 OPEN FLOOR NOT STARTED -----
B105 02	9/19/12 9/19/12	MR DA	R*OPEN FLOOR VRU #: 002280188 T/S: 09/19/2012 12:33 PM MREARIC ----- block at load point towards front of house and beef up all others
B105 03	9/20/12 9/20/12	MR AP	R*OPEN FLOOR VRU #: 002280774 T/S: 09/20/2012 01:00 PM MREARIC -----
R425 01	10/11/12 10/11/12	JH DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002289882 1)Missing window in living room.2)Nail all 2ply & 3ply truss per truss drawings.3)Missing chase in master bed closet & tape hole in duct in chase.4)Missing attic access

CONTINUED ONTO NEXT PAGE

PREPARED 11/07/12, 14:18:04
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 2
DATE 11/08/12

ADDRESS : 44 SLATE DR
CONTRACTOR : D.R. HORTON INC
OWNER : DR HORTON INC
PARCEL : 01-0535-14- -0100- -39-
APPL NUMBER: 11-50026928 CP NEW RESIDENTIAL (SFD)

SUBDIV: STONE CROSS SECT 2 PH2A&B
PHONE : (919) 460-2969
PHONE : (919) 460-2933

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
I129 01	10/15/12	JH	hole in hall upstairs.5)Missing hurricane clips on R03L & R04L truss.
	10/15/12	AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002290617
R425 02	10/15/12	JH	✓ FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002290633
	10/15/12	AP	
H824 01	10/22/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002295319
	10/22/12	AP	T/S: 10/24/2012 11:14 AM SSTEWARD ----- T/S: 10/24/2012 11:15 AM SSTEWARD -----
R429 01	11/07/12	JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 002299808
	11/07/12	DA	✓ Missing triple switch cover in dining room. ✓ Missing filter for return in living room. ✓ Missing insulation in attic. ✓ Need cross bracing on back deck per code. ✓ Seal hole in siding under deck.
R429 02	11/08/12	TL	FOUR TRADE FINAL VRU #: 002300663

11-8-12 APJH

----- COMMENTS AND NOTES -----

Harnett County

INSPECTOR: IVR

DATE 11/07/12

ADDRESS : 44 SLATE DR
CONTRACTOR : D.R. HORTON INC
OWNER : DR HORTON INC
PARCEL : 01-0535-14- -0100- -39-
APPL NUMBER: 11-50026928 CP NEW RESIDENTIAL (SFD)

SUBDIV: STONE CROSS SECT 2 PH2A&B
PHONE : (919) 460-2969
PHONE : (919) 460-2933

DIRECTIONS : T/S: 06/16/2011 10:16 AM VBROWN ----
SLATE DRIVE, STONE CROSS #109.
210S, RIGHT ON OVERHILLS RD GO 4MI,
RIGHT ON STONECROSS DRIVE, RIGHT SLATE
DRIVE.

STRUCTURE: 000 000 49X60.50 3BDR MONO W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW SEPTIC

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

Table with 4 columns: TYP/SQ, REQUESTED COMPLETED, INSP RESULT, DESCRIPTION RESULTS/COMMENTS. Contains multiple rows of inspection records with dates, times, and descriptions of work items.

Harnett County

INSPECTOR: IVR

DATE 11/07/12

ADDRESS : 44 SLATE DR
 CONTRACTOR : D.R. HORTON INC
 OWNER : DR HORTON INC
 PARCEL : 01-0535-14- -0100- -39-
 APPL NUMBER: 11-50026928 CP NEW RESIDENTIAL (SFD)

SUBDIV: STONE CROSS SECT 2 PH2A&B
 PHONE : (919) 460-2969
 PHONE : (919) 460-2933

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			hole in hall upstairs.5)Missing hurricane clips on R03L & R04L truss.
I129 01	10/15/12	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002290617
	10/15/12	AP	
R425 02	10/15/12	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002290633
	10/15/12	AP	
H824 01	10/22/12	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002295319
	10/22/12	AP	T/S: 10/24/2012 11:14 AM SSTEWARD
			T/S: 10/24/2012 11:15 AM SSTEWARD
R429 01	11/07/12	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002299808

11-7-12 DA-JH

----- COMMENTS AND NOTES -----