

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: D.R. Horton Inc

Address: 60 Slate Dr
Spring Lake, NC 28390

Date: 8/5/13

Building Official: _____

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 11 _____

MFG Home: _____

50026929

[Signature]

ADDRESS : 60 SLATE DR SUBDIV: STONE CROSS SECT 2 PH2A&B
 CONTRACTOR : D.R. HORTON INC PHONE : (919) 460-2969
 OWNER : D.R. HORTON INC PHONE : (919) 460-2933
 PARCEL : 01-0535-14- -0100- -40-
 APPL NUMBER: 11-50026929 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 06/16/2011 10:23 AM VBROWN ----
 SLATE DRIVE, STONE CROSS #110.
 210S, RIGHT ON OVERHILLS RD GO 4MI,
 RIGHT ON STONECROSS DR, RIGHT ON SLATE
 DRIVE.

STRUCTURE: 000 000 38X46 3BDR MONO W/ GARAGE
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	5/08/13 5/08/13	JH AP	R*PLUMB UNDER SLAB VRU #: 002378545
A814 01	5/10/13 5/14/13	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002380418 60 slate dr lot 110 spring lake 28390 T/S: 05/14/2013 11:04 AM TWARD
B114 01	5/10/13 5/10/13	MR DA	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 002380434 T/S: 05/10/2013 12:17 PM MREARIC pad needs compection test and the plans appear to show two thickened areas by foyer that are missing
B114 02	5/14/13 5/14/13	JH AP	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 002382141
R425 01	6/10/13 6/10/13	JH DA	FOUR TRADE ROUGH IN VRU #: 002393478 1)Have lsl instead of psl per plans under 2ply lvl in garage each end.2)Seal air barrier in garage @ garage door.3)Need strutual nail guard over electrical pannel in garage.4)100psi on water line test with water per code.5)Plans show lvl for back door header & it has lsls.6)Block top plate in rec room @ front.7)Repair tear in duct in bed 2 chase.8)Fire caulk hole left of kight switch in master bedroom.
I129 01	6/13/13 6/13/13	JH AP	R*INSULATION INSPECTION VRU #: 002396000
R425 02	6/13/13 6/13/13	JH AP	FOUR TRADE ROUGH IN VRU #: 002395994
H824 01	7/10/13 7/10/13	BM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002408524 PER BRYAN MCSWAIN OPERATIONS PERMIT FOR SEPTIC ON HOLD. NEEDS PUMP AND ALARM CHECKED BEFORE IT CAN BE ISSUED. CALL HIM 893-7547 TO SCHEDULE THIS INSPECTION WHEN READY. T/S: 07/10/2013 03:50 PM SSTEWARD
H824 02	7/24/13 7/24/13	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002415917 T/S: 07/25/2013 10:26 AM SSTEWARD T/S: 07/25/2013 10:26 AM SSTEWARD
R429 01	8/05/13 <u>8/5/13</u>	TI <u>AP W</u>	FOUR TRADE FINAL VRU #: 002420289

COMMENTS AND NOTES