

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: DR. Horton INC

Address: 73 Slate Dr

Date: 1-10-14

Building Official: James T Hall

**Permit Numbers**

Building: \_\_\_\_\_  
Electrical: \_\_\_\_\_  
Insulation: \_\_\_\_\_  
Plumbing: \_\_\_\_\_  
Mechanical: \_\_\_\_\_  
MFG Home: \_\_\_\_\_

*1539200511*

ADDRESS : 73 SLATE DR SUBDIV:  
 CONTRACTOR : D.R. HORTON INC PHONE : (919) 460-2969  
 OWNER : DR HORTON INC PHONE : (919) 460-2933  
 PARCEL : 01-0535-14- -0100- -43-  
 APPL NUMBER: 11-50026932 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 06/16/2011 10:57 AM VBROWN ----  
 SLATE DRIVE, STONE CROSS #113.  
 210S, RIGHT ON OVERHILLS RD GO 4MI,  
 RIGHT ON STONE CROSS DR, LEFT ON  
 STONEHURST DRIVE

STRUCTURE: 000 000 43.6X38 3BDR CRAWL W/ GARAGE  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/19/13	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002412188
	7/19/13	AP	T/S: July 19, 2013 12:30 PM BSUTTON
B103 01	8/01/13	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 002419208
	8/01/13	AP	T/S: 08/01/2013 02:06 PM MREARIC
B105 01	8/15/13	JH	R*OPEN FLOOR VRU #: 002426161
	8/15/13	AP	
A814 01	9/27/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002445385
	10/07/13	AP	73 slate dr lot 113 spring lake 28390 T/S: 10/07/2013 10:02 AM TWARD
R425 01	9/27/13	DT	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002445393
	9/27/13	DA	T/S: 09/27/2013 12:20 PM DETAYLOR Clear up plumbing leaks Re walk house, and finish all fire caulk/stopping Okay to side, do not insulate
R425 02	10/02/13	DT	FOUR TRADE ROUGH IN VRU #: 002447274
	10/03/13	AP	T/S: 10/03/2013 07:51 AM DETAYLOR
I129 01	10/08/13	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002449759
	10/08/13	AP	
H824 01	10/18/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002455657
	10/18/13	AP	T/S: 10/21/2013 01:15 PM SSTEWARD T/S: 10/21/2013 01:15 PM SSTEWARD
R429 01	12/19/13	JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 002478279
	12/19/13	CA	PER BRIAN
R429 02	1/07/14	JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 002481844
	1/07/14	DA	1) Missing light in back left corner of soffiton house. 2) Missing cross bracing on back deck. 3) Cleanout to grade @ AC units.
R429 03	1/10/14	TI	FOUR TRADE FINAL VRU #: 002483170

1-10-14 *APJH*

COMMENTS AND NOTES