

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: ___ Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Caviness Land Development

Address: 36 Parkview Ln
Lillington, NC 27546

Date: 10/27/11

Building Official: *[Signature]*

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 11-50026967

MFG Home: _____

PREPARED 10/26/11, 13:58:09
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 6
DATE 10/27/11

ADDRESS . . : 36 PARKVIEW LN
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER . . . : WATERS KATHRYN G
PARCEL . . . : 01-0536- - -0028- -94-
APPL NUMBER: 11-50026967 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 06/21/2011 07:51 AM JBROCK ----
FROM 87 S MAKE A LEFT ONTO NURSERY RD
AND THEN CONT TO THE LEFT ON NURSERY RD
MAKE A RIGHT ONTO PARKVIEW LN LOT IS
THE SECOND LOT ON THE LEFT LOT 5

STRUCTURE: 000 000 56.5X40 3BDR MONO W/ GARAGE PORCH

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3000000.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	8/03/11	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002118164
	8/03/11	AP	36 parkview ln lot 5 lillington 27546----- T/S: 08/03/2011 10:49 AM TWARD -----
P309 01	8/03/11	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002118172
	8/03/11	AP	T/S: 08/03/2011 11:57 AM MREARIC -----
B114 01	8/08/11	MR	R*BLDG MONO SLAB/TEMP SVC POLE VRU #: 002119626
	8/08/11	DA	T/S: 08/08/2011 11:56 AM MREARIC ----- not ready, no toilet
B114 02	8/09/11	MR	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 002120269
	8/09/11	AP	T/S: 08/08/2011 12:00 PM VBROWN ----- T/S: 08/09/2011 12:11 PM MREARIC -----
R425 01	8/30/11	TI	FOUR TRADE ROUGH IN VRU #: 002129958
I129 01	9/02/11	DT	R*INSULATION INSPECTION VRU #: 002131687
	9/02/11	AP	
H824 01	9/17/11	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002139392
	9/17/11	AP	T/S: 09/21/2011 09:40 AM SZIMMER ----- T/S: 09/21/2011 09:41 AM SZIMMER -----
R429 01	10/21/11	MR	FOUR TRADE FINAL VRU #: 002151192
	10/21/11	DP	T/S: 10/21/2011 12:33 PM MREARIC ----- no intersystem bond wire disposal need ladder for attic inspection patch hole in garage ceiling water heater not wired where is pressure reducing valve?
R429 02	10/27/11	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002154060
	10/27/11	AP DI	T/S: 10/26/2011 10:54 AM VBROWN -----

----- COMMENTS AND NOTES -----